New Mexico Energy, Minerals and Natural Resources Department

Susana Martinez

Governor

Harrison H. Schmitt Cabinet Secretary-Designate Daniel Sanchez Acting Division Director Oil Conservation Division



Response Required - Deadline Enclosed

Underground Injection Control Program
"Protecting Our Underground Sources of Drinking Water"

12-Jan-11

LEGACY RESERVES OPERATING, LP P. O. BOX 10848 MIDLAND TX 79702 LOVNO. 02-09-191

LETTER OF VIOLATION and SHUT-IN DIRECTIVE Failed Mechanical Integrity Test

Dear Operator:

The following test(s) were performed on the listed dates on the following well(s) shown below in the test detail section.

The test(s) indicates that the well or wells failed to meet mechanical integrity standards of the New Mexico Oil Conservation Division. To comply with guidelines established by the U.S. Environmental Protection Agency, the well(s) must be shut-in immediately until it is successfully repaired. The test detail section which follows indicates preliminary findings and/or probable causes of the failure. This determination is based on a test of your well or facility by an inspector employed by the Oil Conservation Division. Additional testing during the repair operation may be necessary to properly identify the nature of the well failure.

Please notify the proper district office of the Division at least 48 hours prior to the date and time that the well(s) will be retested so the test may be witnessed by a field representative.

MECHANICAL INTEGRITY TEST DETAIL SECTION

SOUTH RED LAKE II UNIT No.007

Active Injection - (All Types)

30-015-00620-00-00 H-35-17S-27E

Test Date:

1/10/2011

Permitted Injection PSI:

Actual PSI:

Test Reason:

Annual IMIT

Test Result:

Repair Due:

4/15/2011

Test Type: B

Bradenhead Test

FAIL TYPE: Other Internal Failure

FAIL CAUSE:

Comments on MIT: Operator reports a hole in the tubing. Not tested. Well has been shut-in.

MIDNIGHT MATADOR No.010

Expired TA Injection - (All Types)

30-015-00621-00-00 A-35-17S-27E

Test Date:

1/10/2011

Permitted Injection PSI:

Actual PSI:

4/15/2011

Test Reason: P
Test Type: S

Post Workover Test

Test Result:

Repair Due:

AUSE.

Comments on MIT:

Std. Annulus Pres. Test

FAIL TYPE: Other Internal Failure

FAIL CAUSE:

Unable to test. Started to pressure up and fluid came out of wellhead. Salt from around cap might indicate

tubing leak. Well must be shut-in and repaired.

Wrong name on Well sign - Indicates S. Red Lake II Unit 003, but name change to Midnight Matador submitted to BLM on 1/25/08. Correct well sign or submit name change.

Oil Conservation Division
1301 W. Grand Avenue • Artesia, New Mexico 88210
Phone (575)748-1283 • Fax (575) 748-9720 • www.emnrd.state.nm.us/OCD



January 12, 2011 Page 2

In the event that a satisfactory response is not received to this letter of direction by the "Repair Due:" date shown above, or if the well(s) are not immediately shut-in, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well. Such a hearing may result in imposition of CIVIL PENALTIES for your violation of OCD rules.

Sincerely,

RUMAND INGE Artesia OCD District Office