Form 3160-5 (August 1999)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on reverse side RECEIVED

FORM APPROVED OMB NO. 1004-0135 Expires: November 30, 2000

Expires: November 30, 2000 5. Lease Serial No.

NMLC029389B	
6. If Indian, Allottee or Tribe Name	

7. If Unit or CA/Agreement, Name and/or No.

1. Type of weil		AUG 1 2 2004		WILMAR FEDERAL 2		
Oil Well Gas Well Other						
2. Name of Operator Contact: PECOS PRODUCTION COMPANY		DORA LARA OCCUPANTESIA: E-Mail: dorab@pecosproduction.com		9. API Well No. 30-015-25607-00-S1		
3a. Address 400 ILLINOIS AVE STE 1070 MIDLAND, TX 79701		3b. Phone No. (include area code) Ph: 432.620.8480 Fx: 432.683.1628		10. Field and Pool, or Exploratory N SHUGART-BONE SPRING		
4. Location of Well (Footage, Sec., 7	., R., M., or Survey Description)	п. с	ounty or Parish, and	State	
Sec 4 T18S R31E NESW 198	80FSL 1980FWL		EC	DDY COUNTY, N	M	
12. CHECK APPI	ROPRIATE BOX(ES) TO	INDICATE NATURE OF	NOTICE, REPORT	Γ, OR OTHER D	OATA	
TYPE OF SUBMISSION		ТҮРЕ О	F ACTION			
Notice of Intent	□ Acidize	Deepen	Production (Sta	art/Resume) [Water Shut-Off	
_	Alter Casing	Fracture Treat	Reclamation		Well Integrity	
☐ Subsequent Report	Casing Repair	☐ New Construction	Recomplete	-	Other Vorkover Operatic	
Final Abandonment Notice	☐ Change Plans	Plug and Abandon	☐ Temporarily Al	bandon V	Vorkover Operatic	
	Convert to Injection	Plug Back	☐ Water Disposal	I		
1. MIRU. Unseat pmp & POOI tbg. RIs TAC, Tag PBTD & TC 2. Perf 2nd BS Carbonate @ 7 3. TIH w/5-1/2" RBP & treating 2500 psi. Ld hole. PU to 7550 4. Acidize perfs F/7710-50' w/3	0OH. 7710-17' (8), 7724-28' (5), g pkr on 2-7/8" tbg. Hydro ' & set pkr. Break perfs do	7740-50' (11), total 2448" test to 7000 psi. Set RBP @ wn w/KCl water. Swab back	holes. 7850' & test to			
14. I hereby certify that the foregoing is	#Electronic Submission For PECOS PRO	34381 verified by the BLM Wel DUCTION COMPANY, sent to essing by LINDA ASKWIG on	the Carlsbad			
Name (Printed/Typed) DORA LAI	RA	Title SUBMIT	TTING CONTACT			
Signature (Electronic S		Date 08/10/2				
	THIS SPACE FO	R FEDERAL OR STATE	OFFICE USE			
Approved By ALEXIS C SWOBOL	T170		UM ENGINEER		Date 08/11/20	
Conditions of approval, if any, are attache tertify that the applicant holds legal or equivalent would entitle the applicant to condu-	uitable title to those rights in the act operations thereon.	subject lease Office Carlsbac	-			
Fitle 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent s	U.S.C. Section 1212, make it a statements or representations as	crime for any person knowingly and to any matter within its jurisdiction	l willfully to make to ar	y department or age	ncy of the United	
** BLM REV	ISED ** BLM REVISED	** BLM REVISED ** BLM	REVISED ** BL	.M REVISED **		

Additional data for EC transaction #34381 that would not fit on the form

- 32. Additional remarks, continued
- 5. Swab back load & test.
- 6. Rls pkr & RBP. TOOH. Perf BS Sand 7210-24' (8), 7238-50' (7) & 7270-90' (11) w/1 shot/2 ft (26-.43" holes).
- 7. TIH w/RBP & pkr on 2-7/8" tbg. Set RBP @ 7400'. Test to 2500 psi. PU to 7100' & set pkr. Break perfs down w/KCl water. Swab tbg dry.
- 8. Ballout perfs w/2500 gal 7-1/2% HCl acid using 52 BS for divert. Swab tbg down. Rls pkr & TOOH.
- 9. Frac BS Sand perfs w/approx 46,000 gal gel & 75,000# 20-40 econon-prop & 25,000# Super DC resin coat.
- 10. Flow back load & test.
- 11. TIH w/production tbg assy to 7000'. Run rods & pmp & PWOP.
- 12. After test on Upper BS Sand, Pull RBP. Place all zones on production.