Office State of New Mexico	Form C-103
District I 23 19 Suprey, Minerals and Natural Resources	Revised March 25, 1999
Submit 3 Copies To Appropriate District Office District I 1625 N. French Dr., Hobbs, NM 88240 (2) 18 19 20 27 22 3	WELL API NO.
811 South First, Artesia, NM 88210 OIL CONSERVATION DIVISION	30-015-23350 5. Indicate Type of Lease
1000 Pin Province And American Andreas Andreas Division Inches Division Div	
District IV 1220 S. St. Francis Dr., Santa Fe, EM RECENTED Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe. EM RECEIVED RATESIA ST. SANTA FE. EM RECEIVED ARTESIA ST. SANTA FE. SAN	B11594-6
SUNDRY ADTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name:
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL TO TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	
PROPOSALS.)	
1. Type of Well:	7.1/ 6
Oil Well Gas Well Other Plug & Abandon  2. Name of Operator	State B 14 Com  8. Well No.
H.E.C. Petroleum, Inc.	0. Well No. 1
3. Address of Operator	9. Pool name or Wildcat
500 W. Illinois - Midland, TX 79701	Loco Hills Wolfcamp
4. Well Location	
Unit Letter P: 660 feet from the South line and	990 feet from the East line
Section 14 Township 18S Range 28E	NMPM Eddy County
10. Elevation (Show whether DR, RKB, RT, GR, 3539.5' GR	etc.)
11. Check Appropriate Box to Indicate Nature of Notice	Report or Other Data
	BSEQUENT REPORT OF:
PERFORM REMEDIAL WORK  PLUG AND ABANDON  REMEDIAL WO	ORK ALTERING CASING
TEMPORARILY ABANDON CHANGE PLANS COMMENCE D	RILLING OPNS. PLUG AND
PULL OR ALTER CASING	ABANDONMENT AND
OTHER: OTHER:	
	give pertinent dates, including estimated date
12. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Atta	
12. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Atta or recompilation.	ch wellbore diagram of proposed completion
<ol> <li>Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Atta or recompilation.</li> <li>11-1-2002 - Moved in and rigged up pulling unit and plugging.</li> </ol>	ng equipment.
12. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Atta or recompilation.	ng equipment.  pled up BOP. Rigged up tubing
12. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Atta or recompilation.  11-1-2002 - Moved in and rigged up pulling unit and plugging 11-2-4-02 - Blew well down. Nippled down wellhead and nipple equipment. Tried to release packer. Shut well in for night 11-5-2002 - Released packer. Tooh with tubing and packer.	nch wellbore diagram of proposed completion  ng equipment.  pled up BOP. Rigged up tubing  tht.  Shut well in for night.
<ul> <li>Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Atta or recompilation.</li> <li>11-1-2002 - Moved in and rigged up pulling unit and plugged 11-2-4-02 - Blew well down. Nippled down wellhead and nip equipment. Tried to release packer. Shut well in for night 11-5-2002 - Released packer. TOOH with tubing and packer. 11-6-2002 - RIH with tubing and set CIBP at 9000'. Pulled</li> </ul>	nch wellbore diagram of proposed completion  Ing equipment.  In pled up BOP. Rigged up tubing this continue in for night.  In place of the continue in the con
12. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Atta or recompilation.  11-1-2002 - Moved in and rigged up pulling unit and plugged 11-2-4-02 - Blew well down. Nippled down wellhead and nip equipment. Tried to release packer. Shut well in for nig 11-5-2002 - Released packer. TOOH with tubing and packer. 11-6-2002 - RIH with tubing and set CIBP at 9000'. Pulled plugging mud. Spotted 5 sacks Class C Neat cement on top	nch wellbore diagram of proposed completion  Ing equipment.  In pled up BOP. Rigged up tubing this continue in for night.  In place of the continue in the con
12. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Atta or recompilation.  11-1-2002 - Moved in and rigged up pulling unit and plugged 11-2-4-02 - Blew well down. Nippled down wellhead and nipple equipment. Tried to release packer. Shut well in for night 11-5-2002 - Released packer. TOOH with tubing and packer. 11-6-2002 - RIH with tubing and set CIBP at 9000'. Pulled plugging mud. Spotted 5 sacks Class C Neat cement on top Shut well in for night.  11-7-2002 - RIH to 4450'. Spotted 25 sacks Class C Neat cement.	ng equipment.  In pled up BOP. Rigged up tubing tht.  Shut well in for night.  I up hole. Circulated hole with of CIBP (9000-8949'). POOH.
12. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Atta or recompilation.  11-1-2002 - Moved in and rigged up pulling unit and plugging 11-2-4-02 - Blew well down. Nippled down wellhead and nipple equipment. Tried to release packer. Shut well in for night 11-5-2002 - Released packer. TOOH with tubing and packer. 11-6-2002 - RIH with tubing and set CIBP at 9000'. Pulled plugging mud. Spotted 5 sacks Class C Neat cement on top Shut well in for night.  11-7-2002 - RIH to 4450'. Spotted 25 sacks Class C Neat cement on top with tubing. Rigged down tubing equipment and nippled down	ng equipment.  In pled up BOP. Rigged up tubing tht.  Shut well in for night.  I up hole. Circulated hole with of CIBP (9000-8949'). POOH.
12. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Atta or recompilation.  11-1-2002 - Moved in and rigged up pulling unit and plugged 11-2-4-02 - Blew well down. Nippled down wellhead and nipple equipment. Tried to release packer. Shut well in for night 11-5-2002 - Released packer. TOOH with tubing and packer. 11-6-2002 - RIH with tubing and set CIBP at 9000'. Pulled plugging mud. Spotted 5 sacks Class C Neat cement on top Shut well in for night.  11-7-2002 - RIH to 4450'. Spotted 25 sacks Class C Neat cement on top Shut well in for night.	ich wellbore diagram of proposed completion ing equipment. ippled up BOP. Rigged up tubing iht. Shut well in for night. I up hole. Circulated hole with of CIBP (9000-8949'). POOH. ement from 4450-4197'. POOH in BOP. Nippled down wellhead.
12. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Atta or recompilation.  11-1-2002 - Moved in and rigged up pulling unit and plugging 11-2-4-02 - Blew well down. Nippled down wellhead and nipple equipment. Tried to release packer. Shut well in for night 11-5-2002 - Released packer. TOOH with tubing and packer. 11-6-2002 - RIH with tubing and set CIBP at 9000'. Pulled plugging mud. Spotted 5 sacks Class C Neat cement on top Shut well in for night.  11-7-2002 - RIH to 4450'. Spotted 25 sacks Class C Neat owith tubing. Rigged down tubing equipment and nippled down Shut well in for night.  11-8-2002 - Rigged up wireline. RIH and stacked out at 24	ich wellbore diagram of proposed completion ing equipment. pled up BOP. Rigged up tubing tht. Shut well in for night. up hole. Circulated hole with of CIBP (9000-8949'). POOH. ement from 4450-4197'. POOH on BOP. Nippled down wellhead.
12. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Atta or recompilation.  11-1-2002 - Moved in and rigged up pulling unit and plugging 11-2-4-02 - Blew well down. Nippled down wellhead and nipple equipment. Tried to release packer. Shut well in for night 11-5-2002 - Released packer. TOOH with tubing and packer. 11-6-2002 - RIH with tubing and set CIBP at 9000'. Pulled plugging mud. Spotted 5 sacks Class C Neat cement on top Shut well in for night.  11-7-2002 - RIH to 4450'. Spotted 25 sacks Class C Neat with tubing. Rigged down tubing equipment and nippled down the shut well in for night.  11-8-2002 - Rigged up wireline. RIH and stacked out at 24 line. Nippled up wellhead and BOP. Rigged up tubing equipment and fell thru at 2480'. RIH to 4450' - did not tage	ng equipment.  Inglied up BOP. Rigged up tubing tht.  Shut well in for night.  I up hole. Circulated hole with of CIBP (9000-8949'). POOH.  Sement from 4450-4197'. POOH on BOP. Nippled down wellhead.  80'. POOH and rigged down wirepment. RIH with tubing open cement. Spotted 25 sacks Class
12. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Atta or recompilation.  11-1-2002 - Moved in and rigged up pulling unit and plugged 11-2-4-02 - Blew well down. Nippled down wellhead and nipple equipment. Tried to release packer. Shut well in for night 11-5-2002 - Released packer. TOOH with tubing and packer. 11-6-2002 - RIH with tubing and set CIBP at 9000'. Pulled plugging mud. Spotted 5 sacks Class C Neat cement on top Shut well in for night.  11-7-2002 - RIH to 4450'. Spotted 25 sacks Class C Neat owith tubing. Rigged down tubing equipment and nippled down the Shut well in for night.  11-8-2002 - Rigged up wireline. RIH and stacked out at 24 line. Nippled up wellhead and BOP. Rigged up tubing equipment and fell thru at 2480'. RIH to 4450' - did not tag C Neat cement from 4450-4197'. POOH with tubing. WOC.	ich wellbore diagram of proposed completion ing equipment. pled up BOP. Rigged up tubing tht. Shut well in for night. up hole. Circulated hole with of CIBP (9000-8949'). POOH. ement from 4450-4197'. POOH on BOP. Nippled down wellhead. BO'. POOH and rigged down wire- pment. RIH with tubing open cement. Spotted 25 sacks Class thut well in for night.
12. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Atta or recompilation.  11-1-2002 - Moved in and rigged up pulling unit and plugged 11-2-4-02 - Blew well down. Nippled down wellhead and nip equipment. Tried to release packer. Shut well in for night 11-5-2002 - Released packer. TOOH with tubing and packer. 11-6-2002 - RIH with tubing and set CIBP at 9000'. Pulled plugging mud. Spotted 5 sacks Class C Neat cement on top Shut well in for night.  11-7-2002 - RIH to 4450'. Spotted 25 sacks Class C Neat with tubing. Rigged down tubing equipment and nippled down Shut well in for night.  11-8-2002 - Rigged up wireline. RIH and stacked out at 24 line. Nippled up wellhead and BOP. Rigged up tubing equipment and fell thru at 2480'. RIH to 4450' - did not tag C Neat cement from 4450-4197'. POOH with tubing. WOC. Secont in the start of the s	ich wellbore diagram of proposed completion ing equipment. pled up BOP. Rigged up tubing tht. Shut well in for night. up hole. Circulated hole with of CIBP (9000-8949'). POOH. ement from 4450-4197'. POOH on BOP. Nippled down wellhead. 80'. POOH and rigged down wire- pment. RIH with tubing open cement. Spotted 25 sacks Class thut well in for night.
12. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Atta or recompilation.  11-1-2002 - Moved in and rigged up pulling unit and plugged 11-2-4-02 - Blew well down. Nippled down wellhead and nipple equipment. Tried to release packer. Shut well in for night 11-5-2002 - Released packer. TOOH with tubing and packer. 11-6-2002 - RIH with tubing and set CIBP at 9000'. Pulled plugging mud. Spotted 5 sacks Class C Neat cement on top Shut well in for night.  11-7-2002 - RIH to 4450'. Spotted 25 sacks Class C Neat owith tubing. Rigged down tubing equipment and nippled down the Shut well in for night.  11-8-2002 - Rigged up wireline. RIH and stacked out at 24 line. Nippled up wellhead and BOP. Rigged up tubing equipment and fell thru at 2480'. RIH to 4450' - did not tag C Neat cement from 4450-4197'. POOH with tubing. WOC.	ich wellbore diagram of proposed completion ing equipment. pled up BOP. Rigged up tubing tht. Shut well in for night. up hole. Circulated hole with of CIBP (9000-8949'). POOH. ement from 4450-4197'. POOH on BOP. Nippled down wellhead. 80'. POOH and rigged down wire- pment. RIH with tubing open cement. Spotted 25 sacks Class thut well in for night.
12. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Atta or recompilation.  11-1-2002 - Moved in and rigged up pulling unit and plugging 11-2-4-02 - Blew well down. Nippled down wellhead and nipequipment. Tried to release packer. Shut well in for night 11-5-2002 - Released packer. TOOH with tubing and packer. 11-6-2002 - RIH with tubing and set CIBP at 9000'. Pulled plugging mud. Spotted 5 sacks Class C Neat cement on top Shut well in for night.  11-7-2002 - RIH to 4450'. Spotted 25 sacks Class C Neat with tubing. Rigged down tubing equipment and nippled down Shut well in for night.  11-8-2002 - Rigged up wireline. RIH and stacked out at 24 line. Nippled up wellhead and BOP. Rigged up tubing equipment and fell thru at 2480'. RIH to 4450' - did not tag C Neat cement from 4450-4197'. POOH with tubing. WOC. Secontinued on Next PAGE:	ich wellbore diagram of proposed completion ing equipment. pled up BOP. Rigged up tubing tht. Shut well in for night. up hole. Circulated hole with of CIBP (9000-8949'). POOH. ement from 4450-4197'. POOH on BOP. Nippled down wellhead. 80'. POOH and rigged down wire- pment. RIH with tubing open cement. Spotted 25 sacks Class thut well in for night.
12. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Atta or recompilation.  11-1-2002 - Moved in and rigged up pulling unit and plugged 11-2-4-02 - Blew well down. Nippled down wellhead and nipple equipment. Tried to release packer. Shut well in for night 11-5-2002 - Released packer. TOOH with tubing and packer. 11-6-2002 - RIH with tubing and set CIBP at 9000'. Pulled plugging mud. Spotted 5 sacks Class C Neat cement on top Shut well in for night.  11-7-2002 - RIH to 4450'. Spotted 25 sacks Class C Neat with tubing. Rigged down tubing equipment and nippled down Shut well in for night.  11-8-2002 - Rigged up wireline. RIH and stacked out at 24 line. Nippled up wellhead and BOP. Rigged up tubing equipment and fell thru at 2480'. RIH to 4450' - did not tag C Neat cement from 4450-4197'. POOH with tubing. WOC. Start Continued on Next PAGE:	Ing equipment.  Ing equipment.  In pled up BOP. Rigged up tubing tht.  Shut well in for night.  I up hole. Circulated hole with of CIBP (9000-8949'). POOH.  Seement from 4450-4197'. POOH on BOP. Nippled down wellhead.  180'. POOH and rigged down wire-pment. RIH with tubing open cement. Spotted 25 sacks Class thut well in for night.
12. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Atta or recompilation.  11-1-2002 - Moved in and rigged up pulling unit and plugging 11-2-4-02 - Blew well down. Nippled down wellhead and nipequipment. Tried to release packer. Shut well in for night 11-5-2002 - Released packer. TOOH with tubing and packer. 11-6-2002 - RIH with tubing and set CIBP at 9000'. Pulled plugging mud. Spotted 5 sacks Class C Neat cement on top Shut well in for night.  11-7-2002 - RIH to 4450'. Spotted 25 sacks Class C Neat with tubing. Rigged down tubing equipment and nippled down Shut well in for night.  11-8-2002 - Rigged up wireline. RIH and stacked out at 24 line. Nippled up wellhead and BOP. Rigged up tubing equipment and fell thru at 2480'. RIH to 4450' - did not tage C Neat cement from 4450-4197'. POOH with tubing. WOC. See CONTINUED ON NEXT PAGE:  1 hereby certify that the information above is true and complete to the best of my knowleds.	In the wellbore diagram of proposed completion on the equipment.  In the pled up BOP. Rigged up tubing that.  Shut well in for night.  I up hole. Circulated hole with of CIBP (9000-8949'). POOH.  The ement from 4450-4197'. POOH on BOP. Nippled down wellhead.  BO'. POOH and rigged down wire-pment. RIH with tubing open cement. Spotted 25 sacks Class that well in for night.  Telephone No. 505-748-2159
12. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Atta or recompilation.  11-1-2002 - Moved in and rigged up pulling unit and plugged 11-2-4-02 - Blew well down. Nippled down wellhead and nip equipment. Tried to release packer. Shut well in for nig 11-5-2002 - Released packer. T00H with tubing and packer. 11-6-2002 - RIH with tubing and set CIBP at 9000'. Pulled plugging mud. Spotted 5 sacks Class C Neat cement on top Shut well in for night.  11-7-2002 - RIH to 4450'. Spotted 25 sacks Class C Neat with tubing. Rigged down tubing equipment and nippled down Shut well in for night.  11-8-2002 - Rigged up wireline. RIH and stacked out at 24 line. Nippled up wellhead and BOP. Rigged up tubing equipment and fell thru at 2480'. RIH to 4450' - did not tag C Neat cement from 4450-4197'. POOH with tubing. WOC. Secontinued on Next PAGE:  Thereby certify that the information above is true and complete to the best of my knowled.  SIGNATURE TITLE Agent for BCM.	In the wellbore diagram of proposed completion on any equipment.  In pled up BOP. Rigged up tubing tht.  Shut well in for night.  I up hole. Circulated hole with of CIBP (9000-8949'). POOH.  Sement from 4450-4197'. POOH on BOP. Nippled down wellhead.  BO'. POOH and rigged down wire-pment. RIH with tubing open cement. Spotted 25 sacks Class thut well in for night.  I & Associates DATE Nov. 14, 2002

H.E.C. CORPORATION
State B 14 Com #1
Section 14-T18S-R28E
Eddy County, New Mexico

## SUNDRY NOTICE CONTINUED:

11-9-11-2002 - RIH with tubing and tagged cement at 4156. POOH with tubing. Rigged down tubing equipment. Nippled down BOP and wellhead. Rigged up wireline. RIH and cut 5-1/2" casing at 3122'. POOH and rigged down wireline. Rigged up casing equipment. Worked casing free. POOH with 63 joints of 5-1/2" casing. Shut well in for night. 11-12-2002 - Finished laying down 5-1/2" casing (total of 81 joints). Rigged down casing equipment. Nippled up wellhead and BOP. Rigged up tubing equipment. RIH with 2-3/8" tubing open ended to 3177'. Spotted 50 sacks Class C Neat cement from 3177-2965'. POOH. WOC 4 hours. RIH with tubing and tagged cement at 2958'. POOH. Shut well in for night. 11-13-2002 - RIH to 947'. Spotted 45 sacks Class C Neat cement from 947-737'. POOH. WOC 4 hours. RIH with tubing and tagged cement at 779'. Pulled up hole to 519'. Spotted 45 sacks Class C Neat cement from 519-319'. POOH. WOC. Shut well in for night. 11-14-2002 - RIH with tubing and tagged cement at 3541. POOH and rigged down tubing equipment. Nippled down BOP. RIH with tubing to 60'. Circulated 15 sacks Class C Neat cement. POOH. Nippled down wellhead. Rigged down pulling unit and plugging equipment. Installed regulation abandonment marker. PLUGGED AND ABANDONED - FINAL REPORT. Plugging completed 11-13-2002.

Rusty Klein

Agent for BCM & Associates

November 14, 2002