

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

30-015-32203

Release Notification and Corrective Action *Todd 22 B Fed. #2*

NLRN0428054360

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: Devon Energy Production Co. LP	Contact: Jennifer Van Curen
Address: PO Box 250; Artesia, NM 88211	Telephone No.: 505-748-0160
Facility Name: Todd 22 Battery	Facility Type: Battery

Surface Owner <i>BLM</i>	Mineral Owner	Lease No. NMNM0405444A
--------------------------	---------------	------------------------

LOCATION OF RELEASE

Unit Letter <i>B</i>	Section 22	Township 23S	Range 31E	Feet from the 510	North/South Line North	Feet from the 1980	East/West Line East	County Eddy
-------------------------	---------------	-----------------	--------------	----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release: Water	Volume of Release: 432	Volume Recovered: 428
Source of Release: Damaged PW tank	Date and Hour of Occurrence 9-20-04; 5:00 am	Date and Hour of Discovery 9-20-04; 5:00 am
Was Immediate Notice Given? ☒ Yes ☐ No ☐ Not Required	If YES, To Whom? Mike Bratcher	
By Whom?	Date and Hour: 9-20-04; 5:00 am	
Was a Watercourse Reached? ☐ Yes ☒ No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

RECEIVED

SEP 24 7AM

OGG-ARTESIA

Describe Cause of Problem and Remedial Action Taken.*

Upon Arrival, found 500 bbl fiberglass tank had ruptured because gas vented from production vessels with high gas pressures. 20 bbl water and 2 bbl oil was not recovered out of 446 bbl Water and 4 bbl oil inside berm. Property Damage cost is approx. \$9000.00. Preventative Action: Plumbed all gas vent lines into open top 50 bbl fiberglass tank to keep gas off the stock and produced water tanks.

Describe Area Affected and Cleanup Action Taken.*

Area Affected: 20' X 20' within the firewall. Corrective Action: Visited with Paul Evans with Carlsbad office BLM, and he wants us to till and air soil. Then use the contaminated soil to build firewall up. Driveway chat will then be hauled in to replace the scraped soil.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Jennifer Van Curen</i>	OIL CONSERVATION DIVISION	
Printed Name: Jennifer Van Curen	Approved by District Supervisor:	
Title: Production Field Tech	Approval Date:	Expiration Date:
E-mail Address: Jennifer.vancuren@dmn.com	Conditions of Approval:	Attached ☐
Date: 9/22/2004	Phone: 748-0160	

* Attach Additional Sheets If Necessary