Submit 3 Copies To Appropriate District	State of New Mo	exico		Form C	
Office District I	Energy, Minerals and Nati	ural Resources		March 4,	2004
1625 N. French Dr., Hobbs, NM 88240		7	VELL API NO.		
District II OIL CONCED VATION DIVISION			0-015-33556		
1301 W. Grand Ave., Altesia, NW 00210		1.3	. Indicate Type of	Lease	
District III	1220 South St. Fra	ncis Dr.	STATE [FEE 🛛	
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NM 8	7505	. State Oil & Gas I	.ease No.	
1220 S. St. Francis Dr., Santa Fe, NM					-
87505 SUNDRY NOT	ICES AND REPORTS ON WELL	9	. Lease Name or U	nit Agreement Na	me
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			Big Chief Fee #6	111(1161001110111111111	
	ICATION FOR PERMIT" (FORM C-101) F		ong chici i co no		
PROPOSALS.)		9	. Well Number		
1. Type of Well:	• • •	l S			1
Oil Well Gas Well	Other	/·		RECE	IVED
2. Name of Operator	3	1	OGRID Number	NOV O	5 2004
Nadel and Gussman Permian, LLC	<u> </u>		55615		
3. Address of Operator	1		0. Pool name or W	IIdcat OCD-A!	rtegia
601 N. Marienfeld Suite 508 Midl	and, Texas 79701		Oubling Ranch; Mor	rrow	
4. Well Location			LIEST		
Unit Letter F 1990'	feet from the North line a	nd 1980' feet f	•	line	j
Om Letter F 1980 _	iest from the North line a	III 1760ICCL	TORI (IIIC South		
Section 21 To	ownship 22-S Range 28-E	NMPM	County Ed	ldy	
	11. Elevation (Show whether Di	R, RKB, RT, GR, etc.)			**************************************
	3068'				
	or pit or below-grade tank closures, a form				
Pit Location: ULF_Sect 21_Twp 22	-SRng 28-E Pit type Reserve _Depth	to Groundwater 100'			+
Distance from nearest surface water 10	000"+ Below-grade Tank Location 1	JLSectTw	pRng	, RECEI	IVEU
feet from the line and	feet from the line			M 4 0 8	2004
				· · · · · · · · · · · · · · · · · · ·)
				<u> </u>	
		Vature of Notice D	one of Other D	OCD-AP	
12. Check	Appropriate Box to Indicate 1		-	OCD-AP	
12. Check NOTICE OF II	Appropriate Box to Indicate 1	SUBSI	EQUENT REPO	OCD-AP ata ORT OF:	TESIA
12. Check	Appropriate Box to Indicate 1		EQUENT REPO	OCD-AP	TESIA
12. Check NOTICE OF II PERFORM REMEDIAL WORK □	Appropriate Box to Indicate INTENTION TO: PLUG AND ABANDON	SUBSI REMEDIAL WORK	EQUENT REPO	ata ORT OF: LTERING CASING	TESIA
12. Check NOTICE OF II	Appropriate Box to Indicate INTENTION TO: PLUG AND ABANDON	SUBSI	EQUENT REP(□ A ING OPNS.□ P	ata ORT OF: LTERING CASING	TESIA
12. Check NOTICE OF II PERFORM REMEDIAL WORK □	Appropriate Box to Indicate INTENTION TO: PLUG AND ABANDON CHANGE PLANS	SUBSI REMEDIAL WORK	EQUENT REPORT A PORT A	ata ORT OF: LTERING CASING	TESIA
12. Check NOTICE OF II PERFORM REMEDIAL WORK	Appropriate Box to Indicate INTENTION TO: PLUG AND ABANDON CHANGE PLANS	SUBSI REMEDIAL WORK COMMENCE DRILL	EQUENT REP(□ A ING OPNS.□ P A	ata ORT OF: LTERING CASING	TESIA
12. Check NOTICE OF II PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING	Appropriate Box to Indicate INTENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION	SUBSI REMEDIAL WORK COMMENCE DRILL CASING TEST AND CEMENT JOB	EQUENT REPORT A PORT A	ata ORT OF: LTERING CASING LUG AND BANDONMENT	TESIA
12. Check NOTICE OF II PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER:	Appropriate Box to Indicate INTENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION	SUBSI REMEDIAL WORK COMMENCE DRILL CASING TEST AND CEMENT JOB OTHER: Amended	EQUENT REPORT REPORT A SERVICE A SER	ata ORT OF: LTERING CASING LUG AND BANDONMENT	TESIA
12. Check NOTICE OF II PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or com	Appropriate Box to Indicate INTENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION pleted operations. (Clearly state all	SUBSI REMEDIAL WORK COMMENCE DRILL CASING TEST AND CEMENT JOB OTHER: Amended	EQUENT REPORT A ING OPNS. PA	ata ORT OF: LTERING CASING LUG AND BANDONMENT	TESIA G G
12. Check NOTICE OF II PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or come of starting any proposed w	Appropriate Box to Indicate INTENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION	SUBSI REMEDIAL WORK COMMENCE DRILL CASING TEST AND CEMENT JOB OTHER: Amended	EQUENT REPORT A ING OPNS. PA	ata ORT OF: LTERING CASING LUG AND BANDONMENT	TESIA G G
12. Check NOTICE OF II PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or com of starting any proposed w or recompletion.	Appropriate Box to Indicate 1 NTENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION pleted operations. (Clearly state all york). SEE RULE 1103. For Multiple Content of the c	SUBSI REMEDIAL WORK COMMENCE DRILL CASING TEST AND CEMENT JOB OTHER: Amended pertinent details, and a ple Completions: Attac	EQUENT REPORT A	ata ORT OF: LTERING CASING LUG AND BANDONMENT including estimate of proposed comp	TESIA G G G G G G G G G G G G G
12. Check NOTICE OF II PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or com of starting any proposed w or recompletion. 08/27/04 Depth 320' Footage 320'	Appropriate Box to Indicate INTENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION pleted operations. (Clearly state all ork). SEE RULE 1103. For Multiple TOH & laid down BHA. Rig up an	SUBSI REMEDIAL WORK COMMENCE DRILL CASING TEST AND CEMENT JOB OTHER: Amended pertinent details, and g ple Completions: Attach	Report pive pertinent dates, the wellbore diagram 320' 13 3/8" H-40 4	ata ORT OF: LTERING CASING LUG AND BANDONMENT including estimate of proposed comp	ed date pletion
12. Check NOTICE OF II PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or common of starting any proposed wor recompletion. 08/27/04 Depth 320' Footage 320' capacity. CMT w/ 200sx 35/65 pos	Appropriate Box to Indicate INTENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION pleted operations. (Clearly state all ork). SEE RULE 1103. For Multiple TOH & laid down BHA. Rig up are 2 C + 6%D20 + 3% S1 + .25 PPSD2	SUBSI REMEDIAL WORK COMMENCE DRILL CASING TEST AND CEMENT JOB OTHER: Amended pertinent details, and g ple Completions: Attach and run 8 jt. 323' set @ 3 9 lead. 200sx class C	Report pive pertinent dates, the wellbore diagram 20' 13 3/8" H-40 4 - 2% S1. Plug down	ata ORT OF: LTERING CASING LUG AND BANDONMENT including estimate of proposed comp 8# csg, circ two cs n @ 9:30am circ 1	ed date pletion
12. Check NOTICE OF II PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or come of starting any proposed we or recompletion. 08/27/04 Depth 320' Footage 320' capacity. CMT w/ 200sx 35/65 post to surface. WOC for 18hrs. Cut of	Appropriate Box to Indicate INTENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION Pleted operations. (Clearly state all rork). SEE RULE 1103. For Multiple TOH & laid down BHA. Rig up are Z C + 6%D20 + 3% S1 + .25 PPSD2 off cond. Weld well head test 500 ps	SUBSI REMEDIAL WORK COMMENCE DRILL CASING TEST AND CEMENT JOB OTHER: Amended pertinent details, and g ple Completions: Attach and run 8 jt. 323' set @ 3 9 lead. 200sx class C	Report pive pertinent dates, the wellbore diagram 20' 13 3/8" H-40 4 - 2% S1. Plug down	ata ORT OF: LTERING CASING LUG AND BANDONMENT including estimate of proposed comp 8# csg, circ two cs n @ 9:30am circ 1	ed date pletion
12. Check NOTICE OF II PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or common of starting any proposed wor recompletion. 08/27/04 Depth 320' Footage 320' capacity. CMT w/ 200sx 35/65 pos	Appropriate Box to Indicate INTENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION Pleted operations. (Clearly state all rork). SEE RULE 1103. For Multiple TOH & laid down BHA. Rig up are Z C + 6%D20 + 3% S1 + .25 PPSD2 off cond. Weld well head test 500 ps	SUBSI REMEDIAL WORK COMMENCE DRILL CASING TEST AND CEMENT JOB OTHER: Amended pertinent details, and g ple Completions: Attach and run 8 jt. 323' set @ 3 9 lead. 200sx class C	Report pive pertinent dates, the wellbore diagram 20' 13 3/8" H-40 4 - 2% S1. Plug down	ata ORT OF: LTERING CASING LUG AND BANDONMENT including estimate of proposed comp 8# csg, circ two cs n @ 9:30am circ 1	ed date pletion
12. Check NOTICE OF II PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or come of starting any proposed we or recompletion. 08/27/04 Depth 320' Footage 320' capacity. CMT w/ 200sx 35/65 post to surface. WOC for 18hrs. Cut of	Appropriate Box to Indicate INTENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION Pleted operations. (Clearly state all rork). SEE RULE 1103. For Multiple TOH & laid down BHA. Rig up are Z C + 6%D20 + 3% S1 + .25 PPSD2 off cond. Weld well head test 500 ps	SUBSI REMEDIAL WORK COMMENCE DRILL CASING TEST AND CEMENT JOB OTHER: Amended pertinent details, and g ple Completions: Attach and run 8 jt. 323' set @ 3 9 lead. 200sx class C	Report pive pertinent dates, the wellbore diagram 20' 13 3/8" H-40 4 - 2% S1. Plug down	ata ORT OF: LTERING CASING LUG AND BANDONMENT including estimate of proposed comp 8# csg, circ two cs n @ 9:30am circ 1	ed date pletion
12. Check NOTICE OF II PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or com of starting any proposed w or recompletion. 08/27/04 Depth 320' Footage 320' capacity. CMT w/ 200sx 35/65 por to surface. WOC for 18hrs. Cut of BHA and tag cmt @ 275'. Tested	Appropriate Box to Indicate INTENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION pleted operations. (Clearly state all york). SEE RULE 1103. For Multiple TOH & laid down BHA. Rig up at 2 C + 6%D20 + 3% S1 + .25 PPSD2 off cond. Weld well head test 500 ps for 30 min.	SUBSI REMEDIAL WORK COMMENCE DRILL CASING TEST AND CEMENT JOB OTHER: Amended pertinent details, and g ple Completions: Attac and run 8 jt. 323' set @ 3 9 lead. 200sx class C - si ok. N/U BOP and ch	Report cive pertinent dates, the wellbore diagram 320' 13 3/8" H-40 4 - 2% S1. Plug down oke manifold test @	ata ORT OF: LTERING CASING LUG AND BANDONMENT including estimate of proposed comp 8# csg, circ two cs n @ 9:30am circ 1 0 1384 psi ok. TIF	ed date pletion sg 29 sx H w/
12. Check NOTICE OF II PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or come of starting any proposed we or recompletion. 08/27/04 Depth 320' Footage 320' capacity. CMT w/ 200sx 35/65 post to surface. WOC for 18hrs. Cut of	Appropriate Box to Indicate INTENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION Deleted operations. (Clearly state all york). SEE RULE 1103. For Multiple TOH & laid down BHA. Rig up at 2. C + 6%D20 + 3% S1 + .25 PPSD2 off cond. Weld well head test 500 perfor 30 min.	SUBSI REMEDIAL WORK COMMENCE DRILL CASING TEST AND CEMENT JOB OTHER: Amended pertinent details, and g ple Completions: Attac and run 8 jt. 323' set @ 3 9 lead. 200sx class C - si ok. N/U BOP and ch	Report ive pertinent dates, the wellbore diagram 320' 13 3/8" H-40 4 2% S1. Plug down oke manifold test @	ata ORT OF: LTERING CASING LUG AND BANDONMENT including estimate of proposed comp 8# csg, circ two cs on @ 9:30am circ 1 0 1384 psi ok. TIF	ed date pletion sg 29 sx H w/
12. Check NOTICE OF II PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comof starting any proposed wor recompletion. 08/27/04 Depth 320' Footage 320' capacity. CMT w/ 200sx 35/65 porto surface. WOC for 18hrs. Cut of BHA and tag cmt @ 275'. Tested I hereby certify that the information grade tank has been/will be constructed or	Appropriate Box to Indicate INTENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION Detect operations. (Clearly state all york). SEE RULE 1103. For Multiple Conductions are conducted by the conduction of the conductio	SUBSI REMEDIAL WORK COMMENCE DRILL CASING TEST AND CEMENT JOB OTHER: Amended pertinent details, and g ple Completions: Attac and run 8 jt. 323' set @ 3 9 lead. 200sx class C - si ok. N/U BOP and ch coest of my knowledge a	Report ive pertinent dates, the wellbore diagram 320' 13 3/8" H-40 4 2% S1. Plug down oke manifold test @ and belief. I further can (attached) alternation	ata ORT OF: LTERING CASING LUG AND BANDONMENT including estimate of proposed comp 8# csg, circ two cs n @ 9:30am circ 1 0 1384 psi ok. TIF	ed date pletion sg 29 sx H w/
12. Check NOTICE OF II PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or come of starting any proposed we or recompletion. 08/27/04 Depth 320' Footage 320' capacity. CMT w/ 200sx 35/65 por to surface. WOC for 18hrs. Cut of BHA and tag cmt @ 275'. Tested I hereby certify that the information	Appropriate Box to Indicate INTENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION Detect operations. (Clearly state all york). SEE RULE 1103. For Multiple Conductions are conducted by the conduction of the conductio	SUBSI REMEDIAL WORK COMMENCE DRILL CASING TEST AND CEMENT JOB OTHER: Amended pertinent details, and g ple Completions: Attac and run 8 jt. 323' set @ 3 9 lead. 200sx class C - si ok. N/U BOP and ch	Report ive pertinent dates, the wellbore diagram 320' 13 3/8" H-40 4 2% S1. Plug down oke manifold test @ and belief. I further can (attached) alternation	ata ORT OF: LTERING CASING LUG AND BANDONMENT including estimate of proposed comp 8# csg, circ two cs n @ 9:30am circ 1 0 1384 psi ok. TIF	ed date pletion sg 29 sx H w/
12. Check NOTICE OF II PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or come of starting any proposed we or recompletion. 08/27/04 Depth 320' Footage 320' capacity. CMT w/ 200sx 35/65 porto surface. WOC for 18hrs. Cut of BHA and tag cmt @ 275'. Tested I hereby certify that the information grade tank has been/will be constructed of SIGNATURE	Appropriate Box to Indicate INTENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION Deleted operations. (Clearly state allors). SEE RULE 1103. For Multiports). SEE RULE 1103. For Multiports and Complete to the Inches of the Inche	SUBSI REMEDIAL WORK COMMENCE DRILL CASING TEST AND CEMENT JOB OTHER: Amended pertinent details, and g ple Completions: Attac and run 8 jt. 323' set @ 3 9 lead. 200sx class C- si ok. N/U BOP and ch Dest of my knowledge a J, a general permit or Staff Engineer	Report ive pertinent dates, the wellbore diagram 320' 13 3/8" H-40 4-2% S1. Plug down oke manifold test an (attached) alternative	ata ORT OF: LTERING CASING LUG AND BANDONMENT including estimate of proposed comp 8# csg, circ two cs n @ 9:30am circ 1 0 1384 psi ok. TII certify that any pit or we OCD-approved pla 02/04	ed date pletion sg 29 sx H w/
12. Check NOTICE OF II PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comof starting any proposed wor recompletion. 08/27/04 Depth 320' Footage 320' capacity. CMT w/ 200sx 35/65 porto surface. WOC for 18hrs. Cut of BHA and tag cmt @ 275'. Tested I hereby certify that the information grade tank has been/will be constructed or	Appropriate Box to Indicate INTENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION Deleted operations. (Clearly state allors). SEE RULE 1103. For Multiports). SEE RULE 1103. For Multiports and Complete to the Inches of the Inche	SUBSI REMEDIAL WORK COMMENCE DRILL CASING TEST AND CEMENT JOB OTHER: Amended pertinent details, and g ple Completions: Attac and run 8 jt. 323' set @ 3 9 lead. 200sx class C - si ok. N/U BOP and ch coest of my knowledge a	Report ive pertinent dates, the wellbore diagram 320' 13 3/8" H-40 4-2% S1. Plug down oke manifold test an (attached) alternative	ata ORT OF: LTERING CASING LUG AND BANDONMENT including estimate of proposed comp 8# csg, circ two cs n @ 9:30am circ 1 0 1384 psi ok. TII certify that any pit or we OCD-approved pla 02/04	ed date pletion sg 29 sx H w/
12. Check NOTICE OF II PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or come of starting any proposed wor recompletion. 08/27/04 Depth 320' Footage 320' capacity. CMT w/ 200sx 35/65 post to surface. WOC for 18hrs. Cut of BHA and tag cmt @ 275'. Tested I hereby certify that the information grade tank has been/will be constructed of SIGNATURE Type or print name Josh Fernau	Appropriate Box to Indicate INTENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION Deleted operations. (Clearly state allors). SEE RULE 1103. For Multiports). SEE RULE 1103. For Multiports and Complete to the Inches of the Inche	SUBSI REMEDIAL WORK COMMENCE DRILL CASING TEST AND CEMENT JOB OTHER: Amended pertinent details, and g ple Completions: Attac and run 8 jt. 323' set @ 3 9 lead. 200sx class C- si ok. N/U BOP and ch Dest of my knowledge a J, a general permit or Staff Engineer	Report ive pertinent dates, the wellbore diagram 320' 13 3/8" H-40 4-2% S1. Plug down oke manifold test an (attached) alternative	ata ORT OF: LTERING CASING LUG AND BANDONMENT including estimate of proposed comp 8# csg, circ two cs n @ 9:30am circ 1 0 1384 psi ok. TII certify that any pit or we OCD-approved pla 02/04	ed date pletion sg 29 sx H w/
12. Check NOTICE OF II PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or come of starting any proposed we or recompletion. 08/27/04 Depth 320' Footage 320' capacity. CMT w/ 200sx 35/65 porto surface. WOC for 18hrs. Cut of BHA and tag cmt @ 275'. Tested I hereby certify that the information grade tank has been/will be constructed of SIGNATURE	Appropriate Box to Indicate INTENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION Deleted operations. (Clearly state allors). SEE RULE 1103. For Multiports). SEE RULE 1103. For Multiports and Complete to the Inches of the Inche	SUBSI REMEDIAL WORK COMMENCE DRILL CASING TEST AND CEMENT JOB OTHER: Amended pertinent details, and g ple Completions: Attac and run 8 jt. 323' set @ 3 9 lead. 200sx class C- si ok. N/U BOP and ch Dest of my knowledge a J, a general permit or Staff Engineer	Report ive pertinent dates, the wellbore diagram 320' 13 3/8" H-40 4-2% S1. Plug down oke manifold test an (attached) alternative	ata ORT OF: LTERING CASING LUG AND BANDONMENT including estimate of proposed comp 8# csg, circ two cs n @ 9:30am circ 1 0 1384 psi ok. TII certify that any pit or we OCD-approved pla 02/04	ed date pletion sg 29 sx H w/
12. Check NOTICE OF II PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comon of starting any proposed woor recompletion. 08/27/04 Depth 320' Footage 320' capacity. CMT w/ 200sx 35/65 por to surface. WOC for 18hrs. Cut of BHA and tag cmt @ 275'. Tested I hereby certify that the information grade tank has been/will be constructed of SIGNATURE Type or print name Josh Fernau (This space for State use)	Appropriate Box to Indicate INTENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION Deleted operations. (Clearly state allors). SEE RULE 1103. For Multiports). SEE RULE 1103. For Multiports and Complete to the Inches of the Inche	SUBSI REMEDIAL WORK COMMENCE DRILL CASING TEST AND CEMENT JOB OTHER: Amended pertinent details, and g ple Completions: Attac and run 8 jt. 323' set @ 3 9 lead. 200sx class C- si ok. N/U BOP and ch Dest of my knowledge a J, a general permit or Staff Engineer	Report ive pertinent dates, the wellbore diagram 320' 13 3/8" H-40 4 2% S1. Plug down oke manifold test @ and belief. I further can (attached) alternative	ata ORT OF: LTERING CASING LUG AND BANDONMENT including estimate of proposed comp 8# csg, circ two cs n @ 9:30am circ 1 0 1384 psi ok. TII certify that any pit or we OCD-approved pla 02/04	ed date pletion sg 29 sx H w/