

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

RECEIVED

MAR - 8 2012

Form C-141  
Revised August 8, 2011

NMOC DARTESIA

Submit a copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NMLB/208347706

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: Canyon E&P Company 269864	Contact: Travis White
Address: 911 Lake Carolyn Pkwy, Ste 104 Irving, TX 75039	Telephone No.: 214-265-7101
Facility Name: Double L Queen	Facility Type: Tank Battery

Surface Owner State	Mineral Owner	API No. 30-005-60078
---------------------	---------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	1	15s	29e	330	N	330	E	Chaves

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

NATURE OF RELEASE

Type of Release: Overflow	Volume of Release: 20 bbl of water; 10 bbl of crude	Volume Recovered: 0
Source of Release: Switch failure	Date and Hour of Occurrence: 3/4/2012 overnight	Date and Hour of Discovery: 3/4/2012 around 11 AM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*



Describe Cause of Problem and Remedial Action Taken.\*

Automatic switch on main battery tank failed causing the tank overflow.

Describe Area Affected and Cleanup Action Taken.\*

Overrunning of the top of tank battery and the wind gusts of 50 mph caused the crude to spray over the ground and building east of the tank battery. Affected area is between 100-150ft. Covered ground oil with dirt and building was pressure washed. Crude still remains on building. Plans to continue pressure washing as well as properly dispose effect dirt on ground.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOC D rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOC D marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOC D acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Travis White	Signed By: 	
Title: Agent	Approved by Environmental Specialist:	
E-mail Address: travis@eddc.drcer.com	Approval Date: MAR 23 2012	Expiration Date:
Date: 3-8-12	Conditions of Approval: Remediation per OCD Rules & Guidelines. SUBMIT REMEDIATION PROPOSAL NOT LATER THAN: 4/23/2012	Attached <input type="checkbox"/>

\* Attach Additional Sheets If Necessary

2RP-1063