Form 3160-5 (April 2004)

UNITED STATES

DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT BUREAU OF LAND MANAGEMENT

FORM APPROVED OM B No 1004-0137 Expires: March 31, 2007

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.		5. Lease Senal No. NMNM62589
		6 If Indian, Allottee or Tribe Name
SUBMIT IN TRIPLICATE- Other in	nstructions on reverse side.	7. If Unit or CA/Agreement, Name and/or No.
1. Type of Well ☐ ☐ Gas Well ☐ ☐ Other		8. Well Name and No.
2. Name of Operator OXY USA Inc.	16696	Federal 23 # ¶ 9. API Well No.
3a Address P.O. Box 50250 Midland, TX 79710	3b. Phone No. (include area code) 432-685-5717	30-015- 37334 10. Field and Pool, or Exploratory Area
4. Location of Well (Footage, Sec., T., R., M., or Survey Description 2261 FNL 656 FEC SENECH		Livingston Ridge Delaware 11. County or Parish, State
1978 FIL 2027 FEL SWINE (·	Eddy, NM
12. CHECK APPROPRIATE BOX(ES)	TO INDICATE NATURE OF NOTICE, I	REPORT, OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACTION	
Acidize Alter Casing Casing Repair Change Plans Final Abandonment Notice Acidize Alter Casing Casing Repair Change Plans Convert to Injection	□ Deepen □ Production (St □ Fracture Treat □ Reclamation □ New Construction □ Recomplete □ Plug and Abandon □ Temporarily A □ Plug Back □ Water Disposal	Well Integrity Other bandon
following completion of the involved operations. If the open testing has been completed. Final Abandonment Notices sha determined that the site is ready for final inspection.)		
Accepted for reco	See Attached	RECEIVED DEC 1 2 2011
NMOCD NMOCD ARTESIA		
14. I hereby certify that the foregoing is true and correct Name (Printed/Typed) David Stewart	Title Regulatory Advisor	
Signature Out The	Date 9/25/4	FOR RECORD
THIS SPACE FOR FEDERAL OR STAYE BETTIELD SE / /		
Approved by Conditions of approval, if any, are attached. Approval of this ne	Title	DEC Date 2011

Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfullyllo make to Early department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction. (Instructions on page 2)

certify that the applicant holds legal or equitable title to those rights in the subject lease

which would entitle the applicant to conduct operations thereon.

Federal 23 #9 API No. 30-015-37340

TD-8632'M 8383'V PBTD-8540'M 8302'V Perfs-8267-8518'

11-3/4" 42# @ 846' w/ 330sx, 14-3/4" hole, TOC-Surface-Circ 8-5/8" 32# @ 4238' w/ 1150sx, 10-5/8" hole, TOC-Surface-Circ 5-1/2" 17# @ 8629' DVT's @ 6008, 4334' w/ 1590sx, 7-7/8" hole, TOC-Surf-Circ

Procedure:

- 1. Clean location & set anchors
- 2. RU DDPU, POOH w/ rods and pump. NDWH, NU BOP.
- 3. POOH w/ tubing, ND BOP and NU Frac Valve, RD DDPU.
- 4. RU WL UNIT and RIH w/ Composite BP and set above existing perfs @ 8518-8267'.
- 5. Perforate 1 JSPF @ in 4 stages @ 7923-7702, 7562-7290, 7232-6893, 6738-6487' w/ 4" Titan SDP EXP 4039-321T 38.5 gram charge w/ .43" EHD and 55" penetration on 90 degree phasing. RD WLU.
- 6. Frac well down casing at first available date per Halliburton frac procedure.
- 7. RU WLU and set Composite BP between stages.
- 8.. Shut well in overnight and RD Frac equipment and WLU.
- 9. MI RUPU, ND Frac valve, NU BOP.
- 10. PU tubing and RIH with bit and drill out Composite BP's to PBTD.
- 11. RIH w/ tbg & pkr, swab & flow well until sand cleans up.
- 12. POOH & RIH W/ production BHA as directed
- 13. Test well into battery

OXY USA Inc. Federal 23 #9 API No. 30-015-37334

