

Submit 1 Copy To Appropriate District Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised August 1, 2011

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-015-04700
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>		5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
2. Name of Operator VANGUARD PERMIAN LLC		6. State Oil & Gas Lease No.
3. Address of Operator 5847 SAN FELIPE SUITE 3000, HOUSTON TX 77057		7. Lease Name or Unit Agreement Name STOVALL WOOD
4. Well Location Unit Letter C ; 660 feet from the NORTH line and 1980 feet from the WEST line Section 20 Township 205 Range 30E NMPM County EDDY		8. Well Number 1
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3205'		9. OGRID Number 309293
		10. Pool name or Wildcat BARBER; YATES

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPERATIONS ☐ P & A ☐
CASING/CEMENT JOB ☐ **Not to be done prior to any work done.**

OTHER: ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. PLUG & ABANDON AS FOLLOWS:

1)RU PLUGGING CONTRACTOR. TOH & LD PRODUCTION EQUIPMENT. CIRCULATE WELL TO MUD.

2)SPOT CEMENT PLUG FROM 1540' - 1350' (40 SXS). WOC. TAG PLUG. TOP OFF AS NECESSARY.

3)SPOT CEMENT PLUG FROM 1350' - 800' (140 SXS). PERF SQUEEZE HOLES @790'. SET GMT-RETAINER. *Packer*
ESTABLISH PUMP IN RATE. FILL 7" ANNULUS TO SURFACE W/CEMENT (150 SXS). TOP OFF 7", 8 5/8",
12 1/2" ANNULI AS NECESSARY.


4)CUT OFF WELL HEADS. INSTALL P&A MARKER. RESTORE SURFACE LOCATION.

R-111-P Potash Mine area

A solid Cement plug must be set across the salt section.

Spud Date:

Rig Release Date:



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Vickie Tompkins

TITLE OFFICE MANAGER

DATE 01/26/12

Type or print name VICKIE TOMPKINS

E-mail address: vtompkins@vnrlc.com

PHONE: 432.362.2209

For State Use Only

APPROVED BY:

[Signature]

TITLE

DATE 2/2/2012

SEE ATTACHED
CONDITIONS OF
APPROVAL

Approval Granted providing work
is complete by 5/8/2012