


District I
1625 N French Dr , Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St Francis Dr , Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003

Release Notification and Corrective Action

JMW 1229741733

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: Linn Operating 269324	Contact: Joe Hernandez
Address: 2130 W. Bender Hobbs, NM 88240	Telephone No.: 575-738-1739
Facility Name: Turner B # 60	Facility Type: Injection

Surface Owner: Federal	Mineral Owner: Federal	API No.: 3001505447
------------------------	------------------------	---------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
K	29	17S	31E	1980	South	1980	West	Eddy

Latitude: 32.8037530192612 Longitude: -103.893970977208

NATURE OF RELEASE

Type of Release: Oil / Produced Water	Volume of Release: 60 bbls / 196 bbls	Volume Recovered: 25 bbls / 15 bbls
Source of Release: Steel pipeline	Date and Hour of Occurrence: 10/15/2012 8am	Date and Hour of Discovery: 10/15/2012 8:30am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Randy Dade- NM OCD Terry Gregston-BLM	
By Whom? Gary Wink	Date and Hour 10/15/2012 10am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*:

Describe Cause of Problem and Remedial Action Taken.*: 2x6 inch nipple on header in front of 2" transition was under dirt and corroded, causing to blow a hole on nipple. Sucked up all standing water inside dike area, and along road where it ran off dike.

Describe Area Affected and Cleanup Action Taken.* : Spill ran north of header and west to dike and washed out dike, ran southwest along lease road and fingered off onto pasture. It ran 180ft onto first trail and 250ft onto second trail into pasture. Average footage was 1,126X12. THIS HAPPEND AT BATTERY NOT WELL HEAD. Further remedial action pending.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCB rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCB marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCB acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION	
Printed Name: Joe Hernandez	Signed By	
Title: Production Foreman	Approved by District Supervisor: OCT 23 2012	Expiration Date:
E-mail Address: jhernandez@linenergy.com	Approval Date:	Attached <input type="checkbox"/>
Date: 10/18/2012 Phone: 575-942-9492	Conditions of Approval:	

* Attach Additional Sheets If Necessary

Remediation per OCD Rules & Guidelines. SUBMIT REMEDIATION PROPOSAL NOT LATER THAN:

Nov. 23, 2012

2RP-1335