Submit 3 Copies To Appropriate District Office	State of New Mexico		Form C-103
District I	Energy, Minerals and Natural Resources		May 27, 2004 WELL API NO.
1625 N. French Dr., Hobbs, NM 88240 District II			30-02524-24-6
1301 W. Grand Ave., Artesia, NM 88210 District III	OIL CONSERVATION DIVISION		5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410	Rio Brazos Rd., Aztec, NM 87410 Santa Fe NM 87505		STATE FEE XX
District IV 1220 S. St. Francis Dr., Santa Fe, NM		6. State Oil & Gas Lease No.	
87505			5-229-1
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		J.F. Janda(NCT-E)	
1. Type of Well: Oil Well X Gas Well Other		8. Well Number # 1	
2. Name of Operator			9. OGRID Number
Pogo Producing Company 3. Address of Operator			10. Pool name or Wildcat
P.O. Box 10340, Midland, TX 79702		Eumont	
4. Well Location			
· I	990 feet from the North	line and 165	feet from the East line
Section 21	Township 235 Ran	-7	NMPM Lea County
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3439 GR			
Pit or Below-grade Tank Application or Closure Over			
Pit type Steel Depth to Groundwater 188.5 Distance from nearest fresh water well 1000' Distance from nearest surface water 1000'			
Pit Liner Thickness: mil Below-Grade Tank: Volume bbls; Construction Material			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING			
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. P AND A PULL OR ALTER CASING MUST			
OTHER: BENETIFIED 24 HOURS PRIDE TO THE			
13. Describe proposed or completed operations. (Clearly state al Bie Grand Red Red Red Red Red Red Red Red Red Re			
or recompletion.			
•			
 POOH - w/ Production equipment. Set C.I.B.P. @ 2,875', cap w/ 25 sx of cement. 			
3. Circulate hole w/ 9.5 # mud.			
4. POOH w/ tubing.			
5. Cut and pull casing at1500'.			
6. RIH w/ open tubing and spot a 75 sx Plug.			
7. Tag Plug at 1350' . /335' 8. Spot a 35 sx from 500' - 350'.			
9. Spot 10 sx surface Prug & place Dry Hole marker.			
:			
I hereby certify that the information	ahove is true and complete to the be-	ot of my less and a de-	a and haliaf ve at
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-approved plan .			
1112	***		DATE 9-16-055
SIGNATURE Y	TITLE_	Agent	DATE 9-10-053
Type or print name Howard Bo	atright . E-mail add	dress:	Telephone No.

APPROVED BY: Approval (if any)

Conditions of Approval (if any)

Telephone No.

432-617-0208

Conditions of Approval (if any)