


District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505



Form C-141  
Revised October 10, 2003

Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

Release Notification and Corrective Action

NJM 130384712

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company	COG OPERATING LLC 229137	Contact	Pat Ellis
Address	600 West Illinois Avenue, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	Hambone Fee Com #1H	Facility Type	Tank Battery

Surface Owner Private	Mineral Owner	Lease No. (API#) 30-015-38980
-----------------------	---------------	-------------------------------

LOCATION OF RELEASE

Unit Letter M	Section 5	Township 26S	Range 29E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
------------------	--------------	-----------------	--------------	---------------	------------------	---------------	----------------	----------------

Latitude 32 3 57.3

Longitude 104 00 50.4

NATURE OF RELEASE

Type of Release Produced water	Volume of Release 450bbbls	Volume Recovered 445bbbls
Source of Release Water transfer pump	Date and Hour of Occurrence 01/19/2013	Date and Hour of Discovery 01/19/2013 12:00 p.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher-OCD	
By Whom? Michelle Mullins	Date and Hour 01/20/2013 2:45 p.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

A 1" steel nipple failed on the water transfer pump allowing the release of fluid into the lined facility. Replaced with new stainless steel nipple and valve, and plastic coated Victaulic bushing.

Describe Area Affected and Cleanup Action Taken.\*

Initially 450bbbls were released from the water pump and we were able to recover 445bbbls with vacuum trucks. The entire release was contained inside the lined facility. All free fluid has been recovered. Contaminated gravel has been removed from the facility and we have replaced with fresh gravel as necessary. Equipment and lining has been pressure washed. This facility has been returned to its prior condition.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOC D rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOC D marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOC D acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		OIL CONSERVATION DIVISION	
Printed Name: Josh Russo		Approved by District Supervisor:	
Title: Senior Environmental Coordinator		Approval Date: FEB 07 2013 Expiration Date:	
E-mail Address: jrusso@concho.com		Conditions of Approval:	
Date: 01/29/2013 Phone: 432-212-2399		Attached <input type="checkbox"/>	

\* Attach Additional Sheets If Necessary

Accepted for record  
NMOC D

2RP-1543