

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

RECEIVED

MAR 12 2013

Form C-141  
Revised October 10, 2003

NMOCD ARTESIA

Submit copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

Release Notification and Corrective Action

nJMW1308553143 OPERATOR ☒ Initial Report ☐ Final Report

Name of Company	Oxy Permian Ltd.	16696	Contact	CJ Summers
Address	1017 W. Stanolind Rd, Hobbs, NM		Telephone No.	(575) 397-8216
Facility Name	Pure Gold A Federal #2 Battery		Facility Type	Gathering
Surface Owner	BLM	Mineral Owner	Lease No. NM 38464	

LOCATION OF RELEASE

\*APT: 30.015.27243

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	21	23S	31E					Eddy

Latitude N 32.28428° Longitude W 103.79005

NATURE OF RELEASE

Type of Release	Oil and Produced water	Volume of Release	15 bbls water and 0.5 bbls skim oil	Volume Recovered	7 bbls
Source of Release	Flex Coupling broke on water transfer pump	Date and Hour of Occurrence	2/08/13	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher - OCD; James Amos & Jennifer Van Curen - BLM		
By Whom?	Chancey Summers	Date and Hour	2/11/13 @ 7:29 am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

Flex coupling on a water transfer pump broke and caused 15 bbls of water and 0.5 bbl of skim oil to leak onto the ground. 7 bbls of fluid were recovered via vacuum truck. The coupling was repaired.

Describe Area Affected and Cleanup Action Taken.\*

Flex coupling on a water transfer pump broke and caused 15 bbls of water and 0.5 bbl of skim oil to leak onto the ground. 7 bbls of fluid were recovered via vacuum truck. The coupling was repaired. Remediation will be performed in accordance with an OCD and BLM approved remediation plan.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION		
Printed Name: Chancey Summers	Approved by District Supervisor:	Signed By <u>Mike Bratcher</u>	
Title: HES Specialist	Approval Date: <u>MAR 26 2013</u>	Expiration Date:	
E-mail Address: Chancey.Summers@oxy.com	Conditions of Approval:	Attached <input type="checkbox"/>	
Date: <u>3-12-13</u>	Phone: (575) 397-8216		

\* Attach Additional Sheets If Necessary

Remediation per OCD Rule &  
Guidelines. SUBMIT REMEDIATION

PROPOSAL NO LATER THAN:

April 26, 2013

2RP-1588