•		OCD Art	esia				
	UNITED STATES DEPARTMENT OF THE INTERIOR			FORM APPROVED OMB No. 1004-0137 Expires: October 31, 2014			
BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS				5. Lease Serial No. NMNM010907A			
Do not use this	form for proposals to	o drill or to re-enter a D drill or to re-enter a PD) for such proposa		6. If Indian, Allotte	e or Tribe Name		
SUBMIT IN TRIPLICATE – Other instructions on page 2. 1. Type of Well				7. If Unit of CA/Agreement, Name and/or No. RDM065 NM 72364			
Oil Well 🔽 Gas Well 🗌 Other				8. Well Name and No. Empire Fed 35-1			
2. Name of Operator Sabre Operating, Inc. Contact: Denise Field, email: DF@SABREOP.com				9. API Well No. 30-015-23449-00-S1			
3a. Address 3b. Phone No. (include area code) P.O. Box 4848 940-696-8077 Ext. 216				10. Field and Pool or Exploratory Area Undesignated			
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Section 35-T18S-R29E-NESW				 County or Parish, State Eddy County, NM 			
12. CHE0	CK THE APPROPRIATE BO	X(ES) TO INDICATE NATUR	E OF NOTIC	LE, REPORT OR O'I	THER DATA		
TYPE OF SUBMISSION	TYPE OF SUBMISSION TYPE OF ACT				NON		
Votice of Intent	Acidize	Deepen Fracture Treat		uction (Start/Resume) amation	Water Shut-Off		
Subsequent Report		New Construction		mplete	Other		
Final Abandonment Notice	Change Plans	Plug and Abandon Plug Back		oorarily Abandon r Disposal			
determined that the site is ready for Start date is anticipated to be 1/2/13 stimulate the current Wolfcamp pert 9500' with a sealing overshot and e the 2-3/8" tubing. Once the plug has top Atoka perforation at 10,757' this Carlsbad Field Office. We will then stimulation in the Wolfcamp perfora	3. The proposed plan is to r forations (9260'-9284'). We stablish that we are able to s set we will tag it with slick will plug the Atoka perfora set a CIBP at approximately	will drill out the cement and a pump into the Atoka perforal line thru tubing to find the top tion as discussed and agreed y 9480' and cap with 28' of ne	a CIBP set a tions. We wi o of the ceme d upon with I	at 9485', Then latch III then pump a 25 s ent. If the cement t Paul Swartz, Petro	n onto the cut and stuck tubing at sx neat Class H cement plug down op is at least 25 or more above the leum Engineering Technician, in the	9	
Bond number: PIB 01	жчтаа	APR 1 5 2013					
NMOCD		NMOCD ARTES		SEE ATTA CONDITI(ACHED FOR DNS OF APPROVAL		
14. Thereby certify that the foregoing is t Ron Jackson	rhe and correct. Name (Printed.	/Typed) Title Presider	nt		· ·		
Signature DU	<u>}</u>	Date 12/10/20	012		ADDDAVED		
/	THIS SPACE F	FOR FEDERAL OR ST	ATE OFF	FICE USE		1	
Approved by Conditions of approval, if any, are attached that the applicant holds legal or equitable t entitle the applicant to conduct operations Title 18 U.S.C. Section 1001 and Title 43 fictitious or fraudulent statements or repre	itle to those rights in the subject thereon. U.S.C. Section 1212, make it a	t lease which would Office of any person knowingly a	nd willfully to	o make to any dep artm	APR 10 2013 /s/ Chris Walls BUREAU OF LAND MANAGEME BUREAU OF LAND MANAGEME BUREAU OF LAND MANAGEME BUREAU OF LAND MANAGEME	V I	
(Instructions on page 2)							

,

Draft of Conditions of Approval

Sabre Operating Inc. Empire Fed Com 35 - 01 API 3001523449, T18S-R29E, Sec 35

As the current operator you are required to:

- 1. Tag plug a minimum of 210' above the Atoka perforations at 10547'
- 2. A minimum of 35 feet of cement must be bailed on top of CIBP at 9480'.
- 3. Notify BLM 575-200-7902 before plug back procedures. The procedures are to be witnessed. If no answer, leave a voice mail with the API#, workover purpose, and a call back phone number. Note the contact, time, & date in your subsequent report. Surface disturbance beyond the existing pad must have prior approval.
- 4. A closed loop system is required. The operator shall properly dispose of drilling/circulating contents at an authorized disposal site. Tanks are required for all operations, no excavated pits.
- 5. Functional H_2S monitoring equipment shall be on location.
- 6. A minimum of 5000 (5M) BOPE shall be used. All blowout preventer (BOP) and related equipment (BOPE) shall comply with reasonable well control requirements. A two ram system with a blind ram and a pipe ram designed for the size of the work string shall be adequate. Tapered work strings will require an additional pipe ram. The manifold shall comply with Onshore Oil and Gas Order #2 Attachment I (5M) Diagrams of Choke Manifold Equipment). The accumulator system shall have an immediately available power source to close the rams and retain 200 psi above pre-charge. The pre-charge test shall follow requirements in Onshore Order #2.
- 7. All waste (i.e. trash, salts, chemicals, sewage, gray water, etc.) created as a result of work over operations shall be safely contained and disposed of properly at a waste disposal facility. No waste material or fluid shall be disposed of on the well location or surrounding area. Porto-johns and trash containers will be on-location during fracturing operations or any other crew-intensive operations.
- 8. The BLM PET witness is to run tbg tally and agree to cement placement. Sample each plug for cement curing time and tag and/or pressure test (WOC time of 4 hours recommended) as requested by BLM PET witness.
- 9. Class H > 7500ft & C < 7500ft) cement plugs(s) will be necessary. The minimum pumped volume of 25 sacks of cement slurry is to exceed a 100ft cement plug across the drilled wellbore. Add 10% to the 100ft slurry volume for each 1000ft of plug depth when calculations indicate the need. For any plug that requires a tag or pressure test a minimum WOC time of 4 hours(C) & 8 hours(H) is recommended. Formation isolation plugs of Class</p>

"C" to be mixed 14.8#/gal, 1.32 ft³/sx, 6.3gal/sx water and "H" to be mixed 15.6#/gal, 1.18ft³/sx, 5.2gal/sx water.

- 10. Minimum requirement for mud placed between plugs is 25 sacks of salt water gel per 100 barrels in 9 lb/gal brine.
- 11. Prior to the Wolfcamp stimulation prove the production casing integrity from no more than 100 feet above the of the top perforation at with a PET witnessed and documented minimum pressure test of 500psig for 30 minutes. Document the pressure test on a calibrated recorder chart registering within 25 to 85 per cent of its full range. Greater than 10% pressure leakoff will be viewed as a failed MIT. Pressure leakoff will be evaluated site specifically and may restrict continued operation approval.
- 12. Should the mechanical integrity test fail or <u>not be conducted</u> submit a procedure to plug and abandon the well for BLM approval on or before 07/10/2013.

PRS/CRW 04.10.2013

This well's recorded activity has been inactive/shut-in for more than 30 days without authorization. An inactive/shut-in well bore is a non-producing completion that is capable of production in **paying quantities** or of service use.

Consider the beneficial use prospects and the wellbore integrity of this well. Submit your plan for BLM approval on the Sundry Notice Form 3160-5 (the original and 3 copies).

A legitimate request is necessary for extension of that date.

References: 43 CFR 3162.1(a), 43 CFR 3162.3-2, 43 CFR 3162.3-4, 43 CFR 3162.4-1, Onshore Oil and Gas Order #1.X., & Onshore Oil and Gas Order #2.III.G.

Access information for use of Form 3160-5 "Sundry Notices and Reports on Wells"

NM Fed Regs & Forms - http://www.blm.gov/nm/st/en/prog/energy/oil_and_gas.html

§ 43 CFR 3162.3-2 Subsequent Well Operations.

§ 43 CFR 3160.0-9 (c)(1) Information collection.

§ 3162.4-1 (c) Well records and reports.