Office •	State of New	Mexico	Form C-103
District I	Energy, Minerals and N	Vatural Resources	March 4, 2004
1625 N. French Dr., Hobbs, NM 88240			WELL API NO.
District II	OIL CONSERVATI	ON DIVICION	30 005 63272
1301 W. Grand Ave., Artesia, NM 88210			5. Indicate Type of Lease
<u>District III</u> 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. I	rancis Dr.	STATE x FEE
District IV	Santa Fe, NM	1 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	,		26571
	CES AND REPORTS ON WE	110	7 Loggo Nome on Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOS			7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLIC.	ATION FOR PERMIT" (FORM C-10	1) FOR SUCH	Will G : "Oln G.
PROPOSALS.)	(-,	Willow Springs "21" State
1. Type of Well:		סבטבו ערט	8. Well Number
Oil Well Gas Well x O	ther	RECEIVED	1
2. Name of Operator		APR 2 3 2004	9. OGRID Number
Reliance Energy, Inc		APR & 0 1004	149441
3. Address of Operator		OCD-ARTESIA	10. Pool name or Wildcat
6 Desta Drive, Suite 5500, Midland	T 70705	OOD / WILDING	1
	, 1x /9/03		Pecos Slope Abo
4. Well Location			
Unit LetterU:	_660feet from theNort	h line and6	60feet from theWestline
Section 21	Township 4S	Range 25E	NMPM Chaves County
A STATE OF THE STA	11. Elevation (Show whether	DR, RKB, RT, GR, etc.,	
3876' GR			
Pit or Below-grade Tank Application (For	pit or below-grade tank closures, a f	orm C-144 must be attache	<u>d)</u>
Pit Location: UL Sect Twn	Rng Pit type	Denth to Groundwater	Distance from nearest fresh water well
Distance from nearest surface water	Below-grade Tank Location U	LSectTwp	Rng;
feet from theline and	feet from theline		
			* · · · · · · · · · · · · · · · · · · ·
12. Check A	ppropriate Box to Indicate	Nature of Notice,	Report or Other Data
NOTICE OF INT			SEQUENT REPORT OF:
PERFORM REMEDIAL WORK			K II ALTERING CASING II
PERFORM REMEDIAL WORK	PLOG AND ABANDON	REWIEDIAL WOR	K ☐ ALTERING CASING ☐
PERFORM REMEDIAL WORK [] TEMPORARILY ABANDON []	CHANGE PLANS	COMMENCE DRI	LLING OPNS. □ PLUG AND x
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRI	LLING OPNS.□ PLUG AND x ABANDONMENT
_	CHANGE PLANS MULTIPLE	COMMENCE DRI	LLING OPNS.□ PLUG AND x ABANDONMENT
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRI	LLING OPNS.□ PLUG AND x ABANDONMENT
TEMPORARILY ABANDON PULL OR ALTER CASING	CHANGE PLANS MULTIPLE	COMMENCE DRI CASING TEST AN CEMENT JOB	LLING OPNS.□ PLUG AND x ABANDONMENT
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER:	CHANGE PLANS MULTIPLE COMPLETION	COMMENCE DRI CASING TEST AN CEMENT JOB OTHER:	LLING OPNS. PLUG AND X ABANDONMENT ND
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or complete	CHANGE PLANS MULTIPLE COMPLETION cted operations. (Clearly state	COMMENCE DRI CASING TEST AN CEMENT JOB OTHER: all pertinent details, and	LLING OPNS. PLUG AND x ABANDONMENT ND I give pertinent dates, including estimated date
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or complet of starting any proposed work.	CHANGE PLANS MULTIPLE COMPLETION cted operations. (Clearly state	COMMENCE DRI CASING TEST AN CEMENT JOB OTHER: all pertinent details, and	LLING OPNS. PLUG AND X ABANDONMENT ND
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or complet of starting any proposed work or recompletion	CHANGE PLANS MULTIPLE COMPLETION cted operations. (Clearly state k). SEE RULE 1103. For Mu	COMMENCE DRI CASING TEST AN CEMENT JOB OTHER: all pertinent details, and ltiple Completions: At	LLING OPNS. PLUG AND x ABANDONMENT ND digive pertinent dates, including estimated date tach wellbore diagram of proposed completion
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or complet of starting any proposed work or recompletion	CHANGE PLANS MULTIPLE COMPLETION cted operations. (Clearly state k). SEE RULE 1103. For Mu	COMMENCE DRI CASING TEST AN CEMENT JOB OTHER: all pertinent details, and ltiple Completions: At	LLING OPNS. PLUG AND x ABANDONMENT ND I give pertinent dates, including estimated date
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comple of starting any proposed wor or recompletion 4/19/04: ND well head. NU BOP. P	CHANGE PLANS MULTIPLE COMPLETION eted operations. (Clearly state k). SEE RULE 1103. For Mu OH w/tbg. RU wireline & GII	COMMENCE DRI CASING TEST AN CEMENT JOB OTHER: all pertinent details, and Itiple Completions: At	LLING OPNS. PLUG AND x ABANDONMENT ND digive pertinent dates, including estimated date tach wellbore diagram of proposed completion
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comple of starting any proposed wor or recompletion 4/19/04: ND well head. NU BOP. P	CHANGE PLANS MULTIPLE COMPLETION eted operations. (Clearly state k). SEE RULE 1103. For Mu OH w/tbg. RU wireline & GII (48 jts) tbg ND BOP & well h	COMMENCE DRI CASING TEST AN CEMENT JOB OTHER: all pertinent details, and Itiple Completions: At	PLUG AND x ABANDONMENT If give pertinent dates, including estimated date tach wellbore diagram of proposed completion (2) 3700'. Cap w/35' of cmt. GIH w/tbg &
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or completion of starting any proposed work or recompletion 4/19/04: ND well head. NU BOP. P circ w/10# M.L.F. Pull & LD 2050' (csg 50' below shoes, could not pull csg	CHANGE PLANS MULTIPLE COMPLETION eted operations. (Clearly state k). SEE RULE 1103. For Mu OH w/tbg. RU wireline & GII (48 jts) tbg ND BOP & well h gg, not free @ 1994'. SDFN	COMMENCE DRI CASING TEST AN CEMENT JOB OTHER: all pertinent details, and Itiple Completions: At H w/5-12" CIBP & set (ead. Remove 5-1/2" cs	PLUG AND X ABANDONMENT If give pertinent dates, including estimated date tach wellbore diagram of proposed completion (2) 3700°. Cap w/35° of cmt. GIH w/tbg & g slips. Work csg. RU wireline & GIH cut
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or complet of starting any proposed wor or recompletion 4/19/04: ND well head. NU BOP. P circ w/10# M.L.F. Pull & LD 2050' (csg 50' below shoes, could not pull cs 4/20/04: RU wireline & GIH & cut 5	CHANGE PLANS MULTIPLE COMPLETION cted operations. (Clearly state k). SEE RULE 1103. For Mu OH w/tbg. RU wireline & GII (48 jts) tbg ND BOP & well h g, not free @ 1994'. SDFN -1/2" csg @ 1750'. PU & LD	COMMENCE DRI CASING TEST AN CEMENT JOB OTHER: all pertinent details, and ltiple Completions: Att H w/5-12" CIBP & set (ead. Remove 5-1/2" cs	ABANDONMENT In D In D
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or complet of starting any proposed work or recompletion 4/19/04: ND well head. NU BOP. Procirc w/10# M.L.F. Pull & LD 2050' (csg 50' below shoes, could not pull csd/20/04: RU wireline & GIH & cut 5-1560'. Spot 30 sxs cmt @ 970'. WO	CHANGE PLANS MULTIPLE COMPLETION cted operations. (Clearly state k). SEE RULE 1103. For Mu OH w/tbg. RU wireline & GII (48 jts) tbg ND BOP & well h g, not free @ 1994'. SDFN -1/2" csg @ 1750'. PU & LD C. Tag @ 864'. Mix & circ circ	COMMENCE DRI CASING TEST AN CEMENT JOB OTHER: all pertinent details, and ltiple Completions: Att H w/5-12" CIBP & set (ead. Remove 5-1/2" cs	ABANDONMENT In D In D
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or complet of starting any proposed work or recompletion 4/19/04: ND well head. NU BOP. Price w/10# M.L.F. Pull & LD 2050' (csg 50' below shoes, could not pull cst) 4/20/04: RU wireline & GIH & cut 5-1560'. Spot 30 sxs cmt @ 970'. WO 4/21/04: Surf plug @ surf. RD & model of the country of	CHANGE PLANS MULTIPLE COMPLETION eted operations. (Clearly state k). SEE RULE 1103. For Mu OH w/tbg. RU wireline & GII 48 jts) tbg ND BOP & well h g, not free @ 1994'. SDFN -1/2" csg @ 1750'. PU & LD C. Tag @ 864'. Mix & circ cove off location.	COMMENCE DRI CASING TEST AN CEMENT JOB OTHER: all pertinent details, and ltiple Completions: At H w/5-12" CIBP & set (ead. Remove 5-1/2" cs csg. GIH w/tbg to 204 mt to surf w/25 sxs cmt	ABANDONMENT If give pertinent dates, including estimated date tach wellbore diagram of proposed completion (2) 3700°. Cap w/35° of cmt. GIH w/tbg & g slips. Work csg. RU wireline & GIH cut 1°. Spot 80 sxs cmt. WOC. Tag TOC (2). WOC.
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or complet of starting any proposed work or recompletion 4/19/04: ND well head. NU BOP. Peirc w/10# M.L.F. Pull & LD 2050' (csg 50' below shoes, could not pull cs 4/20/04: RU wireline & GIH & cut 5/1560'. Spot 30 sxs cmt @ 970'. WO 4/21/04: Surf plug @ surf. RD & mod I hereby certify that the information page.	CHANGE PLANS MULTIPLE COMPLETION cted operations. (Clearly state k). SEE RULE 1103. For Mu OH w/tbg. RU wireline & GII (48 jts) tbg ND BOP & well h g, not free @ 1994'. SDFN -1/2" csg @ 1750'. PU & LD C. Tag @ 864'. Mix & circ cove off location. bove is true and complete to the	COMMENCE DRI CASING TEST AN CEMENT JOB OTHER: all pertinent details, and ltiple Completions: At H w/5-12" CIBP & set (ead. Remove 5-1/2" cs csg. GIH w/tbg to 204 mt to surf w/25 sxs cmt e best of my knowledge	ABANDONMENT If give pertinent dates, including estimated date tach wellbore diagram of proposed completion (2) 3700°. Cap w/35° of cmt. GIH w/tbg & g slips. Work csg. RU wireline & GIH cut 1°. Spot 80 sxs cmt. WOC. Tag TOC (2). WOC.
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or complet of starting any proposed work or recompletion 4/19/04: ND well head. NU BOP. Peirc w/10# M.L.F. Pull & LD 2050' (csg 50' below shoes, could not pull cs 4/20/04: RU wireline & GIH & cut 5/1560'. Spot 30 sxs cmt @ 970'. WO 4/21/04: Surf plug @ surf. RD & mod I hereby certify that the information page.	CHANGE PLANS MULTIPLE COMPLETION cted operations. (Clearly state k). SEE RULE 1103. For Mu OH w/tbg. RU wireline & GII (48 jts) tbg ND BOP & well h g, not free @ 1994'. SDFN -1/2" csg @ 1750'. PU & LD C. Tag @ 864'. Mix & circ cove off location. bove is true and complete to the	COMMENCE DRI CASING TEST AN CEMENT JOB OTHER: all pertinent details, and ltiple Completions: At H w/5-12" CIBP & set (ead. Remove 5-1/2" cs csg. GIH w/tbg to 204 mt to surf w/25 sxs cmt e best of my knowledge	ABANDONMENT If give pertinent dates, including estimated date tach wellbore diagram of proposed completion (2) 3700°. Cap w/35° of cmt. GIH w/tbg & g slips. Work csg. RU wireline & GIH cut 1°. Spot 80 sxs cmt. WOC. Tag TOC (2). WOC.
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or complet of starting any proposed work or recompletion 4/19/04: ND well head. NU BOP. Peirc w/10# M.L.F. Pull & LD 2050' (csg 50' below shoes, could not pull cstarting and the cut 5.1560'. Spot 30 sxs cmt @ 970'. WO 4/21/04: Surf plug @ surf. RD & mod I hereby certify that the information and grade tank has been/will be constructed by	CHANGE PLANS MULTIPLE COMPLETION cted operations. (Clearly state k). SEE RULE 1103. For Mu OH w/tbg. RU wireline & GII (48 jts) tbg ND BOP & well h g, not free @ 1994'. SDFN -1/2" csg @ 1750'. PU & LD C. Tag @ 864'. Mix & circ cove off location. bove is true and complete to the	COMMENCE DRI CASING TEST AN CEMENT JOB OTHER: all pertinent details, and ltiple Completions: At H w/5-12" CIBP & set (ead. Remove 5-1/2" cs csg. GIH w/tbg to 204 mt to surf w/25 sxs cmt e best of my knowledge les □, a general permit □	ABANDONMENT Id give pertinent dates, including estimated date tach wellbore diagram of proposed completion 3700'. Cap w/35' of cmt. GIH w/tbg & g slips. Work csg. RU wireline & GIH cut 1'. Spot 80 sxs cmt. WOC. Tag TOC @ WOC. e and belief. I further certify that any pit or belowor an (attached) alternative OCD-approved plan
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or complet of starting any proposed work or recompletion 4/19/04: ND well head. NU BOP. Peirc w/10# M.L.F. Pull & LD 2050' (csg 50' below shoes, could not pull cs 4/20/04: RU wireline & GIH & cut 5/1560'. Spot 30 sxs cmt @ 970'. WO 4/21/04: Surf plug @ surf. RD & mod I hereby certify that the information page.	MULTIPLE COMPLETION ceted operations. (Clearly state k). SEE RULE 1103. For Mu OH w/tbg. RU wireline & GII (48 jts) tbg ND BOP & well h sg, not free @ 1994'. SDFN -1/2" csg @ 1750'. PU & LD C. Tag @ 864'. Mix & circ cove off location. bove is true and complete to the losed according to NMOCD guideling.	COMMENCE DRI CASING TEST AN CEMENT JOB OTHER: all pertinent details, and ltiple Completions: At H w/5-12" CIBP & set (ead. Remove 5-1/2" cs csg. GIH w/tbg to 204 mt to surf w/25 sxs cmt e best of my knowledges he a general permit	ABANDONMENT Id give pertinent dates, including estimated date tach wellbore diagram of proposed completion 3700'. Cap w/35' of cmt. GIH w/tbg & g slips. Work csg. RU wireline & GIH cut 1'. Spot 80 sxs cmt. WOC. Tag TOC @ WOC. e and belief. I further certify that any pit or belowor an (attached) alternative OCD-approved plan
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or complet of starting any proposed work or recompletion 4/19/04: ND well head. NU BOP. Peirc w/10# M.L.F. Pull & LD 2050' (csg 50' below shoes, could not pull cstarting and starting any proposed work or recompletion 4/19/04: ND well head. NU BOP. Peirc w/10# M.L.F. Pull & LD 2050' (csg 50' below shoes, could not pull cstarting and starting and s	MULTIPLE COMPLETION cted operations. (Clearly state k). SEE RULE 1103. For Mu OH w/tbg. RU wireline & GII (48 jts) tbg ND BOP & well h (59, not free @ 1994'. SDFN -1/2" csg @ 1750'. PU & LD C. Tag @ 864'. Mix & circ cove off location. bove is true and complete to the losed according to NMOCD guideling.	COMMENCE DRI CASING TEST AN CEMENT JOB OTHER: all pertinent details, and ltiple Completions: At H w/5-12" CIBP & set (ead. Remove 5-1/2" cs csg. GIH w/tbg to 204 mt to surf w/25 sxs cmt e best of my knowledge les \(\), a general permit \(\) Regulatory Analyst	ABANDONMENT ABANDONMENT I give pertinent dates, including estimated date tach wellbore diagram of proposed completion 3700'. Cap w/35' of cmt. GIH w/tbg & g slips. Work csg. RU wireline & GIH cut 1'. Spot 80 sxs cmt. WOC. Tag TOC @ WOC. and belief. I further certify that any pit or belowor an (attached) alternative OCD-approved plan DATE 4/22/04.
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or complet of starting any proposed work or recompletion 4/19/04: ND well head. NU BOP. Peirc w/10# M.L.F. Pull & LD 2050' (csg 50' below shoes, could not pull cstarting and the cut 5.1560'. Spot 30 sxs cmt @ 970'. WO 4/21/04: Surf plug @ surf. RD & mod I hereby certify that the information and grade tank has been/will be constructed by	MULTIPLE COMPLETION cted operations. (Clearly state k). SEE RULE 1103. For Mu OH w/tbg. RU wireline & GII (48 jts) tbg ND BOP & well h (59, not free @ 1994'. SDFN -1/2" csg @ 1750'. PU & LD C. Tag @ 864'. Mix & circ cove off location. bove is true and complete to the losed according to NMOCD guideling.	COMMENCE DRI CASING TEST AN CEMENT JOB OTHER: all pertinent details, and ltiple Completions: At H w/5-12" CIBP & set (ead. Remove 5-1/2" cs csg. GIH w/tbg to 204 mt to surf w/25 sxs cmt e best of my knowledges he a general permit	ABANDONMENT Id give pertinent dates, including estimated date tach wellbore diagram of proposed completion 3700'. Cap w/35' of cmt. GIH w/tbg & g slips. Work csg. RU wireline & GIH cut 1'. Spot 80 sxs cmt. WOC. Tag TOC @ WOC. e and belief. I further certify that any pit or belowor an (attached) alternative OCD-approved plan
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comple of starting any proposed wor or recompletion 4/19/04: ND well head. NU BOP. P circ w/10# M.L.F. Pull & LD 2050' (csg 50' below shoes, could not pull cs 4/20/04: RU wireline & GIH & cut 5 1560'. Spot 30 sxs cmt @ 970'. WO 4/21/04: Surf plug @ surf. RD & mo I hereby certify that the information at grade tank has been/will be constructed by csignature. Type or print name DeeAnn Kemp	MULTIPLE COMPLETION cted operations. (Clearly state k). SEE RULE 1103. For Mu OH w/tbg. RU wireline & GII (48 jts) tbg ND BOP & well h (59, not free @ 1994'. SDFN -1/2" csg @ 1750'. PU & LD C. Tag @ 864'. Mix & circ cove off location. bove is true and complete to the losed according to NMOCD guideling.	COMMENCE DRI CASING TEST AN CEMENT JOB OTHER: all pertinent details, and ltiple Completions: At H w/5-12" CIBP & set (ead. Remove 5-1/2" cs csg. GIH w/tbg to 204 mt to surf w/25 sxs cmt e best of my knowledge les \(\), a general permit \(\) Regulatory Analyst	ABANDONMENT ABANDONMENT I give pertinent dates, including estimated date tach wellbore diagram of proposed completion 3700'. Cap w/35' of cmt. GIH w/tbg & g slips. Work csg. RU wireline & GIH cut 1'. Spot 80 sxs cmt. WOC. Tag TOC @ WOC. and belief. I further certify that any pit or belowor an (attached) alternative OCD-approved plan DATE 4/22/04 Telephone No. (432) 683-4816
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or complet of starting any proposed work or recompletion 4/19/04: ND well head. NU BOP. Peirc w/10# M.L.F. Pull & LD 2050' (csg 50' below shoes, could not pull cstarting and starting any proposed work or recompletion 4/19/04: ND well head. NU BOP. Peirc w/10# M.L.F. Pull & LD 2050' (csg 50' below shoes, could not pull cstarting and starting and s	MULTIPLE COMPLETION cted operations. (Clearly state k). SEE RULE 1103. For Mu OH w/tbg. RU wireline & GII (48 jts) tbg ND BOP & well h (59, not free @ 1994'. SDFN -1/2" csg @ 1750'. PU & LD C. Tag @ 864'. Mix & circ cove off location. bove is true and complete to the losed according to NMOCD guideling.	COMMENCE DRI CASING TEST AN CEMENT JOB OTHER: all pertinent details, and ltiple Completions: Att H w/5-12" CIBP & set (ead. Remove 5-1/2" cs csg. GIH w/tbg to 204 mt to surf w/25 sxs cmt e best of my knowledge les , a general permit Regulatory Analyst akemp@reimid.com	ABANDONMENT Date Plug And Abandonment
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or complet of starting any proposed work or recompletion 4/19/04: ND well head. NU BOP. Peirc w/10# M.L.F. Pull & LD 2050' (csg 50' below shoes, could not pull cstarting and starting any proposed work or recompletion 4/19/04: ND well head. NU BOP. Peirc w/10# M.L.F. Pull & LD 2050' (csg 50' below shoes, could not pull cstarting the cut 5 starting and starting any proposed work or recompletion 4/19/04: ND well head. NU BOP. Peirc w/10# & Cut 5 starting any proposed work or recompletion 4/19/04: ND well head. NU BOP. Peirc w/10# & Cut 5 starting any proposed work or recompletion 4/19/04: ND well head. NU BOP. Peirc w/10# & Cut 5 starting any proposed work or recompletion 4/19/04: ND well head. NU BOP. Peirc w/10# & Cut 5 starting any proposed work or recompletion 4/19/04: ND well head. NU BOP. Peirc w/10# & Cut 5 starting any proposed work or recompletion 4/19/04: ND well head. NU BOP. Peirc w/10# & Cut 5 starting any proposed work or recompletion 4/19/04: ND well head. NU BOP. Peirc w/10# & Cut 5 starting any proposed work or recompletion 4/19/04: ND well head. NU BOP. Peirc w/10# & Cut 5 starting any proposed work or recompletion 4/19/04: ND well head. NU BOP. Peirc w/10# & Cut 5 starting any proposed work or recompletion 4/19/04: ND well head. NU BOP. Peirc w/10# & Cut 5 starting any proposed work or recompletion 4/19/04: ND well head. NU BOP. Peirc w/10# & Cut 5 starting any proposed work or recompletion 4/19/04: ND well head. NU BOP. Peirc w/10# & Cut 5 starting any proposed work or recompletion 4/20/04: RU wireline & GIH & cut 5 starting any proposed work or recompletion 4/20/04: RU wireline & Cut 5 starting any proposed work or recompletion 5/19/04: ND well head. NU BOP. Peirc w/10# & Cut 5 starting any proposed work or recompletion 5/19/04: ND well head. NU BOP. Peirc w/10# & Cut 5 starting an	MULTIPLE COMPLETION eted operations. (Clearly state k). SEE RULE 1103. For Mu OH w/tbg. RU wireline & GII (48 jts) tbg ND BOP & well h sg, not free @ 1994'. SDFN -1/2" csg @ 1750'. PU & LD C. Tag @ 864'. Mix & circ cove off location. bove is true and complete to the losed according to NMOCD guideling. TITLE E-mail address: december 1995.	COMMENCE DRI CASING TEST AN CEMENT JOB OTHER: all pertinent details, and ltiple Completions: At H w/5-12" CIBP & set (ead. Remove 5-1/2" cs csg. GIH w/tbg to 204 mt to surf w/25 sxs cmt e best of my knowledge les \(\), a general permit \(\) Regulatory Analyst	ABANDONMENT D
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comple of starting any proposed wor or recompletion 4/19/04: ND well head. NU BOP. P circ w/10# M.L.F. Pull & LD 2050' (csg 50' below shoes, could not pull cs 4/20/04: RU wireline & GIH & cut 5 1560'. Spot 30 sxs cmt @ 970'. WO 4/21/04: Surf plug @ surf. RD & mo I hereby certify that the information at grade tank has been/will be constructed by csignature. Type or print name DeeAnn Kemp	MULTIPLE COMPLETION cted operations. (Clearly state k). SEE RULE 1103. For Mu OH w/tbg. RU wireline & GII (48 jts) tbg ND BOP & well h (59, not free @ 1994'. SDFN -1/2" csg @ 1750'. PU & LD C. Tag @ 864'. Mix & circ cove off location. bove is true and complete to the losed according to NMOCD guideling.	COMMENCE DRI CASING TEST AN CEMENT JOB OTHER: all pertinent details, and ltiple Completions: Att H w/5-12" CIBP & set (ead. Remove 5-1/2" cs csg. GIH w/tbg to 204 mt to surf w/25 sxs cmt e best of my knowledge les , a general permit Regulatory Analyst akemp@reimid.com	ABANDONMENT Date Plug And Abandonment