1		0	CD Artesia		
Form 3160-5 (April 2004)	Form 3160-5 UNITED STATES			FORM APPROVED OM B No. 1004-0137 Expires: March 31, 2007	
(the second s	DEPARTMENT OF TH BUREAU OF LAND MA			5. Lease Serial No.	: March 31, 2007
	RY NOTICES AND R			NMLC054980	
Do not use abandoned	this form for proposals well. Use Form 3160-3	s to drill or to re 8 (APD) for such p	-enter an roposals.	6. If Indian, Allotte	e or Tribe Name
	RIPLICATE- Other in	structions on reve	ərse sidə.	7. If Unit or CA/Ag	reement, Name and/or No.
I. Type of Well ↓ Oil Well □ □	Gas Well	r		8Well Name and	
2. Name of Operator Fair Oil, I	LTD			Fair 17 Feder 9. API Well No.	al #1
3a. Address PO Box 689, Tyler, Texas 7	5710	3b. Phone No. (inclu 903 592-3811	ide area code)	30-015-28969	
	ec., T., R., M., or Survey Description			10. Field and Pool, Cedar Lake; (or Exploratory Area Slorieta-Yeso
1792' FNL & 727' FWL, So	c 17-T17S-R31E, Unit E			11, County or Paris	n, State
<u></u>	·			Eddy Co., NM	
12. CHECK	APPROPRIATE BOX(ES) 1	TO INDICATE. NATU	TRE OF NOTICE,	REPORT, OR OTH	ER DATA
TYPE OF SUBMISSION			YRE OF ACTION		
Notice of Intent	Acidize	Deepen Fracture Treat	Production (S		ater Shut-Off ell Integrity
Subsequent Report	Casing Repair	New Construction	Recomplete	L	her
Final Abandonment Notice	Change Plans	Plug and Abandon	Temporarily A		
If the proposal is to deepen d Attach the Bond under whic following completion of the	leted Operation (clearly state all pe lirectionally or recomplete horizont h the work will be performed or pre involved operations. If the operation Final Abandonment Notices shall in ady for final inspection.)	tally, give subsurface locati ovide the Bond No. on file on results in a multiple con be filed only after all requir	stimated starting date of ions and measured and t with BLM/BIA. Requi upletion or recompletion rements, including reclar	any proposed work and a rue vertical depths of all red subsequent reports sl in a new interval, a Form nation, have been compl	pertinent markers and zones. Hall be filed within 30 days In 3160-4 shall be filed once
If the proposal is to deepen d Attach the Bond under whic following completion of the testing has been completed.	lirectionally or recomplete horizont h the work will be performed or pre- involved operations. If the operation Final Abandonment Notices shall in ady for final inspection.)	tally, give subsurface locati ovide the Bond No. on file on results in a multiple con be filed only after all requir	timated starting date of ions and measured and to with BLM/BIA, Requi pletion or recompletion	any proposed work and a rue vertical depths of all red subsequent reports sl in a new interval, a Form nation, have been compl	pertinent markers and zones. Hall be filed within 30 days In 3160-4 shall be filed once
If the proposal is to deepen d Attach the Bond under which following completion of the testing has been completed. determined that the site is read See attached, revised dr Install new 5-1/2" Will drill out plugs Run CBL and Casin Run a Casing Integ	lirectionally or recomplete horizond In the work will be performed or pre- involved operations. If the operation Final Abandonment Notices shall in ady for final inspection.) Illing:procedure: "Triser and 3K wellhead is and cleanout to appring Integrity Log and ev- grity Test to be witness	tally, give subsurface locati ovide the Bond No. on file on results in a multiple com be filed only after all requir Level 1 & 3K Manual BO oximately 6700 fe aluate and report s by a BLM PET (cl	timated starting date of ions and measured and to with BLM/BIA. Requina pletion or recompletion rements, including reclar and the start of the start of the start of the start NMOCD of for workover set is finding to BLM	any proposed work and a rue vertical depths of all red subsequent reports sl in a new interval, a Form nation, have been compl / 3 MMC Rig and no chok ASAP	ertinent markers and zones. hall be filed within 30 days h 3160-4 shall be filed once red, and the operator has
If the proposal is to deepen d Attach the Bond under which following completion of the testing has been completed. determined that the site is read See attached, revised dr Install new 5-1/2" Will drill out plugs Run CBL and Casin Run a Casing Integ SEE ATTAC CONDITION	lirectionally or recomplete horizond In the work will be performed or pre- involved operations. If the operation Final Abandonment Notices shall in ady for final inspection.) Integrity for final inspection.) Integrity construction ing Integrity Log and ev- grity Test to be witness INTED FOR IS OF APPROVA	tally, give subsurface locati ovide the Bond No. on file on results in a multiple com be filed only after all requir Level 1 & 3K Manual BO oximately 6700 fe aluate and report s by a BLM PET (cl	timated starting date of ions and measured and to with BLM/BIA. Requina pletion or recompletion rements, including reclar and the start of the start of the start of the start NMOCD of for workover set is finding to BLM	any proposed work and a rue vertical depths of all red subsequent reports si in a new interval, a Form nation, have been compl , 3 , 3 , C Rig and no choke ASAP to 700psig.	e manifold AUG 1
If the proposal is to deepen of Attach the Bond under which following completion of the testing has been completed, determined that the site is read See attached, revised dar Install new 5-1/2" Will drill out plugs Run CBL and Casin Run a Casing Inter SEE ATTAC CONDITION	lirectionally or recomplete horizond In the work will be performed or pre- involved operations. If the operation Final Abandonment Notices shall in ady for final inspection.) Integrity content in the operation integrity content in the operation integrity Log and every grity Test to be witness INTED FOR IS OF APPROVA	tally, give subsurface location ovide the Bond No. on file on results in a multiple com be filed only after all require all & 3K Manual BO oximately 6700 fe aluate and report s by a BLM PET (cl	timated starting date of ions and measured and to with BLM/BIA. Requina pletion or recompletion rements, including reclar and the start of the start of the start of the start NMOCD of for workover set is finding to BLM	any proposed work and a rue vertical depths of all red subsequent reports sl in a new interval, a Form nation, have been compl / 3 MMC Rig and no chok ASAP	e manifold AUG 1
If the proposal is to deepen d Attach the Bond under which following completion of the testing has been completed. determined that the site is read See attached, revised dr Install new 5-1/2" Will drill out plugs Run CBL and Casin Run a Casing Integ SEE ATTAC CONDITION	lirectionally or recomplete horizond In the work will be performed or pre- involved operations. If the operation Final Abandonment Notices shall in ady for final inspection.) Integrity content in the operation integrity content in the operation integrity Log and every grity Test to be witness INTED FOR IS OF APPROVA	ally, give subsurface locati ovide the Bond No. on file on results in a multiple com be filed only after all requir & C I & 3K Manual BO oximately 6700 fe aluate and report s by a BLM PET (cl L Title Date	timated starting date of ions and measured and the with BLM/BLA. Requi inpletion or recompletion rements, including rectar and the start of the start of the start of the start of the start of the start of the start of the start of the start of the star	ASAP to 700psig.	e manifold AUG 1
If the proposal is to deepen d Attach the Bond under which following completion of the testing has been completed. determined that the site is read See attached, revised dar Install new 5-1/2" Will drill out plugs Run CBL and Casin Run a Casing Integ SEE ATTAC CONDITION	lirectionally or recomplete horizond h the work will be performed or pre- involved operations. If the operation Final Abandonment Notices shall in ady for final inspection.) Illing-procedure: "Triser and 3K wellhead is and cleanout to appri- ing Integrity Log and ev- grity Test to be witness HED FOR IS OF APPROVA "regoing is true and correct M. M. M. THIS SPACE FOR attached. Approval of this notice al or equitable title to those rights	ally, give subsurface location of the Bond No. on file on results in a multiple combe filed only after all require and require and report aluate and report s by a BLM PET (clean combe file of the second se	timated starting date of ions and measured and the with BLM/BLA. Requi inpletion or recompletion rements, including rectar and the start of the start of the start of the start of the start of the start of the start of the start of the start of the star	ASAP to 700psig.	e manifold AUG 1
If the proposal is to deepen d Attach the Bond under which following completion of the testing has been completed. determined that the site is read See attached, revised dr Install new 5-1/2" Will drill out plugs Run CBL and Casin Run a Casing Integ SEE ATTAC CONDITION	lirectionally or recomplete horizond In the work will be performed or pre- involved operations. If the operation Final Abandonment Notices shall in ady for final inspection.) Illing-procedure: "Triser and 3K wellhead is and cleanout to appring Integrity Log and ev- grity Test to be witness HED FOR IS OF APPROVA regoing is true and correct THIS SPACE FOR I attached. Approval of this notice attached. Approval of this no	ally, give subsurface location of the Bond No. on file on results in a multiple combe filed only after all require the filed only after all require the filed only after all requires a solution of the filed only after all requires the solution of the filed only after all requires the solution of the filed only after all requires the solution of the filed only after all requires the solution of the filed only after all requires the solution of the filed only after all requires the solution of the filed only after all requires the solution of the filed only after all requires the solution of the filed only after all requires the solution of the filed only after all requires the solution of the filed only after all requires the solution of the	timated starting date of ions and measured and the with BLM/BLA. Requi- poletion or recompletion rements, including rectar and the start of the start and the start of the start and the start of the start and test and te	any proposed work and a rue vertical depths of all pred subsequent reports si in a new interval, a Form nation, have been complete , 3 Sound Rig and no choke ASAP to 700psig. Maleum Con 13 USE Date	e manifold RECE AUG 1 NMOCD A usultants (A DEDVED

CONDITIONS OF APPROVAL

Sundry dated August 9, 2013

OPERATOR'S NAME:	FAIR OIL, LTD
LEASE NO.:	LC054908
WELL NAME & NO.:	1-FAIR 17 FEDERAL
SURFACE HOLE FOOTAGE:	1792'/N. & 727'/W.
LOCATION:	Section 17, T. 17 S., R. 31 E., NMPM
COUNTY:	Eddy County, New Mexico

Original COA still applies with the following changes:

<u>Minimum</u> working pressure of the blowout preventer (BOP) and related equipment (BOPE) required for drilling below the surface casing shoe shall be **2000** (**2M**) psi. **Operator will test BOP as soon as it is installed and prior to drilling plug at 2600 feet.** (Operator to install a 3K wellhead & 3K Manual BOP for workover Rig and no choke manifold)

All blowout preventer (BOP) equipment shall comply with reasonable well control requirement and follow basic requirements in Onshore Order #2.

- 1. Operator to tag the plug set at approximately 6665 feet to verify and report results on a subsequent sundry; this plug was set on 02/28/2008.
- 2. Operator to run a CBL and Casing Integrity Log from approximately 6600 feet to surface; and submit to the BLM as soon as possible. (note if casing determined to be un-repairable all plans will change)
- 3. After setting proposed CIBP at 6300' and top off with 50 sx of cement and WOC and <u>before perforating</u>. Operator will be required to do a casing integrity test (CIT). The CIT will be witness by a BLM PET (charted) and test to 700psig. Report result to BLM Engineer and on a subsequent sundry. Pressure leak off may require corrective action prior to perforating in zone of interest.
- 4. All tests are required to be recorded on a calibrated test chart. A copy of the BOP/BOPE test chart and a copy of independent service company test will be submitted to the appropriate BLM office.
- 5. Submit a subsequent sundry and Form 3160-4 completion report within 30 days of the date all BLM approved procedures are complete.

EGF 080913

T & S PETROLEUM CONSULTANTS, INC.



9400 Highway 377 South Brookesmith, Texas 76827 325-646-3400 (Office) 325-646-3411 (Fax)

United States Department of the Interior Bureau of Land Management Oil Conservation Division 811 South First Street Artesia, NM 88210-2834


To whom it may Concern,

Please review and accept for record the attached 3160-5 Sundry Notice for Fair Oil, LTD-- Fair 17 Federal #1. Changes are being made to the drilling program because the reentry will stop short of any prior perforations as to not disturb the lower portion of the well; and the original schematic was done showing a full blown drilling rig, when in fact the work will be done with a work over/completions rig. The rig is set to move onto location as early as Tuesday, July 30, 2013. Your prompt attention to this matter will be greatly appreciated.

Sincerely,

Donnie Tibbitts Owner

FAIR OIL, LTD.



ĩ



Fair 17 Federal #1 1792' FNL & 727' FEL Lot E ,Sec. 17, T. 17 S., R. 31 E. Eddy County, New Mexico

8/9/13

Fair 17 Federal #1

SAFETY REQUIREMENTS

HOLD SAFETY MEETING BEFORE EVERY EVENT THAT OCCURS WHILE ON FAIR OIL, LTD. COMPAMY DRILL SITE.

BE SURE THAT WINDSOCK ON RIG IS IN PLACE AT ALL TIMES AND ALL PERSONEL ARE TRAINED IN H2S.

ALL PERSONNEL WILL WEAR HARD HATS, SAFETY GLASSES AND STEEL TOE BOOTS

NO SMOKING EXCEPT IN DESIGNATED AREAS

LOCATION INFORMATION

Lovington Highway 82 to County Road 221 Turn North on 221 for 1 mile to lease road on right. Pass Fair 18-1 location on right, **Fair 17 Federal #1** is located on right.

WELL OBJECTIVES

Basic Rig 35 will drill out cement plugs. TD of 6,730' and clean out hole to The permitted depth is 6,300'. (There is a 25 sack plug @ 6,730')

SPECIAL DRILLING CONSIDERATIONS

This well has been plugged since February 28, 2008. No perforations are open above 6,730'
This does not mean that proper well control should not be observed.
H2S is present in the area therefore H2S measures will be observed as well.
Make sure that rig is spotted over the hole properly. Make sure that all environmental
measures are completed and in full working order.

DRILLING CONSIDERATIONS

- 1. Set 6'X6' cellar.
- 2. Install new 5 ¹/₂" riser and 3 K Well head & 3 K manual B.O.P.
- 3. Pressure test Well head & B.O.P to 3,000 PSI for 20 min.
- 4. Rig up H2S equipment
- 5. Pick up 3 ¹/₂" bit & 4 3" Drill collars and Trip in hole, Cleaning out any cement or debris to 6,730'
- 6. Circulate hole Clean.
- 7. Trip out of the hole & pick up 5 1/2" Casing scraper & trip in to 6,730'
- 8. Circulate hole clean
- 9. Trip out of hole

10. Rig-up wire line unit & R.I.H W/ CIBP to 6,300' and set.

-11. Pull out of hole with wire line & pick up Casing integrity log and log from 6,300' to surface.

12. Once logs are interrupted T.I.H. open ended and spot 50 BBL cement on top of CIBP. (Note: BLM will need to witness setting of cement plug & said plug will need to be tested to 700 Psi.

see COA

- 13. Reverse out and clean string of all cement debris.
- 14. Displace hole with 2% KCL

SPP

- 15. Trip out & Pick up 5 ½ packer and test casing to 6,000 Psi. (If leak is found report to Fair & T&S Office immediately (Test will need to be charted & BLM will need to witness.
- 16. Trip out of hole laying down all tubular's.
- 17. Install 5 ½ Dry hole tree
- 18. Clean Pits & release drilling rig

CASING PROGRAM

Depth	Size	Weight	Grade	Tread	Torque
0-6,300'	5 ½"	17	P-110	LTC	Maximum 5780 Optimum 4620 Minimum 3470

Casing Collapse: 7,460 psi (NO SAFETY FACTOR) Casing Collapse: 6,112 psi (WITH SAFETY FACTOR 20%) Casing Burst: 12,640 psi (NO SAFETY FACTOR) Casing Burst: 10,112 psi (WITH SAFETY FACTOR 20%)



T-S Petroleum Consulting 600 Fisk, Suite 124 Brownwood, TX 76801

> Fair 17 Federal #1 Workover & Prep for Frac Recommendation

> > 1792' FNL & 727' FEL Lot E, Sec 17, T17S, R31E API: 30-015-39189 Eddy County, NM

For: Jay Bynum, Superintendent Fair Oil LTD P. O. Box 689 Tyler, TX 75710 (903) 592-3811 (903) 510-6525

July 24, 2013

Prepared by: Prentice Creel, PE T-S Petroleum Consulting IPhone: 432-770-2265 Home: 432-362-1101 <u>p.creel@t-sconsulting.com</u>

Safety Requirements:

Hold safety meetings before every event that occurs while on Fair Oil, LTD. Company Workover Well Site.

Insure that windsock on workover unit is in place at all times and all personnel are trained in H₂S Safety.

All personnel will wear Hard Hats, Safety Glasses, and Steel Toe Boots.

No Smoking except in designated areas.

Location Information:

East of Loco Hills, NM 3 miles to CO Rd 221. Turn North on Co Rd 221 for 1 mile to lease road on right. Pass Fair 18 Federal #1 &-#2 on right, South to Fair 17 Federal #1 on left

Workover Objectives:

Basic Rig 35 will drill out cement plugs set in well above the depth of 6,730'. TD the well at 6,730' and then clean out hole to the permitted depth of 6,300'. (NOTE: Currently there exists a 25 sack plug @ 6,730' to 6,850').

Special Drilling Considerations:

This well has been plugged since February 28, 2008.No perforations are open above 6,730'. This does not mean that proper well control should not be observed. H₂S is present in the area therefore H₂S measures will be observed. Make sure that workover unit is spotted over the hole properly, Make sure that all environmental measures are completed and in full working order. Full contained measures will be in place.

Drill-Out Considerations:

Set 6' X 6' cellar.

Install new 5-1/2" riser and 3K Well Head & 3K manual B.O.P.

Pressure test Well head & B.O.P. 3,000 psi for 20 mins.

Rig up H2S monitoring equipment. Placard and place H2S notices.

Mobilize workover pulling unit (Basic 35), reverse unit with reverse tank and swivel, frac tanks (10), and Blast tanks (2). Move-in 2-7/8" WS tubing, racks and cat walk. Load Fresh Water into frac tanks spotted on location.

Make arrangements for safety monitoring and PPE requirements. Make safety meetings standard.

RIH w/ 4-3/4" rock bit, four (4) 3-1/2" or (4) 4" Drill Collars, and 2-7/8" WS to drill out the plugs set at 0-60'. Ret & Sq @ 550-650', Plug @ 2500-2600', and Plug @ 4650-4750'.

Trip to the top of PBD of 6730'-6850' with bit to clean out hole. Clean out any cement or debris to a depth of 6,730'.

Trip out of hole. Pick up a 5-1/2'' scrapper and trip in to 6,730'.

Circulate clean with FW using kill truck or reverse unit.

Rig up Wireline unit and RIH with CIBP to 6300' and set. - See COA

Rig to run casing integrity log from 6,300' to surface. RIH w/ Casing Integrity Log with a CBL to 6300' and

determine casing integrity back to surface. The CIT will be witnessed by a BLM PET (charted) and test to 700 psig. A pressure leak off test is also required and if greater than allowable, repaired.

BOP W/ No Choke Mumi Fold.

Once logs are interpreted, TIH open ended and spot 50 sks (12 bbls) of Class C cement on top of CIBP @ 6,300' – WOC before perforating 24 hrs. **.Form 3160-4 is to be completed within 30 days and turned in to the BLM. (NOTE: BLM will need to witness setting of cement plug and said plug will need to be tested to 700 psi.**

Once hole circulated, load with treated 2% KCL water with scale inhibitor and clay stabilizer.

Pick up 5-1/2" packer and test casing to 6,000 psi. (If leak is found, report to Fair Oil & T&S Offices immediately.) Test will need to be charted & BLM will need to witness. Report To BLM - ASAP

Trip out of hole laying down all tubulars.

Install 5-1/2" Dry hole Tree. Rig up 7-1/16" 5M Frac valve & 10-02 4-way cross with 5-1/2" HP wireline connections on top after removing the BOP.

Clean Pits and release workover unit, reverse unit, & B.O.P.

RIH with WL and perforate the Lower Brinebry perfs. Once shot and guns checked for proper firing, TOH and prep for frac treatment on Lower Brinebry. Following intervals will be isolated by placing a Composite Plug above treated intervals and Perfing next interval to frac. Once all intervals fraced, - well will be prepped for drillout of composite plugs and rigged for recovery.

WL can be released if frac day is extended.

Well Data:

Field	Cedar Lake, Glorietta-Yeso
County	Eddy
State	NM
Frac Formations:	Lower Blinebry, Middle Blinebry, Upper Blinebry, & Paddock
Reference Pay	Yeso @ 4670'
КВ	16.5'
KB Elev	3736.5 (12')
Ground Level	3720'
BHT:	±101°F - 95°F
Drilled TD:	11,500 ft
PBTD	6,730 ft - 25 sk cmt plug down to 6850 ft
Casing Depth	11,492 ft
Casing Grade	M-95 & P-110
Casing Wt.	17#
TOC on 5-1/2"	2,500 ft inside 8-5/8" Intermediate set @ 4700 ft

Casing Information:

Casing String	Depth	PBT Depth	Size	Weight	Grade	Thread
Surface	600		13-3/8"	48#	H-40	STC
Intermediate	4700		8-5/8"	32#	J-55	
Production	11492	6730	5-1/2"	17#	M-95 & P- 110	LTC

Casing Strength		
Casing Collapse	7,460 psi	(No Safety Factor)
Casing Collapse	6,112 psi	With 20% Safety Factor
Casing Burst	12,640 psi	(No Safety Factor)
Casing Burst	10,112 psi	With 20% Safety Factor

Well plugged for abandonment:

8187-7950-: CIBP w/ 30 sks @ 8100'
Squeezed Perfs @ 8164-9261'
CIBP w/ 35 sks @ 8700'
Squeezed Perfs @ 8762-8797'
Squeezed Perfs @ 9031-9130'
CIBP w/ 35 sks @ 9620'
Squeezed Perfs @ 9643-9647'
CIBP w/ 35 sks @ 10500'
Squeezed Perfs @ 10537-10579'
DV @ 10664'
CIBP w/ cmt @ 10840'
Squeezed Perfs @ 10880-10887'
CIBP w/ cmt @ 11150'
Squeezed Perfs @ 11196-11199'
CIBP w/ cmt @ 11300'
Squeezed Perfs @ 11320-11333'

Plugs requiring drilling out:

1. Plug back w/ 40 sks from surface to 60' - having had 4 shots @ 60' made thru the Production & Intermediate casings – circulating 20 sks cement out both strings.

1

Re- Submit Sundry - A Plugging

- 2. Cement squeeze under ret @ 550' w/ perfs @ 650' 50 sks
- 3. Cement Plug back w/ 25 sks Class C 2500'-2600'
- 4. Cement Plug back w/ 25 sks Class C 4650'-4750'

Plug not requiring a drill-out:

- 5. Plug back w/ 25 sks 6730'-6850'. If plug leaks, it will be required to set a CIBP or Composite Plug.
- 6. [Will Not be drilled out] Cement Plug back w/ 25 sks Class C 6830 -6665'
- 7. [Will Not be drilled out] CIBP, Plugging Mud, & Cement Plug back w/ 30 sks Class C 8187 -7950'

Well Schematic:

۰.

•

		ı.	a .		
			i •		1 D @ 13331, w/ 60 sk bing back
			, 1 .	Haze	12121-12321 [200, bin8] e0 sks Cla
			1 1	1	
			: .		
			i i		
		t	; ·		OOSTI OI YSEQ BAIL
					the second se
		•	1 :	,	@ 195 DIT 0TI-0/56-W #/TZ/I-5
		1	EEETT-DEETT pajuad		,EEETT-0ZETT @ JJad pazaanbo
			{		
		ł		'	
			6TTTT-96TTT pəjuəd	WOLLOW :	.66TIT-96TIT @ sylad pataanbs
			1		CIBE M/ CUI @ 11120,
			78801-08801 bairag	EX01A	2801-108801 @ 10880-10882
			1		CIBb w/ cut @ 10840.
					φ 10Λ @ 109901
		1	64201-75201 beined	uwents	.62201-7521 @ 2019 Paraenp2
		1		1	CIBb M\ 32 242 @ 10200.
		1		•	
		}	748-E488 being	, novne)	Squeezed Perts @ 9643-9647
		1	1	1	
		[CIBb M\ 32 5K2 @ 30200,
			0519-150		2dneeseq beile @ 9031-9130
	•	[7978-5978 betred	Cisco	Squeezed Perfs @ 8762-8797
				F	00/8 @ 8145 SE /M 3810
		l	.	1	
	:		6528-9218 behad	qmsottoW	
	:			1	,2818-0562 @ \$48 SE (M 391)
		1		1	
				1	
				į	
				i	
	i	ł		į	
	ł				╏ ┟ ┟ ╞┟╬╠╄┽╞╬┼╡╸┊ ┟ ╺
	}	}	↓	i -	
	F			ł	bing back w/ 25 sks 6730.6850
	F			mottod	┼╍╍┽╷╷╎╎╎ ╎╷ ┥┽┽╢┊┥┥┝╴╵┝╴╵┝╴
			2809 0985 0895		In the second se
	ŀ	1	0985 0895]**	┲╦┉┲┉┉┧╺╴╴┥╴╴┝╼┠╶┨╠╍┠┝━ <u>┣</u> ╣┞╼╏╺╴╶╺┥╶╴╺┥╶╴╴
	• •	· ·		ł ·	┧╸╸┧╴╶╎╶╎╎╢╍┥╊╾╠╚╦┝╴╶┝╶╶┤
	1		0795 0005	λ <i>i</i> σai	Middle Brin
			0003]	
•	i .		0205	top	
			0785 0505		Upper Brine
	j.				하는 사람 가 가 나는 물건을 많은 것을 수 있는 것을 수 있다. 것을 것 같이 같이 것 같이 않는 것 않는 것 같이 않는 것 않는 것 같이 않는 것 같이 않는 것 않는
			5897	dos	
		t	0864 0074	İ i	baddock
			1 1	1	
	I .	I · · ·	F. 1 T	Γ	0520-0520 515 52 /M 320 801d
	1 .		D 05	ร์ + วาห ฑร อ	56T
	1			I	
	ľ.		r • • •	}	
	Γ		F	1	
,26711	211	011-9 & 26M	#/1 "2/1-5]	ber TS
4100.		085 % 55-1	#ZE "8/S-8		10092-0052 51/5
009	STC	01/-H	#878/E-EI]	
	1	1		[]	
-5288	0189	0069	Total Depth		
59EZ ·	2809	2209	ddul		
1348	0205	0905	Blinebry		
£96-			Paddack (,059-,b7E 343 0/ /M 328 9/ 6 9/ 6 9/ 6 9/ 6 9/ 6 9/ 6 9/ 6 9/
	5892	\$297			
856-	0897	0297	əşirbydrike	STT + DTH	11-1/5, 11-1/5, 13-3/8, 48H H-40 2LC @ 000, - 320
856- 588-	0897 2557	0297 4243	Glorieta ·	STT + DTH	
856+ 588- 609	0897 2557 EIIE	0297 4242 103	San Andres Gorieta	STT+DTH	
856- 5E8- 609 8E6	0897 2557 EILE 75284	4670 4547 3103 2774	Grayburg San Andres Gorieta		
856- 5E8- 609 8E6 20ET	0897 2557 EILE 7822 SIV2	0297 2727 5103 7272 2402	Guéen Grayburg San Andres Gorieta		Shed (59 of b5 93 05,055)
856- 528- 609 826 1301 1301	0897 2555 EILE 7822 SIP2 1081	0297 2727 EDIE 7227 SOP2 IGZI	Seven Rivers Seven Rivers Grayburg San Andres Gorieta		shed (59 of bs 11 05 (055 (24))
856- 5E8- 609 8E6 20E1 1Z61 6EZZ	0897 2557 EILE 7822 SIVZ E081 E871	0297 2757 EDIE 7227 SOP2 IG21 E271	vaites Seven Aivers Grayburg San Andres Glorieta		shed (59 of bs 11 05 (055 (24))
856- 528- 609 826 2051 1261 1261 1261 2533	0897 2557 EILE 7822 S172 E871 S821	0297 2725 2015 2015 2072 2072 1621 2271 2271	oberez mojod zavén filvers zavén filvers savén filvers sav		
856- 5E8- 609 8E6 20E1 1261 6E22 2E92 261E	0897 2557 EILE 7822 SIF2 E871 S821 S821 0ES	0297 2757 EDIE 7227 SOF2 IG21 E271 S221 OZS	Glorieta Saredo salt top Saren Andres Saren		shed (59 of bs 11 05 (055 (24))
856- 5E8- 609 8E6 20E1 1261 6E22 261E 261E 2261E	0897 2557 EILE 7822 5172 1081 E871 5821 0ES 575	0297 2257 EDIE 7227 SOF2 IG21 E271 S221 OZS SEE	Giorieta Sando salt top Sando salt top Sando salt top Sando Salt top Sando Salt top Sando Salt top Sando Salt top Salt Salt Salt top Salt Salt Salt Salt Salt Salt Salt Salt Salt Salt Salt Salt Salt Salt Salt		5,144,59 0,155 355 5
856- 5E8- 609 8E6 20E1 1761 6E22 2615 2615 2615 2225 2615 2225 2615 2225	0897 2557 EILE 7822 5172 1081 E871 5821 0ES 575 01	0297 2757 EDIE 7227 SOV2 IG21 E277 S227 OZS SEE 0	briet remer y som briet for any som gen for all to all the source of all to all the source of all the		5, Jaid (59 of 165 31 55, 055)
856- 5E8- 609 8E6 20E1 1761 6E22 2615 2615 2615 2225 2615 2225 2615 2225	0897 2557 EILE 7822 5172 1081 E871 5821 0ES 575 01	0297 2257 EDIE 7227 SOF2 IG21 E271 S221 OZS SEE	Giorieta Sando salt top Sando salt top Sando salt top Sando Salt top Sando Salt top Sando Salt top Sando Salt top Salt Salt Salt top Salt Salt Salt Salt Salt Salt Salt Salt Salt Salt Salt Salt Salt Salt Salt		5,144,59 0,155 355 5
856- 5E8- 609 8E6 20E1 1261 6E22 261E 261E 225	0897 2557 EILE 7822 5172 1081 E871 5821 0ES 575 01	0297 2757 EDIE 7227 SOV2 IG21 E277 S227 OZS SEE 0	briet remer y som briet for any som gen for all to all the source of all to all the source of all the		5/#d (59 of b\$ 13 05,055
856- 5E8- 609 8E6 20E1 1261 6E22 2612 2612 2612 2612 2212E	0897 2557 EILE 7822 5172 1081 E871 5821 0ES 575 01	0297 2257 EDIE 7227 SOV2 IG21 E271 S221 OZS SEE 0	Citybure Citybu		5 1940 (59 0) 05 13 05 (055) 5 1 2 2 2 2 0 0 15 13 05 (055) 5 1 2 2 2 2 0 0 15 13 05 (055) 5 1 2 2 2 2 0 0 15 13 05 (055) 5 1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2
856- 5E8- 609 8E6 20E1 1261 6E22 2612 2612 2612 2612 2212E	0897 2557 EILE 7822 5172 1081 E871 5821 0ES 575 01	0297 2257 EDIE 7227 SOV2 IG21 E271 S221 OZS SEE 0	Citybure Citybu		د بال المراجع ا المراجع المراجع br>مراجع المراجع ال مراجع المراجع المراح مراجع المراجع المراجع المراجع المراجع المراجع المرا
856- 5E8- 609 8E6 20E1 1261 1261 6E22 2532 261E 2725 261E 2725 261E	0897 2557 EILE 7822 5172 1081 E871 5821 0ES 575 01	0297 2257 EDIE 7227 SOV2 IG21 E271 S221 OZS SEE 0	Citybure Citybu		i i
856- 5E8- 609 8E6 20E1 1261 1261 6E22 2532 6E22 261E 2725 261E 2725 261E	0897 2557 EILE 7822 5172 1081 E871 5821 0ES 575 01	0297 2257 EDIE 7227 SOV2 IG21 E271 S221 OZS SEE 0	Citybure Citybu		51/ad 59 ol bs 19 05,055 3 51/ad 59 ol bs 19 05,055 3 1 59 ol bs 100,055 100,052 1 100,052 100,052
856- 5E8- 609 8E6 20E1 1261 6E22 2612 2612 2612 2612 2212E	0897 2557 EILE 7822 5172 1081 E871 5821 0ES 575 01	0297 2257 EDIE 7227 SOV2 IG21 E271 S221 OZS SEE 0	Citybure Citybu		strad 59 of bs 33 05,055 5 5 strad 0.92,034 05 0.92 of bs 34 05 5 strad 0.92,034 05 1.642 5 strad 1.5962/5 1.642 1.5962/5 strad 1.5962/5 1.642 1.5962/5 strad 1.5962/5 1.642 1.797 strad 1.5962/5 1.642 1.797 strad 1.5962/5 1.642 1.797 strad 1.591 1.642 1.797 strad 1.592/2 1.797 1.797 strad 1.642 1.797 1.797 strad 1.797 1.797 1.797 strad 1.797 1.797 1.797 strad 1.642 1.797 1.797 strad 1.797 1.797 1.797 strad 1.797 1.797 1.797
856- 5E8- 609 8E6 20E1 1261 1261 6E22 2532 6E22 261E 2725 261E 2725 261E	0897 2557 EILE 7822 5172 1081 E871 5821 0ES 575 01	0297 2257 EDIE 7227 SOV2 IG21 E271 S221 OZS SEE 0	Citybure Citybu		51/ad 59 ol bs 19 05,055 3 51/ad 59 ol bs 19 05,055 3 1 59 ol bs 100,055 100,052 1 100,052 100,052

.

•

Planned Perforations for Frac:

٠

J

• •


Zone	Upper pay	Lower Pay	SPF	Orientation	Size
Lower Brinebry	5680	5860	48	60º	0.42
Middle Brinebry	5400	5620	56	60º	0.42
Upper Brinebry	5050	5340	72	60º	0.42
Paddock	4700	4980	72	60º	0.42

.

Fair Oil, LTD. Fair 17 Fed #1 1792' FNL & 727' FWL Sec. 17, T. 17 S, R. 31 E. Eddy County, New Mexico



North



Topsoil

Entrance

CONDITIONS OF APPROVAL

Sundry dated August 9, 2013

OPERATOR'S NAME:	FAIR OIL, LTD
LEASE NO.:	LC054908
WELL NAME & NO.:	1-FAIR 17 FEDERAL
SURFACE HOLE FOOTAGE:	1792'/N. & 727'/W.
LOCATION:	Section 17, T. 17 S., R. 31 E., NMPM
COUNTY:	Eddy County, New Mexico

Original COA still applies with the following changes:

<u>Minimum</u> working pressure of the blowout preventer (BOP) and related equipment (BOPE) required for drilling below the surface casing shoe shall be **2000** (**2M**) psi. **Operator will test BOP as soon as it is installed and prior to drilling plug at 2600 feet.** (Operator to install a 3K wellhead & 3K Manual BOP for workover Rig and no choke manifold)

All blowout preventer (BOP) equipment shall comply with reasonable well control requirement and follow basic requirements in Onshore Order #2.

- 1. Operator to tag the plug set at approximately 6665 feet to verify and report results on a subsequent sundry; this plug was set on 02/28/2008.
- 2. Operator to run a CBL and Casing Integrity Log from approximately 6600 feet to surface; and submit to the BLM as soon as possible. (note if casing determined to be un-repairable all plans will change)
- 3. After setting proposed CIBP at 6300' and top off with 50 sx of cement and WOC and <u>before perforating</u>. Operator will be required to do a casing integrity test (CIT). The CIT will be witness by a BLM PET (charted) and test to 700psig. Report result to BLM Engineer and on a subsequent sundry. Pressure leak off may require corrective action prior to perforating in zone of interest.
- 4. All tests are required to be recorded on a calibrated test chart. A copy of the BOP/BOPE test chart and a copy of independent service company test will be submitted to the appropriate BLM office.
- 5. Submit a subsequent sundry and Form 3160-4 completion report within 30 days of the date all BLM approved procedures are complete.

EGF 080913