Submit 1 Copy To Appropriate District State of New Mexico	Form C-103
Office District I – (575) 393-6161 Energy, Minerals and Natural Resources	Revised August 1, 2011
1625 N. French Dr., Hobbs, NM 88240	WELL API NO.
District II – (575) 748-1283 811 S. First St. Artesia, NM 88210 OIL CONSERVATION DIVISION	30-015-39650
611 5. 1 list St., Artesia, 144 602 (0	5. Indicate Type of Lease
District III - (505) 334-6178 1220 South St. Francis Dr. 1000 Rio Brazos Rd., Aztec, NM 87410	STATE STATE FEE
District IV – (505) 476-3460 Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM	
87505	
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	LONE TREE DRAW 13 STATE COM
1. Type of Well: Oil Well Gas Well Other	8. Well Number 1H
2. Name of Operator	9. OGRID Number
Devon Energy Production Company, LP	6137
3. Address of Operator	10. Pool name or Wildcat
<u> </u>	1
333 W. Sheridan Avenue, Oklahoma City, OK 73102	FENTON; DELAWARE, NORTHWEST
4. Well Location	1
Unit Letter_L : 400 feet from the North line and	355 feet from the West line
Section 13 Township 21S Range 27E	NMPM Eddy, County, NM
11. Elevation (Show whether DR, RKB, RT, GR 3195' GL	, etc.)
	() should be said the said to
12. Check Appropriate Box to Indicate Nature of Not	ice Report or Other Data
NOTICE OF INTENTION TO:	Hinro.state.nm.us OF: Ins are available on our Ins are available on our Ins CASING Ins CASING Ins CASING Ins CASING Ins CASING Ins CASING Ins CASING Ins CASING Ins CASING
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒	ns are available on one of the new are available on the new
TEMPORARILY ABANDON CHANGE PLANS Current for	should be used Wills
PULL OR ALTER CASING MULTIPLE COMPL website an	d show documents.
DOWNHOLE COMMINGLE filing re	d should be used gulatory documents.
DOWINHOLE COMMININGLE	
OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent detail	s, and give pertinent dates, including estimated date
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multipl	
proposed completion or recompletion.	c completions. Thursday wendere diagram of
proposed compression of recompletion.	
Plug and abandon 104' hole drilled by spudder rig (Butches Rat Hole Services)	_
, , , , , , , , , , , , , , , , , , ,	
	RECO
1. MIRU. TIH w/2-7/8" tubing and tag bottom.	RECEIVED
v	RECEIVED
2. Spot cement from 125' to surface.	RECEIVED AUG 3 0 2012
2. Spot cement from 125' to surface.	RECEIVED AUG 3 0 2013
2. Spot cement from 125' to surface.	RECEIVED AUG 3 0 2013 NMOCD ARTS
2. Spot cement from 125' to surface.	RECEIVED AUG 3 0 2013 NMOCD ARTESIA
2. Spot cement from 125' to surface.	MECEIVED
2. Spot cement from 125' to surface.	RECEIVED AUG 3 0 2013 NMOCD ARTESIA
 Spot cement from 125' to surface. Cut conductor 3' below ground level. Top out with cement & set dry hole ma 	RECEIVED AUG 3 0 2013 NMOCD ARTESIA
2. Spot cement from 125' to surface.	RECEIVED AUG 3 0 2013 NMOCD ARTESIA
 Spot cement from 125' to surface. Cut conductor 3' below ground level. Top out with cement & set dry hole ma 	RECEIVED AUG 3 0 2013 NMOCD ARTESIA
2. Spot cement from 125' to surface. 3. Cut conductor 3' below ground level. Top out with cement & set dry hole mass. Spud Date: Rig Release Date:	
 Spot cement from 125' to surface. Cut conductor 3' below ground level. Top out with cement & set dry hole ma 	
2. Spot cement from 125' to surface. 3. Cut conductor 3' below ground level. Top out with cement & set dry hole mass. Spud Date: Rig Release Date: I hereby certify that the information above is true and complete to the best of my known.	
2. Spot cement from 125' to surface. 3. Cut conductor 3' below ground level. Top out with cement & set dry hole mass. Spud Date: Rig Release Date: I hereby certify that the information above is true and complete to the best of my known.	vledge and belief.
2. Spot cement from 125' to surface. 3. Cut conductor 3' below ground level. Top out with cement & set dry hole mass. Spud Date: Rig Release Date: I hereby certify that the information above is true and complete to the best of my known.	vledge and belief.
2. Spot cement from 125' to surface. 3. Cut conductor 3' below ground level. Top out with cement & set dry hole mass. Spud Date: Rig Release Date: I hereby certify that the information above is true and complete to the best of my known SIGNATURE ROBERT STATE Operations Technical States.	viedge and belief. ianDATE8/29//3
2. Spot cement from 125' to surface. 3. Cut conductor 3' below ground level. Top out with cement & set dry hole mass. Spud Date: Rig Release Date: I hereby certify that the information above is true and complete to the best of my known.	viedge and belief. ianDATE8/29//3
2. Spot cement from 125' to surface. 3. Cut conductor 3' below ground level. Top out with cement & set dry hole mass. Spud Date: Rig Release Date: I hereby certify that the information above is true and complete to the best of my known SIGNATURE ROPE STATE Operations Technical E-mail address: Ronnie Slack For State Use Only	viedge and belief. plate 8/29//3 Pdvn.com PHONE: _405-552-4615
2. Spot cement from 125' to surface. 3. Cut conductor 3' below ground level. Top out with cement & set dry hole mass. Spud Date: Rig Release Date: I hereby certify that the information above is true and complete to the best of my known SIGNATURE ROPE STATE Operations Technical E-mail address: Ronnie Slack For State Use Only	viedge and belief. ianDATE8/29//3



