



Submit 1 Copy To Appropriate District Office	State of New Mexico		Form C-103		
<u>District 1</u> – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natural Resources		Revised July 18, 2013 WELL API NO.		
District II – (575) 748-1283	OIL CONSERVATION DIVISION		30-015-27448		
811 S. First St., Artesia, NM 88210 District III - (505) 334-6178			5. Indicate Type of Lease	e	
1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.		STATE S FEE		
District IV – (505) 476-3460 / 1220 S. St. Francis Dr., Santa Fe, NM 87505 4	Santa Fe, NM 87505		6. State Oil & Gas Lease No. VB-414		
SUNDRY NOT (DO NOT USE THIS FORM FOR PROPE	CICES AND REPORTS ON WELLS OSALS TO DRILL OR TO DEEPEN OR PL	UG BACK TO A	7. Lease Name or Unit A Beauregard ANM State		
PROPOSALS.) 1. Type of Well: Oil Well	ICATION FOR PERMIT" (FORM C-101) F Gas Well Other	OR SUCH	8. Well Number		
2. Name of Operator			9. OGRID Number		
Yates Petroleum Corporation 3. Address of Operator			025575 10. Pool name or Wildcat		
105 South Fourth Street, Artesia,	NM 88210		Red Lake; Atoka-Morrov	t e	
4. Well Location Unit Letter L :	1980 feet from the Sout	h line and	660 feet from the	West line	
Section 14		ange 27E		County	
	11. Elevation (Show whether Di	R, <i>RKB, RT, GR, etc.,</i> 5'GR			
12 Chl-	A	CNI-4	D. O.I. D.		
V	Appropriate Box to Indicate 1		•		
NOTICE OF I PERFORM REMEDIAL WORK	NTENTION TO:] PLUG AND ABANDON ⊠		SEQUENT REPORT CONDITIONS OF APPRO		
TEMPORARILY ABANDON	<u> </u>	COMMENCE DR			
PULL OR ALTER CASING DOWNHOLE COMMINGLE	-	CASING/CEMEN	Approval Granted pro	viding work is	
DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM			Completed by	אוו זמוו/	
OTHER:		OTHER:	•	11,2014	
	npleted operations. (Clearly state all				
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.					
Yates Petroleum Corporation plans to plug and abandon this well as follows:					
1. Procedure assumes all equipment is already RU at the well site and all the safety equipment necessary to complete the job is in place. 2. Set a retainer at 3550° inside 7° casing, sting into the retainer and pressure up on the 2-7/8° x 7° annulus to 1000 psi. Displace the tubing with fresh					
water. Displace the 7" x 9-5/8" annulus with fresh water.					
3. Tie on to the 9-5/8" x 7" annulus and pump 1100 sx Class "C" cement while monitoring the tubing pressure. Then shut in the 9-5/8" and move to the tubing, pump 500 sx down the 2-7/8" tubing and displace it to the retainer. Sting out of the retainer and reverse circulate clean. WOC.					
4. Pull CBL to find TOC.					
5. Set a 25 sx cement plug on top of retainer. If necessary perforate and place cement inside and outside 7" casing. 6. Set a 150' cement plug across 9-5/8" shoe from 2090'-2240' and if necessary perforate and place cement inside and outside 7" casing. WOC and tag					
plug, reset if necessary. 7. Set a 150° cement plug across 13-3/8" shoe from 270'-420' and if necessary perforate and place cement inside and outside 7" casing. WOC and tag					
7. Set a 150° cement plug across 13-3 plug, reset if necessary.	/8" shoe from 270'-420' and if necessar	y perforate and place c	ement inside and outside 7" c	asing. WOC and tag	
8. Set a 150' cement plug at surface f	rom 0-150' and if necessary perforate ar	nd place cement inside			
necessary. 9. Remove all surface equipment and	weld dry hole marker per regulations.	Approved for plugging	of well bore only.	CEIVED	
		tightly was bond is	retained petiding receipt	EP 1 0 2013	
Spud Date:	Rig Release I	I which may be found at	OCD Web Page under		
		Forms, www.cmnrd.sta		CD ARTESIA	
I hereby certify that the information	on above is true and complete to the	best of my knowleds	ge and belief.		
. 1					
SIGNATURE (TITLE RE	gulatory Reporting S	Supervisor DATE <u>Sep</u>	tember 9, 2013	
Type or print name Tina F	luerta E-mail address:	tinah@yatespetroleu	ım.com PHONE:	575-748-4168	
For State Use Only					
APPROVED BY: 1 (If any): TITLE 1) SEA CIPCOST DATE 9/11/2013 Conditions of Approval (if any):					
See Attached COA's					
Dee HIMENER					









NEW MEXICO OIL CONSERVATION DIVISION DISTRICT 2 OFFICE 811 S. FIRST STREET ARTESIA, NM 88210 (575)748-1283

CONDITIONS OF APPROVAL FOR PLUGGING & ABANDONMENT

Operator: Vates Actroleum		
Well Name & Number: Beausegard	ANM State Com	1
API #: 30-015-27448		

- 1. Produced water <u>will not</u> be used during any part of the plugging & abandonment operation.
- 2. Notify NMOCD Dist. 2 office at least 24 hrs before beginning work.
- 3. Closed Loop System is to be used for entire plugging operation. Upon completion, contents of steel pit are to be hauled to a permitted disposal location.
- 4. Trucking companies being used to haul oilfield waste fluids to a disposal commercial or private shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator, as well as the contractor, to verify that this permit is place prior to performing work. Drivers shall produce a copy upon request of NMOCD Field Inspectors.
- 5. A subsequent C-103 will serve as notification that the well bore has been plugged ONLY. A C-103 FINAL shall be filed before any bonding can be released on the well. Upon receipt of the Final, an inspection will be performed to verify that the location has been satisfactorily cleaned to NMOCD standards.
- **6.** If work has not begun within 90 days of the approval of this procedure, an extension request must be filed, stating reason that well has not been plugged.
- 7. Every attempt must be made to clean the well bore out to below the perfs, before any plugs can be set, by whatever means possible.
- 8. Cement Retainers may not be used.

- 9. Squeeze pressures are not to exceed 500 PSI, unless approval is given by NMOCD.
- 10. Plugs may be combined after consulting with and getting approval from NMOCD.
- 11. Minimum WOC time for tag plugs will be 4 Hrs.

DATE: Sept 11,2013

APPROVED BY: APPROVED

GUIDELINES FOR PLUGGING AND ABANDONMENT

DISTRICT II / ARTESIA

- All cement plugs will be a minimum of 100' in length or a minimum of 25 sacks of cement, whichever is greater.
- Mud laden fluids must be placed between all cement plugs.
- Mud laden fluids must be mixed at 25 sacks of gel per 100 bbls of water.
- A cement plug is required to be set 50' below and 50' above all casing shoes and casing stub
 plugs. These plugs must be tagged.
- A CIBP with 35' of cement on top may be set in lieu of 100' cement plug.
- A plug as indicated above must be placed within 100' of top perforation. This plug must be tagged.
- Plugs set below and above salt zones must be tagged.
- No more than 2000' is to be allowed between cement plugs in open hole and no more than 3000' in cased hole.
- DV tools are required to have a 100' cement plug set 50' above and below the tool and must be tagged.
- Formations to be isolated with plugs placed at the top of each formation are:
 - o Fusselman
 - o Devonian
 - o Morrow
 - o Wolfcamp
 - o Bone Spring
 - o Delaware
 - Any Salt Section (Plug at top and bottom)
 - o Abo
 - o Glorieta
 - Yates (this plus is usually at base of salt section)
- If cement does not exist behind casing strings at recommended formation depths, the casing
 must be cut and pulled with plugs set at these depths or casing must be perforated and cement
 squeezed behind casing at the formation depths.
- In the R-111-P area (Potash Mine area) a solid cement plug must be set across the salt section. Fluid used to mix the cement shall be saturated with the salts common to the section penetrated and in suitable proportions, but not more than a 3% calcium chloride by weight of cement will be considered the desired mixture whenever possible (50' below and 50' above).