

RECEIVED

VOV **3 o** 2011

NMOCD ARTESIA

October 20, 2011

Ms. Jennifer Van Curen Bureau of Land Management 620 E. Green Street Carlsbad, NM 88220

AMARILLO 92I North Bivins Amarillo. Texas 79107 Phone 806.467.0607 Fax 806.467.0622

ARTESIA

408 West Texas Ave. Artesia, New Mexico 88210 Phone 575.746.8768 Fax 575.746.8905

AUSTIN

9li West Anderson Lane Suite 202 Austin, Texas 78757 Phone 5l2.989.3428 Fax 5l2.989.3487

HOBBS 3/8 East Taylor Street Hobbs, New Mexico 88240 Phone 575.393.426/ Fax 575.393.4658

> MIDLAND 290I State Hwy 349

2901 State Hwy 349 Midland, Texas 79706 Phone 432.522.2133 Fax 432.522.2180

SAN ANTONIO

II Commercial Place Schertz, Texas 78154 Phone 210.265.8025 Fax 210.568.2191

TULSA 525 South Main Street Suite 535

Tulsa, Oklahoma 74103 Phone 918.742.0871 Fax 918.382.0232

ENVIRONMENTAL CONSULTING ENGINEERING

DRILLING CONSTRUCTION SPILL MANAGEMENT GENERAL CONTRACTING Subject:

Soil Assessment and Remediation Work Plan

Cimerax Energy Corporation

Callaway Federal #2 Drilling Pit Remediation

API # 30-015-23486

Dear Ms. Van Curen,

Cimerax Energy has contracted Talon/LPE (Talon) to perform soil assessment and remediation services at the referenced Callaway Federal #2 location. Our soil sampling results and proposed remediation activities consists of the following:

Incident Date

May 18, 2011

Background Information

The Callaway Federal #2 is located approximately twenty (20) miles northeast of Artesia, New Mexico. The legal location for the site is Section 6, Township 16 South and Range 28 East in Eddy County, New Mexico. More Specifically the latitude and longitude for the release are 32.95813 North and -104.21215 West.

According to the soil survey provided by the United States Department of Agriculture National Resources Conservation Services, the soil in this area is made up of Reeves-Gypsum land complex soils with 0 to 3 percent slopes. The local surface and shallow geology, Quaternary Age sedimentary deposits, is comprised of alluvium and eolian sands which includes silty soils under lain by gypsum and hard caliches. Drainage courses in this area are normally dry. The New Mexico State Engineer web site indicates the nearest ground water data to be in S34-T15S-R27E. The ground water in Section 34 is reported to be at depth of 85' below ground surface (bgs). The referenced groundwater data is presented in Appendix I.

The ranking for this site is 10 based on the as following:

Depth to ground water 50'-100'
Wellhead Protection Area >1000'
Distance to surface water body >1000'

Toll Free: 866.742.0742 www.talonlpe.com

Incident Description

On May 18, 2011 the Bureau of Land Management notified Cimarex Energy Corporation regarding the drilling pit at the Callaway Federal #2, requesting a work plan for the restoration of the non-vegetated drilling reserve pit area.

Actions Taken

On July 1, 2011 Talon/LPE mobilized personnel to begin the assessment and soil sampling for the construction of a work plan. The soil sample S-1 was collected from soil within the drilling pit area.

The soil sample was collected by Talon personnel wearing clean nitrile gloves. The sample was placed in a laboratory provided sample container and transported to Cardinal Laboratories in Hobbs, New Mexico for analysis of chlorides using Method SM4500CL-B. The complete laboratory report is attached as Appendix II.

Analytical Results

Analytical results received from Cardinal Laboratories are summarized below:

July 18, 2011

Sample, Depth	<u>Chlorides</u>
S-1 0'	24,400 mg/kg

Summary and Conclusions

- Groundwater in the project vicinity is greater than 50-feet below land surface per the New Mexico State Engineer Database.
- Based upon the results of the laboratory data obtained for this investigation, the chloride impacts have been documented to be 24,400 mg/kg at the surface of the drilling pit area.
- Based on the depth to groundwater at the sample location, it is unlikely that the chloride impacts identified from this release will pose a threat to groundwater after proposed remediation activities are complete.

Proposed Remedial Actions

- A decontamination station will be set up to pressure wash off all equipment and vehicles before leaving location to prevent the cross contamination of the African Rue.
- The surface of the closed drilling pit area will be bladed to prepare for the installation of a liner. Rock and debris will be deep buried into the drilling reserve pit area.
- A composite 20 millimeter liner will be installed over the closed drilling pit area. The edges of the liner will be keyed a minimum of three 3-feet deep into a trench excavated at the boundaries of the closed drilling pit area. Visually impacted area outside the drilling pit will be pushed up under the liner area with a dozer.
- New soil will be transported to the location from a local borrow pit and will be placed over the top of the 20 millimeter liner with a 3-foot soil lift.
- The soil lift will be contoured to match the surrounding terrain and seeded using the recommended BLM seed mixture for the area.
- Erosion control berms will be installed to prevent storm waters from running across the area. A berm and barbed wire fence will be installed across the access road.
- A final report will be provided to the Bureau of Land Management Carlsbad Office utilizing Form 3160.

If we can provide additional information or be of further assistance please contact our office at 575.746.8768.

Respectfully submitted,

TALON/LPE


Mike Stubblefield

med 5 weeker

Project Manager

David J. Adkins District Manager

SITE MAP



APPENDIX I GROUNDWATER DATA



New Mexico Office of the State Engineer Water Column/Average Depth to Water

(quarters are 1=NW 2=NE 3=SW 4=SE)

(quarters are smallest to largest)

(NAD83 UTM in meters)

3648590*

(In feet)

Sub Q Q Q POD Number, basin Use County 64 16 4 Sec Tws Rng X Y Distance Well Water Column

RA 08613

DOM CH 4 4 1 34 15S 27E

572480

2952

35

Average Depth to Water:

85 feet

Minimum Depth:

85 feet

Maximum Depth:

85 feet

Record Count: 1

UTMNAD83 Radius Search (in meters):

Easting (X): 573304

Northing (Y): 3645755

Radius: 5000

*UTM location was derived from PLSS - see Help

James Tinney

From:

Mark Cummings

Sent:

Wednesday, May 18, 2011 11:00 AM

To:

Terry Ainsworth; James Tinney

Subject:

FW: location that need work-response requested.

FYI, on the lease inspection that we should be doing now let's make sure we catch this kind of stuff before the BLM ships us these type of letters.

Thanks

Mark Cummings Midland - Texas Cimarex Energy

mcummings@cimarex.com

(432) 571-7816 office (956) 744-0137 cell

----Original Message-----

From: Zeno Farris

Sent: Wednesday, May 18, 2011 10:45 AM

To: Edgar F. Locke; John Osborne; Mark Martino; Mark Cummings

Subject: FW: location that need work-response requested.

----Original Message----

From: jvancure@blm.gov [mailto:jvancure@blm.gov]

Sent: Wednesday, May 18, 2011 10:37 AM

To: Zeno Farris

Subject: location that need work-response requested.

- 1. Callaway Fed 3--The location has not vegetated and is past due on a reclamation. Complete reclamation of location by 6-17-11. Contact me with plan of action before start.
- 2. Callaway Fed 4--Remove unused equipment, Replace windsock, Downsize and use material for pit remediation. Contact me before starting pit remediation.
- 3. Callaway Fed 1--Remove unused tank, Downsize location and use material for pit remediation after testing and also to prevent stormwater from east. Contact me before starting any remediation and so we can go over test sampling of chlorides.
- 4. Callaway Fed 2-- Block trespass road, Remove polyline from pit area, Remediation of pit area and stormwater prevention a must. Contact me before

APPENDIX II LABORATORY RESULTS



July 18, 2011

MIKE STUBBLEFIELD

TALON LPE

408 W. TEXAS AVE.

ARTESIA, NM 88210

RE: CALLAWAY FED #2

Enclosed are the results of analyses for samples received by the laboratory on 07/14/11 14:47.

Cardinal Laboratories is accredited through Texas NELAP for:

Method SW-846 8021

Benzene, Toluene, Ethyl Benzene, and Total Xylenes

Method SW-846 8260

Benzene, Toluene, Ethyl Benzene, and Total Xylenes

Method TX 1005

Total Petroleum Hydorcarbons

Certificate number T104704398-08-TX. Accreditation applies to solid and chemical materials and non-potable water matrices.

Cardinal Laboratories is accreditated through the State of Colorado Department of Public Health and Environment for:

Method EPA 552.2

Haloacetic Acids (HAA-5)

Method EPA 524.2

Total Trihalomethanes (TTHM)

Method EPA 524.4

Regulated VOCs (V2, V3)

Accreditation applies to public drinking water matrices.

Celey D. Keene

This report meets NELAP requirements and is made up of a cover page, analytical results, and a copy of the original chain-of-custody. If you have any questions concerning this report, please feel free to contact me.

Sincerely,

Celey D. Keene

Lab Director/Quality Manager



Analytical Results For:

TALON LPE MIKE STUBBLEFIELD 408 W. TEXAS AVE. ARTESIA NM, 88210 (575) 745-8905

Received:

07/14/2011

Sampling Date:

07/01/2011

Reported:

07/18/2011

Sampling Type:

Soil

Project Name:

CALLAWAY FED #2

Sampling Condition:

Cool & Intact

Project Number:

701162.006.01

Project Location:

SEC.6 - T16S - R28E

Sample Received By:

Jodi Henson

Sample ID: S-1 0' DRILLING PIT (H101459-01)

Chloride, SM450	00CI-B	mg/I	kg	Analyze	а ву: нм	*				
An	alyte	Result	Reporting Limit	Analyzed	Method Blank	BS	% Recovery	True Value QC	RPD	Qualifier
Chloride		24400	16.0	07/15/2011	ND	416	104	400	3.77	

Cardinal Laboratories

*=Accredited Analyte

PLEASE NOTE: Uability and Damages. Cardinai's liability and client's exclusive remedy for any claim arising, whether based in contract or tort, shall be limited to the amount paid by client for analyses. All claims, including those for negligence and any other cause whatsoever shall be deemed waived unless made in writing and received by Cardinal within thirty (30) days after completion of the applicable service. In no event shall Cardinal be liable for incidental or consequential damages, including, without limitation, business interruptions, loss of use, or loss of profits incurred by client, its substitations is based upon any of the above stated reasons or otherwise. Results relate only to the samples Identified above. This report shall not be reproduced except in full with written approval of Cardinal Laboratories.

Celeg D. Keine



Notes and Definitions

ND Analyte NOT DETECTED at or above the reporting limit

RPD Relative Percent Difference

** Samples not received at proper temperature of 6°C or below.

*** Insufficient time to reach temperature.

Chloride by SM4500Cl-B does not require samples be received at or below 6°C

Samples reported on an as received basis (wet) unless otherwise noted on report '

Cardinal Laboratories

*=Accredited Analyte

PLEASE NOTE: Uability and Damages. Cardinal's liability and client's exclusive remedy for any claim arising, whether based in contract or tort, shall be limited to the amount paid by client for analyses. All claims, including those for negligence and any other cause whatsoever shall be deemed walved unless made in writing and received by Cardinal within thirty (30) days after completion of the applicable service. In no event shall Cardinal be liable for incidental or consequential damages, including, without limitation, business interruptions, loss of use, or loss of use, and the performance of the services hereunder by Cardinal, regardless of whether such claims is based upon any of the above stated reasons or otherwise. Results relate only to the samples identified above. This report shall not be reproduced except in full with written approval of Cardinal laboratories.

Celeg D. Keine



CHAIN-OF-CUSTODY AND ANALYSIS REQUEST

101 East Marland, Hobbs, NM 88240 (575) 393-2326 FAX (575) 393-2476

Company Name: T4400/CPE							12	BI.	LL	TO		ANALYSIS REQUEST																	
Project Manager: Mike Stubblefield					P.O. #:												T												
Address: 408 V. Texas Rue.					Company: Talon / LPE								}			1													
City: Artesia State: NM Zip: 88710					Attn:								- 1			•								1					
Phone #: \$35.44/-72 {\forall Fax #:					Address:								Ī				1]				
Project #: 70 1167, 006.01 Project Owner: Cimarca Energy				City:																				1					
Project Name: Callaway Fed. No. Z					State: Zip:								1									-		1					
Project Location	1: scc.6-T165-1	828E							Phone #:								[1			ſ					
Sampler Name:	mie Sullefil	1				.,			Fax #:												į					ĺ			
FOR LAB USE ONLY	•					M	ATR	IX.	PRESERV. SAMPL						ING	NG 2						1		1		ļ		1	1
			ğ	6	25	.					!		l				ellorides		ļ							1			
Lab I.D.	Sample I.	_	(C)	VER	٧AΤί			İ		نن	_					١	उ									1			
Lab I.D.	Sample I.	ν.	BO	ITAII	ON.	E		ä	02	BAS	18	<u></u>					-												
4101450		İ	(G)RAB OR (C)OMP	# CONTAINERS	GROUNDWATER	WASTEWATER	5 =	SLUDGE	뿔	ACID/BASE:	ICE / COOL	OTHER:	١,	DATE	TIME	.	Total							ŀ					<u> </u>
31.10.10	5-1 o' drilling fo	i	ڇ	<u>#</u> .	<u>.</u>		2	<u>يم ر</u> د	10		<u>=</u>	10.			2:208					1	-	+-	+			 			
	313 0111111		_	-	-		-		-		<u>.</u>		 	, į , ÇUH	2.00	7.							-			-			
	The state of the s					1		1			i																	Comparison of Spaces	
								Ī.,																					
													ĺ			-				1				ļ					
								1	ļ	ļ			 		ļ						.	.							
					_	_ -							ļ			_					-	_							
					\dashv		- -	<u>-</u>	-	 								·····				-							
		.,,,	-			\pm	-	+			<u> </u>		 			-					-	-	-						
	od Damages, Cardinel's liability and clier																		l	4	J					l	l	L	L
service. In no event shall Ca	ng those for negligence and any other ca ardina be liable for incidental or conseq	uental damages, including w	ilbaul	limital	lion, bu	sivess	intern	iplions,	loss o	i use.	ar los	s of p	rofits in	ocutted by	client, its subs	sidiarie	es,	e											
Relinquished By	na out of or related to the performance of:				ed E	_	er suc	s d	is one	eutpt	on an	y Di III	e anov	er stated re	Phone I	Resi	ult:	□ Ye		No		l Phon							
Relinquished By: Date: Date: Received By:					Fax Resi REMARK								□ Ye	<u>s</u> _	No	Add	I Fax #	·											
Relinquished By: Time: 2:47/n Received By: Received By:																													
Time:																													
Dallana J.B.	(6)-1-0			,						r	<u> </u>	F0'	(ED	DV.															
Delivered By: (Circle One) Sample Condit Cool Intact							UН	(Injt	(ED l ligis)	DY:																			
Sampler - UPS - Bus - Other:				(Initials)																									
												· V																	