		OCD A	rtesia			
Form 3160-5	UNITED STATES			FORM APPROVED OMB No. 1004-0137		
(March 2012) DE	PARTMENT OF THE I	NTERIOR	TERIOR		Expires: October 31, 2014	
BUF	GEMENT		5. Lease Serial No. NM-59381			
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.				6. If Indian, Allottee or Tribe Name		
	IT IN TRIPLICATE - Other	instructions on page 2.	<u> </u>	7. If Unit of CA/Agreen	nent, Name and/or No.	
I. Type of Well Image: Contract of Well<				8. Well Name and No. MERIDIAN FEDERAL #1		
2. Name of Operator MANZANO, LLC				9. API Well No. 30-015-26229	_ # !	
3a. Address PO BOX 2107 - ROSWELL, NM 88202-2107	DADIGA		10. Field and Pool or Ex	eld and Pool or Exploratory Area KWAY, BONE SPRING		
4. Location of Well (Footage, Sec., T.	575-623-1996		11. County or Parish, State			
4. Location of Well (Footage, Sec., T.R., M., or Survey Description) 660' FNL & 660' FWL, SECTION 3, T20S, R29E				EDDY, NM		
12. CHE	CK THE APPROPRIATE BC	X(ES) TO INDICATE NATU	RE OF NOTI	CE, REPORT OR OTHE	R DATA	
TYPE OF SUBMISSION		TYPE OF ACTION				
Notice of Intent	Acidize	 Deepen Fracture Treat 		luction (Start/Resume) amation	Water Shut-Off	
Subsequent Report	Casing Repair	New Construction	Rec	omplete	Other	
Final Abandonment Notice	Change Plans	Plug and Abandon Plug Back		porarily Abandon er Disposal		
testing has been completed. Fina determined that the site is ready for PROPOSE TO ABANDON EXISTI SET CIBP @ 7850' & CAP W/35' C SET CIBP @ 5750' & CAP W/35' C PERFORATE DELAWARE FROM	or final inspection.) NG BONE SPRING PERFO DF CEMENT DF CEMENT	DRATIONS, PLUG BACK & ACC	RECOMPLE	TE IN DELAWARE AS		
SEE ATTACHED F CONDITIONS OF A ROUIDE CIO2 - 14. Thereby certify that the foregoing is MIKE HANAGAN	NMUCD		4		1 2014 Ouman ND MANAGELAENT ND FIELD OFFICE	
Signature. Mich	Hans	Date 10/10/	,	5EK		
	THIS SPACE	FOR FEDERAL OR S	TATE OF	FICE USE		
Approved by				·		
Conditions of approval, if any, are attach hat the applicant holds legal or equitable entitle the applicant to conduct operation	title to those rights in the subjects thereon.	ct lease which would Office			ate	
Title 18 U.S.C. Section 1001 and Title 4. fictitious or fraudulent statements or rep			and willfully	to make to any department	or agency of the United States any false	
(Instructions on page 2)			• 14 1 1 1	1		

Conditions of Approval Manzano, LLC Merdian – 01 – Sundry dated 10/10/2013 API 3001526229, T20S-R29E, Sec 03 January 21, 2014

- 1. A new "Well Location and Acreage Dedication Plat" (NMOCD Form C-102) is required with the notice of intent package when opening another pay zone.
- 2. <u>Notify BLM 575-200-7902 Eddy Co. as work begins</u>. Some procedures are to be witnessed. If there is no response, call 575-361-2822, leave a voice mail with the API#, workover purpose, and a call back phone number.
- 3. Surface disturbance beyond the existing pad must have prior approval.
- 4. A closed loop system is required. The operator shall properly dispose of drilling/circulating contents at an authorized disposal site. Tanks are required for all operations, no excavated pits.
- 5. Functional H_2S monitoring equipment shall be on location.
- 6. 3000 (3M) Blow Out Prevention Equipment to be used. All BOPE and workover procedures shall establish fail safe well control. Ram(s) for the work string(s) used is required equipment. Manual BOP closure system including a blind ram and pipe ram(s) designed to close on all (hand wheels) equipment shall be installed regardless of BOP design. Function test the installed BOPE to 500psig when well conditions allow. Related equipment, (choke manifolds, kill trucks, gas vent or flare lines, etc.) shall be employed when needed for reasonable well control requirements.
- 7. All waste (i.e. trash, salts, chemicals, sewage, gray water, etc.) created as a result of work over operations shall be safely contained and disposed of properly at a waste disposal facility. No waste material or fluid shall be disposed of on the well location or surrounding area. Porto-johns and trash containers will be on-location during fracturing operations or any other crew-intensive operations.
- 8. The BLM PET witness is to run tbg tally and agree to cement placement. Sample each plug for cement curing time and tag and/or pressure test (WOC time of 4 hours recommended) as requested by BLM PET witness.
- Set cement plugs to cover a minimum of 100ft plus 10ft for every 1,000ft from the bottom of the plug, rounding the number of necessary sacks up to the nearest 5 sacks. Never use less than 25sx. Examples: A cement plug set at 8000 in 7" casing would require a min of 35sx. A 25sx plug in 5 ¹/₂" casing should cover 250ft, which may exceed 100ft plus 10ft per 1000ft.
- Class H > 7500ft & C < 7500ft) cement plugs(s) will be necessary. For any plug that requires a tag or pressure test a minimum WOC time of 4 hours(C) & 8 hours(H) is recommended. Formation isolation plugs of Class "C" to be mixed 14.8#/gal, 1.32 ft³/sx, 6.3gal/sx water and "H" to be mixed 15.6#/gal, 1.18ft³/sx, 5.2gal/sx water.

- 11. Tag the CIBP set at 8145 for confirmation. Set the proposed CIBP less than 100ft above the perforation at 7930.
- 12. Set a balanced 25 sx Class "H" cement plug on the proposed CIBP.
- 13. Minimum requirement for mud placed between plugs is 25 sacks of salt water gel per 100 barrels in 9 lb/gal brine.
- 14. Operator shall run a CBL to identify top of cement. Provide BLM with an electronic copy (Adobe Acrobat Document) cement bond log record from <u>a good cement bond</u> (6500 or below) to top of cement. The CBL may be attached to a <u>pswartz@blm.gov</u> email. The CFO BLM on call engineer may be reached at 575-706-2779.
- 15. Set the 2nd proposed CIBP at 5752 or deeper and set a balanced 25 sx Class "C" cement plug on that CIBP.
- 16. After setting the top plug and before perforating, perform a BLM PET witnessed (charted) casing integrity test of 800 psig. Pressure leakoff may require correction for approval. Include a copy of the chart in the subsequent sundry for this workover.

17. After a successful casing integrity test continue on and perforate Delaware as planned.

- 18. File intermediate **subsequent sundry** Form 3160-**5** within 30 days of any interrupted workover procedures and a complete workover subsequent sundry. File the subsequent sundry for the frac separately if it is delayed as much as 20 days.
- 19. Submit the BLM Form 3160-4 **Recompletion Report** within 30 days of the date all BLM approved procedures are complete.
- 20. Workover approval is good for 90 days (completion to be within 90 days of approval). A legitimate request is necessary for extension of that date.

EGF/PRS 012114