District I 1625 N. French Dr., Hobbs. NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

٠

State of New Mexico Energy Minerals and Natural Resources

> Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Santa Fe, NM 87505													
Release Notification and Corrective Action													
nJM/14/1024/8209						OPERATOR			X Initi	al Report	П	Final Report	
Name of Company SM ENERGY COMPANY 154903						Contact VICKIE MARTINEZ							
		STREET, B	Telephone No. (432)688-1709										
Facility Name OSAGE 34 FEDERAL 1H						Facility Type WELL							
Surface Owner BLM Mineral Owner						BLM API No. 30-015-41508							
				LOC	ATIC	ON OF RELEASE							
Unit Letter	Unit Letter Section Township Range Feet from the N					rth/South Line Feet from the East			t/West Line County				
Α	34 19S 29E 450 NO				NO	RTH 330 EAS			EDDY				
Latitude Longitude													
NATURE OF RELEASE													
Type of Rele	ase FOAM	IY MIXTUR	RE OF W	ATER,GAS,OI	L&SA	ANDVolume of Release 440 PRELIM Volume Recovered 270							
Source of Re	elease WEL	<u>LHEAD (B</u>	Date and Hour of Occurrence Date and Hour of Discovery SAME										
Was Immedi	ate Notice (liven?	If YES, To Whom? JIM AMOS W/BLM - MIKE BRATCHER W/NMOCD										
By Whom? I	MADE DO	DNDY - RIC	Date and Hour 12/13/13 10:30 PM										
Was a Water		ched?	If YES, Volume Impacting the Watercourse.										
If a Watercourse was Impacted, Describe Fully.*											ED		
						i I I							
									DE	EC 26 20	113		
Describe Cau		NMOCD ARTESA											
Wellbore fl failure of th manufactur	Wellbore fluids were released to the atmosphere, the well pad and to a small extent, the adjacent pasture. The cause of the incident was the failure of the Annular Blowout Preventer being used to seal the wellbore at the surface. The failed BOP element is being examined by the manufacturer. We have established a policy that requires a pump truck to be connected to all horizontal wells that are under initial completion to ensure the wellbore stays full of water during the work. In addition, Annular Blowout Preventers will not be relied upon as a												
completion Describe Are	completion to ensure the wellbore stays full of water during the work. In addition, Annular Blowout Preventers will not be relied upon as a Describe Area Affected and Cleanup Action Taken.* primary wellbore seal.												
Most of the	fluids wer	re contained	on the w	ell pad. Cleanu	p crew	s, safety spec	cialists and well	control	specialis	ts were imr	nediate	ely	
dispatched for personn discharged	Most of the fluids were contained on the well pad. Cleanup crews, safety specialists and well control specialists were immediately dispatched to the site. At approximately midnight, 6 hours after the event started, the flow from the well subsided to the point it was safe for personnel to approach the well, attach a sealing assembly to the tubing and lower it into the wellhead, sealing off the flow. Most of the discharged fluids ran over to a low spot on the West side of the well pad where they were collected by vacuum trucks.												
				e is true and comp									
				nd/or file certain a ce of a C-141 rep									
should their	public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other												
				ptance of a C-141	report	does not reliev	e the operator of	respons	ibility for c	compliance	with any	y other	
federal, state, or local laws and/or regulations.						OIL CONSERVATION DIVISION							
Signature:	100	lII	A ,										
Printed Name: VICKIE MARTINEZ						Approved by Environmental Specialist: Signed By Milly Brancher							
Title: ENC	SINEER T	ECH II				Approval Da	JAN 0320)14	Expiration	Date:			
E-mail Addr	ess: VMAR	TINEZ@SN	M-ENER	GY.COM		Conditions o	••			Attached	1 🗖		
Date: 12/20				:(432)688-1709) ii	Remediation	per OCD Rule & y BLM. <u>SUBMIT</u>	Guidelir	nes, &		_		
* Attach Addi	tional She	ets If Necess	sary		· •		SAL NO LATER 1		ATION	ZRP	-2	36	
					1	ebrua		014	,		- 1		
						`							

OSAGE 34 FEDERAL 1H

C-141 ATTACHMENT

Describe Area Affected and Cleanup Action Taken.* continued:

The cleanup continued throughout the night and into Saturday morning. Jim Amos with the BLM visited the site on Saturday morning to assess the situation and provide some guidance on cleanup strategies. Approximately 17,700 square feet on the pad and another 4,300 off the pad to the west were impacted by the release. Tetra Tech (Environmental testing and consulting company) personnel visited the site Wednesday, December 18, to delineate the extent of the impact. Soil samples were taken to determine hydrocarbon and chloride levels. We are awaiting their recommendations and proposed timing for the final cleanup and remediation of the impacted pasture land. When analysis results are received for the soil samples, they will be evaluated and either a work plan or request for closure will be prepared and submitted for approval. It will likely be mid-January before the work plan or closure request will be ready.