

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

Name of Company	Oxy Permian Ltd.	Contact	Christopher Jones
Address	1502 W. Commerce Dr., Carlsbad, NM	Telephone No.	(575) 628-4121
Facility Name	Jones Canyon 4 Federal #4	Facility Type	

Surface Owner	Mineral Owner	Lease No.	API#30-015-30487
---------------	---------------	-----------	------------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
E	4	22S	24E					Eddy County, NM

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

**NATURE OF RELEASE**

Type of Release	Produced water	Volume of Release	500 bbls	Volume Recovered	50 bbls
Source of Release	Failure in 2" steel production line	Date and Hour of Occurrence	12/13/2012	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher- OCD, James Amos-BLM, Terry Gregston-BLM		
By Whom?	Christopher Jones	Date and Hour	12/13/2012 @ 11:20am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			


**RECEIVED**  
 JUL 30 2013  
 NMOCD ARTESIA

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*  
 Failure in a 2" steel production line caused 500 bbls of produced water to leak onto the ground. 50 bbls of produced water were recovered via vacuum truck.

Describe Area Affected and Cleanup Action Taken.\*  
 Failure in a 2" steel production line caused 500 bbls of produced water to leak onto the ground. 50 bbls of produced water were recovered via vacuum truck. Remediation was completed in accordance with the remediation plan approved by Mike Bratcher of NMOCD via email on 04/05/2013 and by James Amos of the BLM on 04/12/2013.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		<b>OIL CONSERVATION DIVISION</b>	
Printed Name:	Christopher Jones	Approved by District Supervisor:	
Title:	HES Specialist	Approval Date:	4/17/15
E-mail Address:	Christopher Jones@oxy.com	Expiration Date:	N/A
Date:	7-29-13	Conditions of Approval:	Final
Phone:	(575) 628-4121	Attached	<input type="checkbox"/>

\* Attach Additional Sheets If Necessary

2RP-1494