

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

*nJMW1307241610* OPERATOR  Initial Report  Final Report


Name of Company: Devon Energy Production LP <i>6137</i>	Contact: Roy White	
Address: P.O. Box 250 Artesia, N.M. 88211	Telephone No. (575) 513-1741	
Facility Name: Turkey Town # 1	Facility Type: Gas Well # 30-015-24228	
Surface Owner	Mineral Owner	Lease No.

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	23	18S	28E	660	South	1980	West	Eddy

**NATURE OF RELEASE**

Type of Release: Oil/Produced Water	Volume of Release: 94 bbls oil/12 bbls produced water	Volume Recovered: 0 bbls recovered
Source of Release: Broken load line valve	Date and Hour of Occurrence: 1/17/13, 5:00 PM	Date and Hour of Discovery: 1/17/13, 5:00 PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Rudy Zuniga, Assistant Foremen, Devon Energy	
By Whom? Brooke Owens, Lease Operator	Date and Hour: 1/17/13, 5:00 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	



If a Watercourse was Impacted, Describe Fully.\* N/A

Describe Cause of Problem and Remedial Action Taken.\*  
At the Turkey Town # 1 location a load line valve broke causing 94 bbls of oil and 12 bbls of produced water to release onto the ground. The Lease Operator who discovered the spill contacted an environmental cleanup company to remediate soil.

Describe Area Affected and Cleanup Action Taken.\*  
The spill occurred at the Turkey Town #1 location. The Lease Operator who discovered the broken load line valve contacted an environmental cleanup company to remediate soil. 0 bbls. were recovered.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Rebecca Raga</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Rebecca Raga	Approved by District Supervisor: Signed By <i>Mike Benavides</i>	
Title: Field Admin Tech	Approval Date: <b>MAR 13 2013</b>	Expiration Date:
E-mail Address: Rebecca.raga@dmv.com	Conditions of Approval: Remediation per OCD Rule & Guidelines. <b>SUBMIT REMEDIATION PROPOSAL NO LATER THAN:</b>	Attached <input type="checkbox"/>
Date: 1/21/13 Phone: 575-746-5564	<i>April 13, 2013</i>	<i>2RP-1584</i>

\* Attach Additional Sheets If Necessary