

NM OIL CONSERVATION

ARTESIA DISTRICT

MAY 05 2015

Form C-141
Revised August 8, 2011

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED
Submit Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1515278638

OPERATOR

Initial Report Final Report

Name of Company: Devon Energy Production Co LP (6137)	Contact: Brian Kuh, Devon Foreman
Address: PO Box 250 Artesia, NM 88211	Telephone No. 575-513-9136
Facility Name: Cotton Draw 11 Fed 2H	Facility Type: Well location - Poseidon Tank
Surface Owner: Federal	Mineral Owner: Federal
API No. 30-015-39375	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
C	11	25S	31E	330	North	1980	West	Eddy

Latitude: 32deg 9' 4.648" N Longitude: 103deg 45' 3.002" W

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 7.5 bbls	Volume Recovered: 5 bbl +
Source of Release: Poseidon Tank on location	Date and Hour of Occurrence: 4/29/15, 7:00 PM	Date and Hour of Discovery: 4/29/15, 7:00 PM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? (OCD-Mike Bratcher BLM-Jeff Robertson)	
By Whom? Brian Kuh, Devon Foreman	Date and Hour: (5/4/15, 10:45 AM)	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse: N/A	

If a Watercourse was Impacted, Describe Fully.*

N/A

Describe Cause of Problem and Remedial Action Taken.*

A small hole on the underside of the Poseidon tank may have been caused by a power washer which caused the initial leak, then another hole was discovered in the secondary containment caused by an anchor. Vacuum trucks were used to recover the produced water.

Describe Area Affected and Cleanup Action Taken.*

The rest of the water in the tank was transferred to another tank at the Trionyx location so the hole may be mended. Vacuum trucks were used to recover the produced water. Alfredo's will take soil samples once the tank has been moved and remediation will take place accordingly.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Denise Menoud</i>	OIL CONSERVATION DIVISION	
Printed Name: Denise Menoud	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Field Admin Support	Approval Date: 4/11/15	Expiration Date: N/A
E-mail Address: Denise.Menoud@dvn.com	Conditions of Approval: 1	Attached <input type="checkbox"/>
Date: 5/4/2015 Phone: 575-746-5544	Remediation per O.C.D. Rules & Guidelines.	

* Attach Additional Sheets If Necessary

SUBMIT REMEDIATION PROPOSAL NO LATER THAN: 6/2/15

2RP-3021