

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION
ARTESIA DISTRICT

JUL 14 2015

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1520128523

OPERATOR

Initial Report Final Report

Name of Company: BOPCO, L.P. <i>200737</i>	Contact: Bradley Blevins
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: PLU 213	Facility Type: Exploration and Production

Surface Owner: Federal	Mineral Owner:	API No. 3001533859
------------------------	----------------	-----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	18	24S	30E	860		660		Eddy

Latitude 32.212740 Longitude 103.914387

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 13 barrels produced water	Volume Recovered: 4 barrels produced water
Source of Release: Rubber inside Vic clamp failed on water transfer pump.	Date and Hour of Occurrence 7-13-15 @ 2:00pm	Date and Hour of Discovery 7-13-15 @ 2:14pm
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

BOPCO EHS was notified of a release that occurred at the PLU 213. The release occurred on a water transfer line that runs from the 213 production side to the 213 SWD battery (opposite side of location). The rubber on the inside of the Vic clamp failed causing produced water to be released.

Describe Area Affected and Cleanup Action Taken.*

A vacuum truck was called to location and recovered 4 barrels of produced water.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Bradley Blevins</i>	OIL CONSERVATION DIVISION	
Printed Name: Bradley Blevins	Signed By <i>Mike Brannon</i> Approved by Environmental Specialist.	
Title: Assistant Remediation Foreman	Approval Date: <i>7/12/15</i>	Expiration Date: <i>NIA</i>
E-mail Address: bblevins@basspet.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: <i>7.14.15</i> Phone: 432-214-3704	SUBMIT REMEDIATION PROPOSAL NO LATER THAN: <i>8/20/15</i>	

2RP-3130