

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

### Release Notification and Corrective Action

#### OPERATOR

Initial Report  Final Report


Name of Company	Chevron Delaware Basin	Contact	Bradley Blevins
Address	PO Box 190, Hobbs, NM 88241	Telephone No.	(575) 391-1462
Facility Name	Culebra Bluff SWD Water Transfer Line	Facility Type	SWD
Surface Owner	Mineral Owner	Lease No.	

#### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
L	36	22S	28E					Eddy County, NM

Latitude N 32.34734° Longitude W 104.04839°

#### NATURE OF RELEASE

Type of Release	Produced Water	Volume of Release	77 bbls	Volume Recovered	0 bbls
Source of Release	Hole in 3" ball valve in the transition	Date and Hour of Occurrence	03/25/2013 @ 12:30 pm	Date and Hour of Discovery	
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*		<div style="border: 2px solid black; padding: 5px; width: fit-content; margin: auto;"> <p><b>RECEIVED</b></p> <p>JUL 30 2013</p> <p>NMOCD ARTESIA</p> </div>			
Describe Cause of Problem and Remedial Action Taken.*					
A hole in the 3" ball valve in the transition caused 77 bbls of produced water to leak onto the ground. No fluids were recovered and the valve was repaired.					
Describe Area Affected and Cleanup Action Taken.*					
The area affected us approximately 40' x 450'. A hole in the 3" ball valve in the transition caused 77 bbls of produced water to leak onto the ground. No fluids were recovered and the valve was repaired. Remediation was completed in accordance with the NMOCD-approved remediation plan.					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.					
Signature: 		<b>OIL CONSERVATION DIVISION</b>			
Printed Name: Bradley Blevins		Approved by District Supervisor: 			
Title: EHS Specialist		Approval Date: 7/13/15		Expiration Date: MA	
E-mail Address: Bradley.blevins@chk.com		Conditions of Approval: Final		Attached <input type="checkbox"/>	
Date: 7/29/13		Phone: (575) 391-1462			

\* Attach Additional Sheets If Necessary

2RP-1619