


## NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

**BILL RICHARDSON** Governor

Joanna Prukop Cabinet Secretary **Acting Director** Oil Conservation Division

9 January 2006

Devon Energy Production Co 20 North Broadway, Suite 1500. Oklahoma City, Oklahoma 73102



Form C-103 Report of Plugging for your Warthog 2 State #4 I-2-23-28 API 30-015-27182 Cannot be approved until an NMOCD representative has made an inspection of the location and found it to be cleared to comply with OCD rules and regulations. Please check each item in the space provided to indicate that the work has been accomplished and the location is ready for final inspection.

B	<b>1</b> .	All pi	its have	e been	closed	as	per	Rule	50

2. Rat hole and cellar have been filled and leveled.

3. A steel marker 4" in diameter and approximately 4' above mean ground level has been set in concrete to mark the exact location of the plugged well. (Marker must have operator name, lease name, well number and location including quarter/quarter section or unit letter, section, township, range and API well ID number permanently welded, stamped or otherwise engraved into the metal marker.)

4. The location has been leveled as nearly as possible to original top ground contour and has been cleared of all junk and equipment.

X	5	The dead n	nen and tie	downs have	heen cut a	nd removed

6. If a one well lease or last remaining well on lease, the battery and burn pit locations have been leveled and cleared of all junk & equipment.

7. All environmental concerns have been addressed as per OCD guidelines.

The above are minimum requirements and no plugging bond will be cancelled until all locations for plugged and abandoned wells have been inspected and Form C-103 approved.

When all of the work outlined above has been done, please notify this office by completing, signing and returning this letter to us so that our representative will not have to make more than one trip to the location.

I certify that the above work has been done and the above-mentioned lease is ready for OCD inspection and approval.

Field Rep. II

Submit 3 Copies To Appropriate District Office	State of New Mexico			Form C-103				
District I	Energy, Minerals a	Energy, Minerals and Natural Resources			Revised June 10, 2003 WELL API NO.			
1625 N. French Dr., Hobbs, NM 88240 District II	OII CONSEDV	OIL CONSERVATION DIVISION			30-015-27182			
1301 W. Grand Ave., Artesia, NM 88210 District III	1220 South			5. Indicate Type of Lease				
1000 Rio Brazos Rd., Aztec, NM 87410				STATE				
<u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM	Santa i c	1			6. State Oil & Gas Lease No. VB407			
87505 SUNDRY NOTI	CES AND REPORTS ON	IWFIIS		7 Lease Name o	r Unit Agreement Name			
(DO NOT USE THIS FORM FOR PROPOSE DIFFERENT RESERVOIR. USE "APPLICE"	SALS TO DRILL OR TO DEEP	EN OR PLU	JG BACK TO A	Warthog 2 State				
PROPOSALS.) 1. Type of Well:				8. Well Number				
Oil Well Gas Well	Other	RF	CEIVED	4				
2. Name of Operator				9. OGRID Numb	per			
Devon Energy Production Compan	y, LP		N 0 5 2006	6137				
3. Address of Operator 20 North Broadway, Suite 1500, O	0.011		PARTERIA	10. Pool name of				
4. Well Location	klanoma City, Oklanoma	/3102		Herrandura Bend	East Delaware			
4. Well Location								
Unit LetterI_:_198	0'feet from the _	South	line and60	60'feet from	theEastline			
Section 2	Township 23S		ge 28E	Eddy	County			
The second second	11. Elevation (Show who 3069' GR	ether DR,	RKB, RT, GR, etc.,	) 				
12. Check A	Appropriate Box to Inc	dicate N	ature of Notice,	Report or Other	· Data			
NOTICE OF IN	TENTION TO:		SUB	SEQUENT RE	PORT OF:			
PERFORM REMEDIAL WORK	PLUG AND ABANDON		REMEDIAL WOR	к 🗆	ALTERING CASING			
TEMPORARILY ABANDON	CHANGE PLANS		COMMENCE DRI	ILLING OPNS.	PLUG AND 🖂 ABANDONMENT			
PULL OR ALTER CASING	MULTIPLE COMPLETION		CASING TEST AI CEMENT JOB	ND 🗆	, ib, with critical			
OTHER:			OTHER:					
13. Describe proposed or comp								
of starting any proposed we or recompletion.	ork). SEE RULE 1103. F	or Multip	le Completions: At	tach wellbore diag	ram of proposed completion			
1. MIRU for P&A on 12/13/05. Phi	Howleing with NMOCD	natified						
2. Set CIBP at 5549' and dumped ba			ed Delaware perfs f	rom 5574 to 5589'	Spot salt gelled mud			
3. Spot 25 sx cement from 4825 to 5					operation Server and			
4. Spot 50 sx cement at 2830'. Tagg								
5. Spot 25 sx cement at 451'. Tagge								
6. Spot surface cement plug at 63'.	Cut wellnead off & set dry	y noie mai	ker. <u>well plugged</u>	1 & abandoned on 1	2/16/05.			
I hereby certify that the information	<del>-</del>	e to the be	est of my knowledg	e and belief.				
SIGNATURE ROME SI	ack titi	E: Engi	neering Technician	DAT	E 1/3/06			
Type or print name Ronnie Slack	E-mail address: I	Ronnie.Sla	ack@dvn.com	Telephone N	Jo. 405-552-4615			
(This space for State use)	<b>1</b> /2							
APPPROVED BY  Conditions of approval if any any and approved in the second seco	<b>/</b>	TITLE			DAJAN 26 2006			
Conditions of approval, if approval	`							

