Form 3160-5 (August 2007)

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010

5. Lease Scrial No.

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.				NMNM0557371 6. If Indian, Allottee or Tribe Name	
Type of Well				8. Well Name and No. AAO FEDERAL SWD 1	
Name of Operator Contact: EMILY FOLLIS APACHE CORPORATION E-Mail: Emily.Follis@apachecorp.com				9. API Well No. 30-015-42549	
3a. Address 303 VETERANS AIRPARK LA MIDLAND, TX 79705	Phone No. (include area code) 432-818-1801)	10. Field and Pool, or Exploratory SWD;WC-CISCO-CANYON-STRAW		
4. Location of Well (Footage, Sec., T	-		11. County or Parish, and State		
Sec 1 T18S R27E SWNE 2470FNL 2380FEL				EDDY COUNTY COUNTY, NM	
12. CHECK APPI	ROPRIATE BOX(ES) TO INC	DICATE NATURE OF N	NOTICE, REI	PORT, OR OTHER	R DATA
TYPE OF SUBMISSION	TYPE OF ACTION				
Notice of Intent ■ Notice of Intent Notice of	☐ Acidize	□ Deepen	☐ Production	n (Start/Resume)	■ Water Shut-Off
_	□ Alter Casing	□ Fracture Treat	☐ Reclamat	ion	■ Well Integrity
☐ Subsequent Report	□ Casing Repair	■ New Construction	□ Recomple	ete	☑ Other Production Start-up
☐ Final Abandonment Notice	☐ Change Plans	□ Plug and Abandon	☐ Temporar	rily Abandon	Production Start-up
	☐ Convert to Injection	☐ Plug Back	■ Water Dis	sposal	
If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation recompletion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.) Apache is submitting this after the fact NOI in order to comply with APD COA's that completion/production were unaware of at the time of completing the well. Below is the Completion Procedure: 1. Run logs from 6248' to surface GR-CBL-CNL 2. Trip in hole with 6 1/8? bit and drill collars on 2 7/8? tubing to CIBP @ 7000?. Displace hole with new 14 PPG mud. Drill out CIBP and push 100? below 7? casing shoe (7? 26# L-80 set at 7434?). 3. Check for flow & lay tubing down. RU up lubricator and run 7? nickel plated Lok-set packer on wire line (Packer accessories? on-off tool with profile nipple. Below packer run a pump out plug 6000 psi pin on a 2 7/8? x 6? extension below the packer). Note: Run a profile nipple to accommodate the largest blanking plug that is designed for running and setting inside 2 7/8? tubing not 4 ?? tubing. RECEIVED 14. I hereby certify that the foregoing is true and correct.					
, , , ,	Electronic Submission #32308	6 verified by the BLM Well PORATION, sent to the 0	ll Information : Carlsbad	System	
Name (Printed/Typed) EMILY FC	Title REGUL	ATORY ANA	LYST		
Signature (Electronic Submission) Date			015		
	THIS SPACE FOR FI	EDERAL OR STATE	OFFICE US	E	
Approved By		Title			Date
Conditions of approval, if any, are attached certify that the applicant holds legal or equivalent would entitle the applicant to conduct the conduction of t	arrant or			•	
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent	U.S.C. Section 1212, make it a crime			e to any department or a	agency of the United

Additional data for EC transaction #323086 that would not fit on the form

32. Additional remarks, continued

4.Set Packer 100' from 7" casing shoe
5.Trip in hole with 2 7/8? tubing open ended and gently tag on off tool. Displace hole with 10ppg brine packer fluid. Lay down tubing.
6.Run 4 ?? Duo lined tubing with on-off tool. Space out and Latch on-off tool with 4 ?? tubing in 15,000 to 20,000# compression. Land tubing. Test annulus. Rig up lubricator.
7.Retrieve blanking plug. Pressure 4 ?? tubing to 6000 psi and pump out plug. If unable to pump out plug chemically cut off 6? extension.
8.Flow back mud until all mud is recovered.
9.Run 4 Point injectivity test at 1, 2, 3 & 4 BPM pumping 25 barrels 10PPG brine at each flow rate.
10.File injection report and place on injection as soon as approval is received.