

NFW MEXICO ENERGY, MINERALS and Elem-up letter L RESOURCES DEPARTMENT

BILL RICHA

1-

P/A OK To Release 3/15/06

Joanna Prukop
Cabinet Secretary
Acting Director
Oil Conservation Division

8 March 2006

Devon Energy Production Company P. O. Box 250 Artesia, NM 88211-0250 RECEIVED

MAR 1 3 2006

VU-MILEUM

Form C-103 Report of Plugging for your Todd 36A State #16 Unit A of Section 36-T23S-R31E API 30-015-29294 cannot be approved until an NMOCD representative has made an inspection of the location and found it to be cleared to comply with OCD rules and regulations. Please check each item in the space provided to indicate that the work has been accomplished and the location is ready for final inspection.

- 1. All pits have been closed as per Rule 50.
- 2. Rat hole and cellar have been filled and leveled.
- 3. A steel marker 4" in diameter and approximately 4' above mean ground level has been set in concrete to mark the exact location of the plugged well. (Marker must have operator name, lease name, well number and location including quarter/quarter section or unit letter, section, township, range and API well ID number permanently welded, stamped or otherwise engraved into the metal marker.)
- 4. The location has been leveled as nearly as possible to original top ground contour and has been cleared of all junk and equipment.
- 5. The dead men and tie downs have been cut and removed.
- 6. If a one well lease or last remaining well on lease, the battery and burn pit locations have been leveled and cleared of all junk & equipment.
- 7. All environmental concerns have been addressed as per OCD guidelines.

The above are minimum requirements and no plugging bond will be cancelled until all locations for plugged and abandoned wells have been inspected and Form C-103 approved.

When all of the work outlined above has been done, please notify this office by completing, signing and returning this letter to us so that our representative will not have to make more than one trip to the location.

I certify that the above work has been done and the above-mentioned lease is ready for OCD inspection and approval.

Hame 7. Handles

Van Barton Field Rep. II

Title

Submit 3 Copies To Appropriate District Office	State of New Mexico			Form C-103	
District I	Energy, Minerals and Natural Resources			Revised June 10, 2003 WELL API NO.	
1625 N. French Dr., Hobbs, NM 88240 District II			30-015-29294		
1301 W. Grand Ave., Artesia, NM 88210	01 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION			5. Indicate Type of Lease	
District III 1220 South St. Francis Dr. 1000 Rio Brazos Rd., Aztec, NM 87410			STATE S FEE		
District IV Santa Fe, NW 8/303			6. State Oil & G	as Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM 87505				K-952	
SUNDRY NOTICES AND REPORTS ON WELLS				7. Lease Name of	or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH				Todd 36A State	
PROPOSALS.) 1. Type of Well:				8. Well Number	
Oil Well 🛛 Gas Well	Other	HE.	CEIVED	10	
2. Name of Operator		DE	C _ 9 2005	9. OGRID Num	ber
Devon Energy Production Compa	ny, LP	-	ARTBSIA	6137	*****
3. Address of Operator 20 North Broadway, Suite 1500,	Nelahama City Olelahama	4 5 0	statut General	10. Pool name o	
4. Well Location	Oktanoma City, Oktanoma	73102		Ingle Wells (Dela	awaie)
4. Well Escation					
Unit Letter A : 660' feet from the North line and 660' feet from the East line					
Section 36	Township 23S		nge 31E	<u>Edd</u>	y County
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3546' GL					
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data					
				SEQUENT RE	
PERFORM REMEDIAL WORK	PLUG AND ABANDON		REMEDIAL WOR	RK 🗆	ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS		COMMENCE DR	ILLING OPNS.	PLUG AND 🛛 ABANDONMENT
PULL OR ALTER CASING	MULTIPLE COMPLETION		CASING TEST A CEMENT JOB	ND 🗆	
OTHER:			OTHER:		
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date					
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.					
1. Moved in rig for P&A on 11/23/05.					
2. RIH with tubing. Unable to work below top of fish at 6727'. Spot a total of 163 sx cement at 6727'. Tagged TOC at 6178'. Tested					
cement plug & casing to 900 psi. Held Ok. This abandons Delaware perfs at 8151-8288 and covers damaged 5-1/2" casing at 6712-					
6724'. Witnessed by Phil Hawkins with OCD.					
3. Circulated hole with 9# salt gelled mud.					
4. Spot 30 sx cement at 4452'. Tagged TOC at 4179'. Covers 8-5/8" casing shoe at 4400'. 5. Pan stretch & found 5 1/2" assing fronts 2220'. Cover 1/2" assing stretch 2220'. POOM and 1 in 1 days as in 1/2" assing stretch 2220'.					
5. Ran stretch & found 5-1/2" casing free to 3229'. Cut 5-1/2" casing at 3200'. POOH and laid down casing. Spot 35 sx cement at 3258' for stub plug. Tagged TOC at 3098'.					
6. Spot 40 sx cement at 1274'. Tagged TOC at 1139'.					
7. Spot 40 sx cement at 906'. Tagged TOC at 796'. Covers 13-3/8" casing shoe at 856'.					
8. Spot 60' surface plug. Cut off wellhead and installed P&A marker. Well plugged & abandoned on 12/7/05.					
I hereby certify that the information above is true and complete to the best of my knowledge and belief. O					
SIGNATURE ROMME	ack TIT	LE: Engi	neering Technician	DAT	E 12/7/05
Type or print name Ronnie G. Sla	ck E-mail addres	s: Ronnie	.Slack@dvn.com	Telephon	ne No. 405-552-4615
(This space for State use)	<i>/99</i>				MAR 1 6 2006
APPPROVED BY Conditions of approval, if any:		TITLE			_DATE

