Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

NMOCD Artesia FÖRM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010

5. Lease Serial No. NMNM0405444A

BUREAU OF LAND MANAGEMENT Artes	\mathbf{ia}
SUNDRY NOTICES AND REPORTS ON WELLS	
Do not use this form for proposals to drill or to re-enter an	
abandoned well. Use form 3160-3 (APD) for such proposals	

6	If Indian	Allottee or Tribe Name

abandoned well. Use form 3160-3 (APD) for such proposals.				6. If Indian, Allottee or Tribe Name		
SUBMIT IN TRIPLICATE - Other instructions on reverse side.				7. If Unit or CA/Agreement, Name and/or No. NMNM135070		
1. Type of Well Gas Well Go		8. Well Name and No. ALDABRA 25 FEDERAL COM 1H				
Name of Operator DEVON ENERGY PRODUCT	9. API Well 30-015-	No. 38612-00-S1				
3a. Address 333 WEST SHERIDAN AVE OKLAHOMA CITY, OK 7310	b. Phone No. (include area code Ph: 405-552-3303	10. Field an JENNIN	10. Field and Pool, or Exploratory JENNINGS UNKNOWN			
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)				or Parish, and State		
Sec 25 T23S R31E SWSW 20	EDDY (EDDY COUNTY, NM				
•	v	•				
12. СНЕСК ДРР	ROPRIATE BOX(ES) TO I	NDICATE NATURE OF 1	NOTICE, REPORT, OR	OTHER DATA		
TYPE OF SUBMISSION	TYPE OF ACTION					
Notice of Intent ■	☐ Acidize	□ Deepen	☐ Production (Start/Res	sume) 🔲 Water Shut-Off		
	☐ Alter Casing	☐ Fracture Treat	☐ Reclamation	■ Well Integrity		
☐ Subsequent Report	☐ Casing Repair	□ New Construction	Recomplete	Other		
☐ Final Abandonment Notice	☐ Change Plans	□ Plug and Abandon	☐ Temporarily Abando	n Workover Operations		
	☐ Convert to Injection	☐ Plug Back	■ Water Disposal			
determined that the site is ready for f Devon Energy Production Cor new ESP to enhance producti schematics are attached for you Remove Casing Patch ® 834 1. MIRU WSU 2. ND Wellhead. NU BOPE & 3. POOH W/ESP assembly ar 4. RIH in the following order a. Releasing Spear with Graps b. No-Go	mpany, LP respectfully reque on on the Aldabra 25 Fed Co our review and the procedure? test. dd 2-7/8" production tubing fr	om 1H. The current and pro es are as follows:		MAR 29 2016 CONSERVATION ARTESIA DISTRICT MAR 29 2016 COUNTY LUCY RECEIVED 304033		
14. I hereby certify that the foregoing is	true and correct		-}}			
Comm	Electronic Submission #323	PRODUCTION CO LP, sent (o the Carlsbad n 11/16/2015 (16JAS1188)	~^~\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\		
Signature (Electronic S		- Date 11 16/20				
	THIS SPACE FOR	FEDERAL OR STATE	1	161 - WWW 11111		
Approved By Conditions of approval, if any, are attached entify that the applicant holds legal or equivalent would entitle the applicant to conduct the conduction of the conduction of the applicant to conduction of the conducti	itable title to those rights in the sub		BURGAL DE YAND MANA CARLSBAD FIELD OF	Date		
Fitle 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent s			willfully to make to any depar	tment or agency of the United		

Additional data for EC transaction #323620 that would not fit on the form

32. Additional remarks, continued

c. Bumper Jar d. Hydraulic Fishing Jar

e. Drill collar

f. Accelerator Jar

g. Drill collars

XX its of 2-7/8? tubing to reach 847?

5. Pull up on casing patch to min fishing force of 27k# and a max of 40k#

5. Pull up on casing patch to third issuing late of 27km and a max of 40km
6. POOH with casing patch, tubing, BHA
7. Make gauge ring/junk basket run to ~1,000?.
8. RIH w/ 2-7/8? tubing, on/off tool, and Retrievable pkr. Set AS-Xpkr @ 900'.
9. Release off of on/off tool

10. Pressure test casing to 500 psi for 30 minutes. Chart test and send to NMOCD.

11. If test pressure bleeds off less than 5 psi ND BOPE, NU wellhead.

If test fails see procedure below for cement squeeze.
 RIH with ESP

Cement Squeeze if Necessary

1. RIH in the following order

a. AS-1X retrievable packer

b. On/off tool

c. XX jts of 2-7/8? tubing to set pkr. @ 1200?

2. Release off of on/off tool and pick up one jt

3. Bring pumps online and establish circulation

4. Pump @ 1.5 bpm to 400# to determine amount of fluid that perf hole will take

5. Shut pumps down.

6. Spot 2 bags of silca sand on top of AS-1X packer 7. POOH with 2-7/8? tubing.

8. Dump XX sacks of Class C 13.8# cement to fill void space determined by injection test plus 5 sacks additional.


Let cement setup for 48 hours.
 RIH with 2-7/8? tubing and big to drill out cement to 1100?
 Pressure test casing to 500 psi for 30 minutes. Chart test and send to NMOCD.

12. Perform negative pressure test to verify no fluid from the formation.

13. Finish drillout of cement

14. Circulate sand back out of the well

15. POOH with 2-7/8 tubing and bit 16. RIH and retrieve AS-1X packer



WELLBORE DIAGRAM PARTS LIST

