

State of New Mexico  
Energy, Minerals and Natural Resources Department

Susana Martinez  
Governor

David Martin  
Cabinet Secretary

Brett F. Woods, Ph.D.  
Deputy Cabinet Secretary

David Catanach, Director  
Oil Conservation Division



**\*Response Required - Deadline Enclosed\***

*Underground Injection Control Program  
"Protecting Our Underground Sources of Drinking Water"*

26-Apr-16

LINN OPERATING, INC.  
600 TRAVIS STREET SUITE 4900  
HOUSTON TX 77002-7002

**LETTER OF VIOLATION and SHUT-IN DIRECTIVE  
Failed Mechanical Integrity Test**

Dear Operator:

The following test(s) were performed on the listed dates on the following well(s) shown below in the test detail section.

The test(s) indicates that the well or wells failed to meet mechanical integrity standards of the New Mexico Oil Conservation Division. To comply with guidelines established by the U.S. Environmental Protection Agency, the well(s) must be shut-in immediately until it is successfully repaired. The test detail section which follows indicates preliminary findings and/or probable causes of the failure. This determination is based on a test of your well or facility by an inspector employed by the Oil Conservation Division. Additional testing during the repair operation may be necessary to properly identify the nature of the well failure.

Please notify the proper district office of the Division at least 48 hours prior to the date and time that the well(s) will be retested so the test may be witnessed by a field representative.

***MECHANICAL INTEGRITY TEST DETAIL SECTION***

<b>H E WEST B No.026</b>		<b>30-015-05060-00-00</b>	
	Active Injection - (All Types)		I-3-17S-31E
Test Date:	4/12/2016	Permitted Injection PSI:	Actual PSI: 160
Test Reason:	5-year Test	Test Result: F	Repair Due: 7/16/2016
Test Type:	Std. Annulus Pres. Test	FAIL TYPE: Other Internal Failure	FAIL CAUSE:
Comments on MIT:	Well will not hold pressure. 4 attempts to pressure up.		
<b>J L KEEL B No.007</b>		<b>30-015-05108-00-00</b>	
	Active Injection - (All Types)		C-8-17S-31E
Test Date:	4/11/2016	Permitted Injection PSI:	Actual PSI: 1380
Test Reason:	5-year Test	Test Result: F	Repair Due: 7/15/2016
Test Type:	Std. Annulus Pres. Test	FAIL TYPE: Other Internal Failure	FAIL CAUSE:
Comments on MIT:	Well will not hold pressure. After dumping in 20 bbls, well went on vacuum.		

**J L KEEL B No.012****30-015-05111-00-00**

## Active Injection - (All Types)

A-8-17S-31E

Test Date: 4/11/2016 Permitted Injection PSI: Actual PSI:  
 Test Reason: 5-year Test Test Result: F Repair Due: 7/15/2016  
 Test Type: Std. Annulus Pres. Test FAIL TYPE: Other Internal Failure FAIL CAUSE:  
 Comments on MIT: Well will not hold pressure.

**SKELLY UNIT No.063****30-015-05317-00-00**

## Active Injection - (All Types)

E-21-17S-31E

Test Date: 4/12/2016 Permitted Injection PSI: Actual PSI: 1340  
 Test Reason: 5-year Test Test Result: F Repair Due: 7/16/2016  
 Test Type: Std. Annulus Pres. Test FAIL TYPE: Other Internal Failure FAIL CAUSE:  
 Comments on MIT: Well will not hold pressure.

**SKELLY UNIT No.075****30-015-05333-00-00**

## Active Injection - (All Types)

N-21-17S-31E

Test Date: 4/25/2016 Permitted Injection PSI: Actual PSI:  
 Test Reason: Annual IMIT Test Result: F Repair Due: 7/29/2016  
 Test Type: Bradenhead Test FAIL TYPE: Other Internal Failure FAIL CAUSE:  
 Comments on MIT: No guage on tubing. Continuous flow from casing.

**SKELLY UNIT No.052****30-015-05345-00-00**

## Active Injection - (All Types)

J-22-17S-31E

Test Date: 4/12/2016 Permitted Injection PSI: Actual PSI: 1260  
 Test Reason: 5-year Test Test Result: F Repair Due: 7/16/2016  
 Test Type: Std. Annulus Pres. Test FAIL TYPE: Other Internal Failure FAIL CAUSE:  
 Comments on MIT: Well would not pressure-up. Took 12 bbls to load.

**SKELLY UNIT No.088****30-015-05426-00-00**

## Active Injection - (All Types)

A-28-17S-31E

Test Date: 4/25/2016 Permitted Injection PSI: Actual PSI:  
 Test Reason: Annual IMIT Test Result: F Repair Due: 7/29/2016  
 Test Type: Bradenhead Test FAIL TYPE: Permit Violation FAIL CAUSE:  
 Comments on MIT: Original failure on 4/8/2015. Not repaired from previous failure. Out of compliance over 1 year.

**TURNER B No.047****30-015-05435-00-00**

## Active Injection - (All Types)

B-29-17S-31E

Test Date: 4/12/2016 Permitted Injection PSI: Actual PSI: 1430  
 Test Reason: 5-year Test Test Result: F Repair Due: 7/16/2016  
 Test Type: Std. Annulus Pres. Test FAIL TYPE: Other Internal Failure FAIL CAUSE:  
 Comments on MIT: Well will not hold pressure.

**TURNER B No.068****30-015-05452-00-00**

## Active Injection - (All Types)

P-29-17S-31E

Test Date: 4/13/2016 Permitted Injection PSI: Actual PSI:  
 Test Reason: Annual IMIT Test Result: F Repair Due: 7/17/2016  
 Test Type: Bradenhead Test FAIL TYPE: Permit Violation FAIL CAUSE:  
 Comments on MIT: Repaired? Surface is cemented. No paperwork on repair.  
 Original failure on 5/5/2015. Not repaired from previous failure. Out of compliance over 1 year.

**TURNER B No.053****30-015-05472-00-00**

## Active Injection - (All Types)

I-30-17S-31E

Test Date: 4/13/2016 Permitted Injection PSI: Actual PSI:  
 Test Reason: Annual IMIT Test Result: F Repair Due: 7/17/2016  
 Test Type: Bradenhead Test FAIL TYPE: Other Internal Failure FAIL CAUSE:  
 Comments on MIT: Guage reads 3300psi on tubing, (assume it is broken.) Continuous blow of fluid from casing.

**NORTH BENSON QUEEN UNIT No.025****30-015-10127-00-00**

Active Injection - (All Types)

N-28-18S-30E

Test Date: 4/13/2016 Permitted Injection PSI: Actual PSI:  
 Test Reason: Annual IMIT Test Result: F Repair Due: 7/17/2016  
 Test Type: Bradenhead Test FAIL TYPE: Permit Violation FAIL CAUSE:  
 Comments on MIT: Original failure on 2/17/2015. Not repaired from previous failure. Out of compliance over 1 year.

**SKELLY UNIT No.107****30-015-20410-00-00**

Active Injection - (All Types)

E-27-17S-31E

Test Date: 4/25/2016 Permitted Injection PSI: Actual PSI:  
 Test Reason: Annual IMIT Test Result: F Repair Due: 7/29/2016  
 Test Type: Bradenhead Test FAIL TYPE: Permit Violation FAIL CAUSE:  
 Comments on MIT: Original failure on 4/8/2015. Not repaired from previous failure. Out of compliance over 1 year.

**RED LAKE UNIT No.016****30-015-23122-00-00**

Active Injection - (All Types)

O-25-16S-28E

Test Date: 4/13/2016 Permitted Injection PSI: Actual PSI:  
 Test Reason: Annual IMIT Test Result: F Repair Due: 7/17/2016  
 Test Type: Bradenhead Test FAIL TYPE: Permit Violation FAIL CAUSE:  
 Comments on MIT: Original failure on 2/17/2015. Not repaired from previous failure. Out of compliance over 1 year.

**RED LAKE UNIT No.012****30-015-24016-00-00**

Active Injection - (All Types)

I-25-16S-28E

Test Date: 4/13/2016 Permitted Injection PSI: Actual PSI:  
 Test Reason: Annual IMIT Test Result: F Repair Due: 7/17/2016  
 Test Type: Bradenhead Test FAIL TYPE: Permit Violation FAIL CAUSE:  
 Comments on MIT: Original failure on 2/17/2015. Not repaired from previous failure. Out of compliance over 1 year.

**J L KEEL B No.034****30-015-25447-00-00**

Active Injection - (All Types)

H-6-17S-31E

Test Date: 4/11/2016 Permitted Injection PSI: Actual PSI: 1250  
 Test Reason: Annual IMIT Test Result: F Repair Due: 7/15/2016  
 Test Type: Bradenhead Test FAIL TYPE: Other Internal Failure FAIL CAUSE:  
 Comments on MIT: Took a while to load, but would not hold pressure.

**J L KEEL B No.037****30-015-25934-00-00**

Active Injection - (All Types)

E-5-17S-31E

Test Date: 4/11/2016 Permitted Injection PSI: Actual PSI: 1450  
 Test Reason: 5-year Test Test Result: F Repair Due: 7/15/2016  
 Test Type: Std. Annulus Pres. Test FAIL TYPE: Other Internal Failure FAIL CAUSE:  
 Comments on MIT: Well is leaking from cap. Need to replace gasket and re-test..

**TURNER A No.057****30-015-29000-00-00**


Active Injection - (All Types)

C-19-17S-31E

Test Date: 4/14/2016 Permitted Injection PSI: Actual PSI:  
 Test Reason: Annual IMIT Test Result: F Repair Due: 7/18/2016  
 Test Type: Bradenhead Test FAIL TYPE: Permit Violation FAIL CAUSE:  
 Comments on MIT: Original failure on 3/25/2015. Not repaired from previous failure. Out of compliance over 1 year. Part of WFX946 implementation.

In the event that a satisfactory response is not received to this letter of direction by the "Repair Due:" date shown above, or if the well(s) are not immediately shut-in, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well.

Sincerely,

  
Artesia OCD District Office

Note: Pressure Tests are performed prior to initial injection, after repairs and otherwise, every 5 years; Bradenhead Tests are performed annually. Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data. "Failure Type" and "Failure Cause" and any Comments are not to be interpreted as a diagnosis of the condition of the wellbore. Additional testing should be conducted by the operator to accurately determine the nature of the actual failure. \* Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas.