Submit 1 Copy To Appropriate District Office	State of New Mexico	Form C-103
District I - (575) 393-6161	Energy, Minerals and Natural Resources	Revised July 18, 2013
1625 N. French Dr., Hobbs, NM 88240 District II – (575) 748-1283		WELL API NO. 30-015-22759
811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION	5. Indicate Type of Lease
<u>District III</u> - (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.	STATE FEE
District IV - (505) 476-3460	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505		
	FICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
	OSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A JCATION FOR PERMIT" (FORM C-101) FOR SUCH	Williams 35 Com
PROPOSALS.)		0 W IIN 1 4004
1. Type of Well: Oil Well	Gas Well 🛛 Other	8. Well Number #001
2. Name of Operator	ommoo Oil Connection	9. OGRID Number
Penroc Oil Corporation 3. Address of Operator		17213 10. Pool name or Wildcat
PO Box 2769 Hobbs, NM 88241- 2769		Culebra Bluff Strawn
4. Well Location		
Unit Letter C:	660 feet from theN line and	2310 feet from the W line
Section 35	Township 23S Range 28E	NMPM Eddy County
Section 33	11. Elevation (Show whether DR, RKB, RT, GR, etc.	
	111 210 1110 (010) 111, 111, 111, 111, 111, 111, 111,	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK	- · · · · · · · · · · · · · · · · · · ·	-
TEMPORARILY ABANDON PULL OR ALTER CASING		ILLING OPNS.□ PAND A □∷ IT JOB □
DOWNHOLE COMMINGLE	- <u>-</u>	11 30B
CLOSED-LOOP SYSTEM		
OTHER:	☐ OTHER:	
	pleted operations. (Clearly state all pertinent details, an	
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of		
proposed completion or recompletion. Penroc proposes to PA as followsNo carthpits will be constructed. Well fluids will be circulated to steel pits		
Please see attached well data and PA procedure		
	Approved for plugging of well bore only. Liability under bond is retained pending receipt	MBE
	of C-103 (Subsequent Report of Well Plugging)	NM OIL CONSERVATIO
	which may be found at OCD Web Page under Forms, www.cmnrd.state.nm.us/ocd.	DISTRICT
		JUL 1 8 2016
		2010
		RECEIVED
Spud Date:	Rig Release Date:	TOESVED.
1 St. 1 SAUGE TO BE	PLUCEED BY 7/19/201:	
I hereby certify that the informatio	n above is true and complete to the best of my knowledge	ge and belief.
1.	0 () (1)	, ,
SIGNATURE BILLIC	Trucker TITLE Agent for Penroc Oil	DATE 7/8//6
Type or print name Billy E. Pricha	erd E-mail address: billy@pwllc.i	net PHONE: 432-934-7680
For State Use Only		
1/1 + 0 //		
APPROVED BY: flet live	Legiel TITLE COMPLIAMOR OFFI	DATE 7/19/2016
Conditions of Approval (if any):		

ST SEE ATTACHED COA-S

Penroc Oil Corporation Williams 35 Com # 1 API 30-015-22759 Unit Letter "C", Section 35, T23S, R28E Eddy County, NM

Well Data

Spud 12/14/1978

13 3/8" 54.5# CSA 506'. Cmt w/650 sks cmt. Cmt circ. to surface. 9 5/8" 36# CSA 2505'. Cmt w/1700 sks cmt. Cmt circ. to surface. 7" 26# CSA 11012'. Cmt w/1450 sks cmt. TOC 3464' calculated w/50%fill. 4 $\frac{1}{2}$ " Liner set 13100' Top of liner at 10799'. Cmt w/310 sks. Cmt circulated to top of liner. Atoka perfs 11754'-11761' Packer set 11700' with Blanking plug Strawn perfs 11446'-11604'

Delaware 2650'
Bone Spring 7045' - 47H PM3
Wolfcamp 9952' > 3μρ PM3
Penn 11028' ν λμρ PM3
Strawn 11178' ν 1μο PM3
Atoka 11415' ν / 57 PM6
Morrow 12092'

PA Procedure

THE PACHER WITH BLANKING PLUG

Spot 30 sks cement plug x WOC x Tag cmt PLUG AT 1/390' OR ABOVE

Displace well with gelled brine water

Spot 35 sks cmt plug at 18849' x WOC x tag cmt plug at 18849 or above -//062 TO 10,962'

Spot 35 sks cmt plug at 10002'

Spot 35 sks cmt plug at 10002'

Spot 35 sks cmt plug at 1000' TO 7000'

Spot 35 sks cmt plug at 1000'-FILLEN PLUG

Perf and squeeze at 2555' with 35 sks cmt

WOC x tag cmt plug at 2455' or above

Perf at 556' x Circulate cement to the surface x Leave 7" casing full of cement

Remove well head and install PA marker

<u>CURRENT</u> WELLBORE DIAGRAM

7/8/16 By: BEP Created: Updated: By: Williams 35 Com Well No.: Culebra Bluff (South) Lease: Field: Surface Location: 660' FNL & 2310' FWL Unit Ltr: TSHP/Range: 23S/28E Sec: Unit Ltr: TSHP/Range: **Bottomhole Location:** Sec: County: Eddy St: NM API: 30-015-22759 St Lease: Current Status: Prodcer 3018' GL Elevation: Surface Csg. KB: 3033' Size: 13 3/8" DF: Wt.: 54.5# K-55 GL: 3018 Set @: 506' Spud Date: 12/14/78 Sxs cmt: 650 Compl. Date: 2/23/79 Circ: yes TOC: surface, 36 sx Hole Size: 17 1/2" Intermediate Csg. Size: 9 5/8" Wt.: 36# K-55 2505' Set @: Sxs Cmt: 1700 yes, 360 sx Circ: surface TOC: 12 1/4" Hole Size: Production Csg. Size: 23# & 26# S-95 Wt.: Set @: 11,012 Sxs Cmt: 1,450 TOC: 3464' Calc @ 50% Fillup Hole Size: 8 1/2" Strawn Perfs: 11,446'-11,604' **Production Liner** Guiberson Magnum GT Packer @ 11,700' Size: 4-1/2" Tailpipe Perforated at 11,715'-11,717' Wt.: 13.5#, N-80 Blanking Plugs @ 11,717 & 11,728 TOL 10,799 Atoka Perfs: 11,754'-11,761' BOL 13,100 Cement 310 sx

www.pwllc.net

BEP

<u>PA</u> WELLBORE DIAGRAM

7/8/16 By: BEP Created: Updated: By: Williams 35 Com Lease: Well No.: Culebra Bluff (South) Field: TSHP/Range: 23S/28E Surface Location: 660' FNL & 2310' FWL Unit Ltr: Sec: TSHP/Range: **Bottomhole Location:** Unit Ltr: Sec: County: Eddy St: NM St Lease: API: 30-015-22759 Current Status: Prodcer 3018' GL Elevation: Surface Csg. KB: 3033' Size: 13 3/8" DF: Wi: 54.5# K-55 GL: 3018 Set @: 5061 Spud Date: 12/14/78 Sxs cmt: 650 Compl. Date: 2/23/79 Circ: yes TOC: surface, 36 sx Hole Size: 17 1/2" Intermediate Csg. 9 5/8" MLF Size: Wi.: 36# K-55 2505 Set @: Sxs Cmt: 1700 yes, 360 sx Circ: TOC: surface Hole Size: 12 1/4" Production Csg. Size: 23# & 26# S-95 Wt.: Set @: 11,012 1,450 Sxs Cmt: TOC: 3464' Calc @ 50% Fillup 8 1/2" Hole Size: 11,062 woe & TAC MLF Strawn Perfs: 11,446'-11,604' woe & TAG **Production Liner** Guiberson Magnum GT Packer @ 11,700 Size: 4-1/2° Tailpipe Perforated at 11,715'-11,717' Wt.: 13.5#, N-80 Blanking Plugs @ 11,717' & 11,728' TOL 10,799' Atoka Perfs: 11,754'-11,761' BOL 13,100 Cement 310 sx

BEP

www.pwllc.net

CONDITIONS FOR PLUGGING AND ABANDONMENT

DISTRICT II / ARTESIA

The following is a guide or checklist in preparation of a plugging program, this is not all inclusive and care must be exercised in establishing special plugging programs in unique and unusual cases

- 1. Notify NMOCD District Office II at (575)-748-1283 at least 24 hours before beginning work.
- 2. Closed loop system is to be used for entire plugging operation. Upon completion, contents of steel pits are to be hauled to a permitted disposal location.
- 3. Trucking companies being used to haul oilfield waste fluids to a disposal commercial or private shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator as well as the contractor, to verify that this permit is in place prior to performing work. Drivers shall be able to produce a copy upon request of an NMOCD Field inspector.
- Filing a subsequent C-103 will serve as notification that the well has been plugged.
- A final C-103 shall be filed (and a site inspection by NMOCD Inspector to determine if the location is satisfactorily cleaned, all equipment, electric poles and trash has been removed to Meet NMOCD standards) before bonding can be released.
- 6. Squeeze pressures are not to exceed 500 psi, unless approval is given by NMOCD.
- 7. Produced water will not be used during any part of the plugging operation.
- 8. Mud laden fluids must be placed between all cement plugs mixed at 25 sacks per 100 bbls of water.
- 9. All cement plugs will be a minimum of 100' in length or a minimum of 25 sacks of cement, whichever is greater. 50' of calculated cement excess required for inside casing plugs and 100% calculated cement excess required on outside casing plugs.
- 10. Class 'C' cement will be used above 7500 feet.
- 11. Class 'H' cement will be used below 7500 feet.
- 12. A cement plug is required to be set 50' above and 50' below, all casing shoes, casing stubs, DV tools, attempted casing cut offs, salt sections and anywhere the casing is perforated, these plugs require a 4 hour WOC and then will be tagged
- 13. When setting the top out cement plug in production, intermediate and surface casing, wellbores should remain full at least 30 minutes after plugs are set
- 14. A CIBP is to be set within 100' of production perforations, capped with 100' of cement, WOC 4 hours and tag.
- 15. A CIBP with 35' of cement may be used in lieu of the 100' plug if set with a bailer. This plug will be placed within 100' of the top perforation, (WOC 4 hrs and tag).
- 16. No more than 3000' is allowed between cement plugs in cased hole and 2000' in open hole.
- 17. Formations to be isolated with cement plugs are:
 - A) Fusselman
 - B) Devonian
 - C) Morrow

- D) Wolfcamp
- E) Bone Springs
- F) Delaware
- G) Any salt sections
- H) Abo
- I) Glorieta
- J) Yates.
- K) Potash--- (In the R-111-P Area (Potash Mine Area), a solid cement plug must be set across the salt section. Fluid used to mix the cement shall be saturated with the salts that are common to the section penetrated and in suitable proportions, not more than 3% calcium chloride (by weight of cement) will be considered the desired mixture whenever possible, WOC 4 hours and tag, this plug will be 50' below the bottom and 50' above the top of the Formation.
- 18. If cement does not exist behind casing strings at recommended formation depths, the casing can be cut and pulled with plugs set at recommended depths. If casing is not pulled, perforations will be shot and cement squeezed behind casing, cement will be set 50' below to 50' above perforation inside the casing

DRY HOLE MARKER REQUIRMENTS

The operator shall mark the exact location of the plugged and abandoned well with a steel marker not less than four inches in diameter, 3' below ground level with a plate of at least ¼" welded to the top of the casing and the dry hole marker welded on the plate with the following information welded on the dry hole marker:

- 1. Operator name
- 2. Lease and well number
- 3. API number
- 4. Unit letter
- 5. Quarter section (feet from North, South, East or West)
- 6.Section, Township and Range
- 7. Plugging date
- 8. County

(SPECIAL CASES)

AGRICULTURE OR PRARIE CHICKEN BREEDING AREAS

In these areas, a below ground marker is required with all pertinent information mentioned above on a plate, set 3' below ground level, a picture of the plate will be supplied to NMOCD for record, the exact location of the marker (longitude and latitude be GPS) will be provided to NMOCD (We typically require a current survey to verify the GPS)