÷	\cap		()				
				Operator Copy OMB NO. 1004-0137 Expires: January 31, 2018			
SUNDRY Do not use the abandoned we	enter an		5. Lease Serial No. NMLC051783A 6. If Indian, Allottee or Tribe Name				
SUBMIT IN				ent, Name and/or No.			
1. Type of Well D Oil Well D Gas Well D Oil			8. Well Name and No. EMPIRE ABO K 8				
2. Name of Operator APACHE CORPORATION	DSON orp.com		9. AFI Well No. 30-015-00774-00-S1				
303 VETERANS AIRPARK LANE SUITE 3000 Ph: 432.81 MIDLAND, TX 79705			. (include area con 8.1142	ic)	10. Field and Pool or Exploratory Area EMPIRE		
4. Location of Well (Foolage, Sec., 7			11. County or Parish, State				
Sec 4 T18S R27E NESE 1650			EDDY COUNTY, NM				
12. CHECK THE AI	PROPRIATE BOX(ES)	TO INDICA	TE NATURE	OF NOTICE	, REPORT, OR OTHE	R DATA	
TYPE OF SUBMISSION							
Notice of Intent		Dee	-	-	•	Water Shut-Off	
Subsequent Report	Alter Casing Casing Repair		raulic Fracturin Construction			Well Integrity	
Final Abandonment Notice	Change Plans				Recomplete Other Temporarily Abandon		
-	Convert to Injection		- •		•		
13. Describe Proposed or Completed Op If the proposal is to deepen direction Attach the Bond under which the wo following completion of the involved testing has been completed. Final Al determined that the site is ready for f	ally or recomplete horizontally, rk will be performed or provide l operations. If the operation re bandonment Notices must be fil	give subsurface the Bond No. or sults in a multipl	locations and mer n file with BLM/E le completion or n	asured and true value of the sured and true value of the sure of t	ertical depths of all pertinen bsequent reports must be fil new interval, a Form 3160-4 m, have been completed and	t markers and zones. ad within 30 days must be filed once the operator has	
Apache would like to perform	the following work: Pieas	e see attachn	nents.		MAN OIL O	340-	
Objective: TA wellbore and ev	· · · ·	d for reco NOCD LI	ARTES	DISERVIATION			
Procedure: 1. POOH with rods and pump 2. Release TAC and scan tbg	, laying them down out of the hole, mark the	good the and	scrap the resi	2/13/17		- U ZUI/	
3. Rig up wireline ? Set CIBP @ 5.370? w/ 35? :	cmt			-	SEE ATTAGHE	D FOR	
4. Fill casing with 2% KCL flui 5. Schedule a test and record 6. Turn in to OCD for TA appr			CONDITIONS)F Approval			
14. I hereby certify that the foregoing is	# Electronic Submission For APACHI	356709 verifie E CORPORAT	d by the BLM W ION, sent to the	vell information e Carisbad	n System		
Committed to AFMSS for processing by DEBO Name (Printed/Typed) ISABEL HUDSON				ANALYST	6 (17DLM01385E)		
Signature (Electronic S	(ubmiceion)		Data dd 104	mo4e			
Service (Skendule 2	THIS SPACE FC	DR FEDERA	Date 11/01		SE		
	00			SPET		2-7-1	
Approved By Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon. Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any pe			Title	3701		Date	
				<u>CAD</u>			
States any false, fictitious or fraudulent s	statements or representations as	to any matter wi	ithin its jurisdictio	n	and to any department of age	acy of the United	

*** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED **

rche

1


November 1, 2016

Empire ABO Unit # K-8 API # 30-015-00774 Eddy County, NM Producing Interval: 5,400-74'; 5,502-52' 4-1/2" csg @ 5,621'

Objective: TA wellbore and evaluate well for future re-completion

Procedure:

- 1. POOH with rods and pump, laying them down
- 2. Release TAC and scan tbg out of the hole, mark the good tbg and scrap the rest
- 3. Rig up wireline
 - Set CIBP @ 5,370' w/ 35' cmt
- 4. Fill casing with 2% KCL fluid and pressure test plug to 500 psi
- 5. Schedule a test and record the chart
- 6. Turn in to OCD for TA approval





Temporary Abandonment of Wells on Federal Lands Conditions of Approval

A temporarily abandoned well is defined as a completion that is not capable of production in paying quantities but which may have value as a service well. Pursuant to 43 CFR 3162.3-4 (c), no well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer.

Temporary Abandonment (TA) status approval requires a successful mechanical or casing integrity test as follows:

- 1. A Notice of Intent (NOI) Sundry Notice (Form 3160-5) requesting approval to run a mechanical integrity test (MIT) or casing integrity test (CiT).
- 2. A description of the temporary abandonment procedure.

a. A bridge plug or packer must be installed as close to 50 feet above any open perforations or open hole as possible. The bridge plug is to be capped with 35 feet of cement (if balled) or 25 sacks (if placed with tubing). If a cement plug is used, the top of the cement must be verified by tagging.

b. The wellbore must be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes with a 10% allowable leakoff.

c. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if they are not isolated by a packer.

d. A bradenhead test must be conducted. If the test indicates a problem exists, a remedial plan and time frame for remediation shall be submitted within ninety (90) days of the test.

e. Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Eddy County, 575-361-2822; Lea County 575-393-3612.

 Provides justification why the well should be temporarily abandoned rather than permanently plugged and abandoned and an estimated date that the well will be returned to beneficial use or plugged and abandoned.

Wells that successfully pass the casing integrity test may be approved for Temporary Abandonment (TA) status provided that the operator:

- 1. Submits a subsequent Sundry Notice (Form 3160-5) requesting TA approval with well bore diagram.
- 2. Describes the temporary abandonment procedure.
- 3. Attaches a clear copy or the original of the pressure test chart.
- 4. Give justification to allow well to be place in TA status and plan for future use of well with time frame that well will be place back on line or plans to P&A well will be submitted.

If the well does not pass the casing integrity test, then the operator shall within 30 days submit to BLM for approval one of the following:

1. A procedure to repair the casing so that a TA approval can be granted.

2. A procedure to plug and abandon the well.

Well Name: Submit Subsequent Report and well bore diagram with all Perforations and CIBP with tops of cement. Well may be approved to be TA for a period of 1 year after successful MIT and subsequent report is submitted.