

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

JUL 12 2018

Form C-141
Revised April 3, 2017

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
DISTRICT II-ARTESIA 0101 with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1819453408

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company Devon Energy Production Company 1037	Contact Aaron Kidd, Technical Services Foreman
Address 6488 Seven Rivers Hwy Artesia, NM 88210	Telephone No. 575-748-3371
Facility Name Cotton Draw Unit 89	Facility Type Salt Water Disposal

Surface Owner Federal	Mineral Owner Federal	API No. 30-015-31381
-----------------------	-----------------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	3	25S	31E					Eddy

Latitude 32.153094 N Longitude 103.763271 W NAD83

NATURE OF RELEASE

Type of Release Oil	Volume of Release 66 Bbls	Volume Recovered 66 Bbls
Source of Release Pipeline below belly of oil tank	Date and Hour of Occurrence 6/27/2018 @ 1:30 AM MST	Date and Hour of Discovery 6/27/2018 @ 1:30 AM MST
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? NMOCD-Mike Bratcher and Crystal Weaver BLM-Shelly Tucker	
By Whom? Mike Shoemaker	Date and Hour 6/27/2018 @ 9:20 PM MST	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.*
N/A

Describe Cause of Problem and Remedial Action Taken.*

The lease operator went to the site to check pumps and upon arrival found a spill inside the lined containment. Upon further inspection a hole was found in the belly line underneath the oil tank

Describe Area Affected and Cleanup Action Taken.*

Approximately 66bbls of oil was released into the lined SPCC containment ring. A vacuum truck was dispatched and recovered approximately 66bbls of oil from lined containment. All fluid stayed inside the lined SPCC containment. Once fluids were removed the liner was visually inspected by Devon field staff for any pinholes or punctures and none were found. Based on this inspection there is no evidence that the spill fluids left containment.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Tamala J. Robison</i>		OIL CONSERVATION DIVISION	
Printed Name: Tamala J Robison		Approved by Environmental Specialist <i>[Signature]</i>	
Title: Field Admin Support		Approval Date: 7/13/18	Expiration Date: N/A
E-mail Address: Tamala.Robison@dvn.com		Conditions of Approval:	
Date: 6/28/2018 Phone: 575-748-3371		Attached <i>7RP-4859</i>	

FINAL

Attached

7RP-4859

* Attach Additional Sheets If Necessary