Form 3160-5 (June 2015)

# UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 201	COPY
Carial Na	

BUREAU OF LAND MANAGEMENT					5. Lease Serial No. NMI C062052	5. Lease Serial No. NMLC062052			
SUNDRY NOTICES AND REPORTS ON WELLS  Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.						6. If Indian, Allottee or Tribe Name			
SUBMIT IN TRIPLICATE - Other instructions on page 2					7. If Unit or CA/Agre	7. If Unit or CA/Agreement, Name and/or No.			
1. Type of Well ☐ Oil Well ☐ Gas Well ☑ Other: INJECTION					8. Well Name and No TAMANO (BSSC	8, Well Name and No. TAMANO (BSSC) UNIT 704			
Name of Operator Contact: JOHN SAENZ     LEGACY RESERVES OPERATING LÆ-Mail: jsaenz@legacylp.com					9. API Well No. 30-015-25893				
3a. Address 303 W WALL ST STE 1800 MIDLAND, TX 79701	b. Phone No. (include area code) Ph: 432-689-5200			TAMANO					
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)					11. County or Parish, State				
Sec 11 T18S R31E SWNE 2310FNL 2310FEL					EDDY CO COUNTY, NM				
·· ·· · · · · · · · · · · · · · · · ·				· 					
12. CHECK THE AF	PROPRIATE BOX(ES) T	O INDICA	ΓΕ NATURE	OF NOT	ICE, REPORT, OR OT	HER DA	ATA		
TYPE OF SUBMISSION	TYPE OF ACTION								
Notice of Intent	☐ Acidize	Deep	en	□ Pı	roduction (Start/Resume)	□ Wa	iter Shut-Off		
	☐ Alter Casing	☐ Hyd	raulic Fracturi	ng 🗖 R	eclamation	_	ell Integrity		
☐ Subsequent Report	□ Casing Repair	□ New	Construction	_	☐ Recomplete				
☐ Final Abandonment Notice	☐ Change Plans	Plug	and Abandon		emporarily Abandon				
Convert to Injection Plug Back  3. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starti				/ater Disposal					
Attach the Bond under which the wor following completion of the involved testing has been completed. Final Attach the testing has been completed. Final Attach the site is ready for final to convert to producer.  Drill out CIBP and acidize. Re	operations. If the operation resu- pandonment Notices must be filed inal inspection.  turn well to production.	its in a multipli only after all i	a completion or	recombletio	amation, have been completed	and the op	ATION		
No.					ARTESIA	ARTESIA DISTRICT  JUL 3 0 2018			
Accepted for record · NMOCD									
					REC	CEIVE	J		
14. I hereby certify that the foregoing is	s true and correct. Electronic Submission #42 For LEGACY RESE	8780 verifie RVES OPER	d by the BLM ATING LP, se	Well Information	mation System arlsbad				
Name (Printed/Typed) JOHN SA	ENZ		Title OPE	RATIONS	S ENGINEER				
		, .							
Signature (Electronic S				5/2018		-			
	THIS SPACE FOR	R FEDERA	L OR STAT	TE OFFIC	CE USE				
Approved By		-	Title		·	<u> </u>	Date		
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease			Office						
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent	U.S.C. Section 1212, make it a cr statements or representations as to	rime for any pe o any matter w	rson knowingly ithin its jurisdict	and willfull	ly to make to any department o	r agency o	f the United		

#### Tamano Unit # 704 (BSSC), API: 30-015-25893

#### Well Summary & Objective:

The subject well is temporarily abandoned. The well was an injector, which is being converted to a producer. The 53 ft. of perforations are in the Bone Spring Second Carbonate. They will be acidized with about 150 gallons of acid per foot.

- 1. Rig Up Pulling Unit.
- 2. Pick up work string 2 7/8" and 4 3/4" drill bit.
- 3. Drill out cement and CIBP at 7,957'.
- 4. Go to 8,180' to verify that there is no fill in the wellbore across the perforations.
- 5. Set packer at 8,000'.
- 6. Pressure test backside 500 #.
- 7. Pickle tubing with 500 gal acid.
- 8. Flush with 50 bbl water.
- 9. Acid treat perfs in 3 stages: Use 8,000 gal 15 % NEFE HCl acid. Use 1000# rock salt. Rate is 6-10 bpm. Target rate is 8 bpm. Max pressure is 4,000 psi.
  - a. 1st stage, pump 2,000 gal acid.
  - b. 400 # rock salt in brine water.
  - c. 2nd stage, use 3,000 gal acid.
  - d. 500 # rock salt in brine water.
  - e. 3rd stage, use 3,000 gal acid.
  - f. Switch to fresh water. Flush with 50 bbl fresh water at 8 bpm.
  - g. Obtain ISIP after 5, 10, 15 min.
  - h. Shut down for 2 hours.
- 10. Flush with 200 bbl fresh water.
- 11. Swab back 500 bbl.
- 12. Release packer, TOH.
- 13. TIH with bit. Clean out to 8,180'.
- 14. Lay down work string. RIH with production string.
- 15. Install AL equipment per field foreman directions.
- 16. Rig down and RTP.



### TAMANO (BSSC) UNIT #704

LOCATION: 2310' FNL & 2310' FEL, Sec 11, T18S, R31E

Wellbore

FIELD: Tamano (Bone Spring)

COUNTY: Eddy

STATE: New Mexico

GL: 3743'


KB: 3758'

SPUD DATE: 5/28/1988

LATEST UPDATE: 8/28/2015

BY: CSPARKMAN

API No: 30-015-25893





## TAMANO (BSSC) UNIT #704

LOCATION: 2310' FNL & 2310' FEL, Sec 11, T18S, R31E

Proposed Wellbore

FIELD: Tamano (Bone Spring)

COUNTY: Eddy

STATE: New Mexico

GL: 3743' KB: 3758'

SPUD DATE: 5/28/1988

LATEST UPDATE: 10/2/2015

15% HCI

BY: CSPARKMAN

API No: 30-015-25893

