
	State of New Me		Form C-103
Office District I – (575) 393-6161	575) 393-6161 Energy, Minerals and Natural Resources		Revised July 18, 2013
1625 N. French Dr., Hobbs, NM 88240			WELL API NO.
<u>District II</u> - (575) 748-1283	OIL CONSERVATION	DIVISION	30-015-22023
811 S. First St., Artesia, NM 88210 District III – (505) 334-6178	1220 South St. Fr		5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410	_	-	STATE FEE
<u>District IV</u> $-$ (505) 476-3460	Santa Fe, NM 87		6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	DISTRIC	T II-ARTESIA O.C.D	K-6653
SUNDRY NO	FICES AND REPORTS ON WELLS OSALS TO DRILL OR TO DEEPEN OR PLU		7. Lease Name or Unit Agreement Name Millman H.D. State Com
	ICATION FOR PERMIT" (FORM C-101) FO		Miniman H.D. State Com
PROPOSALS.) 1. Type of Well: Oil Well	Gas Well 🛛 Other	·	8. Well Number 1
2. Name of Operator			9. OGRID Number
Vanguard Operating LLC		258350	
3. Address of Operator		10. Pool name or Wildcat	
5847 San Felipe Ste 3000 Houston Texas 77057		South Millman (Morrow)	
4. Well Location			
Unit Letter O: 660 feet from the South line and 1980 feet from the East line			
Section 17 Township 19S Range 28E NMPM Eddy County			
11. Elevation (Show whether DR, RKB, RT, GR, etc.)			
3,530 GR			
5,550 GK			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING			
		COMMENCE DRIL	
PULL OR ALTER CASING		CASING/CEMENT	JOB 🗌
DOWNHOLE COMMINGLE	1		
CLOSED-LOOP SYSTEM]		· _
OTHER:		OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date			
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of			
proposed completion or recompletion.			
	ccompletion. ved for P&A but due to lease issues t	he well is requested	
The well has been appro	ved for P&A but due to lease issues t	he well is requested	Notify OCD 24 hrs. prior to
The well has been appro 1. Notify NMOCD	ved for P&A but due to lease issues t 24 hrs before rigging up.	he well is requested	Notify OCD 24 hrs. prior to
The well has been appro 1. Notify NMOCD 2. MIRU WS. LD p	ved for P&A but due to lease issues t 24 hrs before rigging up. production equipment.	-	
The well has been appro 1. Notify NMOCD 2. MIRU WS. LD p 3. RU WL. Set CIB	ved for P&A but due to lease issues t 24 hrs before rigging up. production equipment. 3P at 9,321'(top perf 9,371). Cap with	h 35ft of cement.	Netify OCD 24 hrs . prior to any work done.
The well has been appro 1. Notify NMOCD 2. MIRU WS. LD p 3. RU WL. Set CIB 4. Fill casing with t	ved for P&A but due to lease issues t 24 hrs before rigging up. production equipment. 3P at 9,321'(top perf 9,371). Cap with reated water and pressure test casing	h 35ft of cement. to 500 psig for thirty	Notify OCD 24 hrs . prior to any work done.
The well has been appro 1. Notify NMOCD 2. MIRU WS. LD p 3. RU WL. Set CIB 4. Fill casing with t Open all casing w	ved for P&A but due to lease issues t 24 hrs before rigging up. production equipment. 3P at 9,321'(top perf 9,371). Cap with reated water and pressure test casing valves (bradenhead and intermediate)	h 35ft of cement. to 500 psig for thirty during the internal p	Metify OCD 24 hrs . prior to any work done.
The well has been appro 1. Notify NMOCD 2. MIRU WS. LD p 3. RU WL. Set CIB 4. Fill casing with t Open all casing w change occurring	ved for P&A but due to lease issues t 24 hrs before rigging up. production equipment. 3P at 9,321'(top perf 9,371). Cap with reated water and pressure test casing	h 35ft of cement. to 500 psig for thirty during the internal p diately after the 30 p	Motify OCD 24 hrs . prior to any work done.
The well has been appro 1. Notify NMOCD 2. MIRU WS. LD p 3. RU WL. Set CIB 4. Fill casing with t Open all casing w change occurring 5. RD WS & WL	ved for P&A but due to lease issues t 24 hrs before rigging up. oroduction equipment. 3P at 9,321'(top perf 9,371). Cap with reated water and pressure test casing valves (bradenhead and intermediate) g immediately before, during or imme	h 35ft of cement. to 500 psig for thirty during the internal p diately after the 30 n TA st	Metify OCD 24 hrs . prior to any work done.
The well has been appro 1. Notify NMOCD 2. MIRU WS. LD p 3. RU WL. Set CIB 4. Fill casing with t Open all casing w change occurring 5. RD WS & WL	ved for P&A but due to lease issues t 24 hrs before rigging up. production equipment. 3P at 9,321'(top perf 9,371). Cap with reated water and pressure test casing valves (bradenhead and intermediate)	h 35ft of cement. to 500 psig for thirty during the internal p diately after the 30 n TA st Succe	Netify OCD 24 hrs . prior to any work done.
The well has been appro 1. Notify NMOCD 2. MIRU WS. LD p 3. RU WL. Set CIB 4. Fill casing with t Open all casing w change occurring 5. RD WS & WL	ved for P&A but due to lease issues t 24 hrs before rigging up. oroduction equipment. 3P at 9,321'(top perf 9,371). Cap with reated water and pressure test casing valves (bradenhead and intermediate) g immediately before, during or imme	h 35ft of cement. to 500 psig for thirty during the internal p diately after the 30 of TA st Succe Conta	Notify OCD 24 hrs . prior to any work done.
The well has been appro 1. Notify NMOCD 2. MIRU WS. LD p 3. RU WL. Set CIB 4. Fill casing with t Open all casing w change occurring 5. RD WS & WL	ved for P&A but due to lease issues t 24 hrs before rigging up. oroduction equipment. 3P at 9,321'(top perf 9,371). Cap with reated water and pressure test casing valves (bradenhead and intermediate) g immediately before, during or imme	h 35ft of cement. to 500 psig for thirty during the internal p diately after the 30 of TA st Succe Conta	Notify OCD 24 hrs . prior to any work done.
 The well has been appro Notify NMOCD MIRU WS. LD p RU WL. Set CIB Fill casing with t Open all casing v change occurring RD WS & WL File subsequent 0 	ved for P&A but due to lease issues t 24 hrs before rigging up. production equipment. 3P at 9,321'(top perf 9,371). Cap with reated water and pressure test casing valves (bradenhead and intermediate) g immediately before, during or imme C103 complete with chart.	h 35ft of cement. to 500 psig for thirty during the internal p diately after the 30 n TA st Succe Conta	Notify OCD 24 hrs . prior to any work done.
The well has been appro 1. Notify NMOCD 2. MIRU WS. LD p 3. RU WL. Set CIB 4. Fill casing with t Open all casing w change occurring 5. RD WS & WL	ved for P&A but due to lease issues t 24 hrs before rigging up. oroduction equipment. 3P at 9,321'(top perf 9,371). Cap with reated water and pressure test casing valves (bradenhead and intermediate) g immediately before, during or imme	h 35ft of cement. to 500 psig for thirty during the internal p diately after the 30 n TA st Succe Conta	Netify OCD 24 hrs . prior to any work done.
 The well has been appro Notify NMOCD MIRU WS. LD p RU WL. Set CIB Fill casing with t Open all casing v change occurring RD WS & WL File subsequent 0 	ved for P&A but due to lease issues t 24 hrs before rigging up. production equipment. 3P at 9,321'(top perf 9,371). Cap with reated water and pressure test casing valves (bradenhead and intermediate) g immediately before, during or imme C103 complete with chart.	h 35ft of cement. to 500 psig for thirty during the internal p diately after the 30 n TA st Succe Conta	Notify OCD 24 hrs . prior to any work done.
The well has been appro 1. Notify NMOCD 2. MIRU WS. LD p 3. RU WL. Set CIB 4. Fill casing with t Open all casing with t Open all casing with t Change occurring 5. RD WS & WL 6. File subsequent (Spud Date:	A but due to lease issues to 24 hrs before rigging up. 24 hrs before rigging up. 25 oroduction equipment. 26 at 9,321'(top perf 9,371). Cap with reated water and pressure test casing valves (bradenhead and intermediate) 27 or immediately before, during or immediate) 27 or immediately before, during or immediate) 27 cmplete with chart. 20 cmplete with chart. 20 cmplete Barton Chart.	h 35ft of cement. to 500 psig for thirty during the internal p diately after the 30 n TA st Succe Conta So it m	Notify OCD 24 hrs . prior to any work done.
The well has been appro 1. Notify NMOCD 2. MIRU WS. LD p 3. RU WL. Set CIB 4. Fill casing with t Open all casing with t Open all casing with t Change occurring 5. RD WS & WL 6. File subsequent (Spud Date:	ved for P&A but due to lease issues t 24 hrs before rigging up. production equipment. 3P at 9,321'(top perf 9,371). Cap with reated water and pressure test casing valves (bradenhead and intermediate) g immediately before, during or imme C103 complete with chart.	h 35ft of cement. to 500 psig for thirty during the internal p diately after the 30 n TA st Succe Conta So it m	Notify OCD 24 hrs . prior to any work done.
The well has been appro 1. Notify NMOCD 2. MIRU WS. LD p 3. RU WL. Set CIB 4. Fill casing with t Open all casing with t Open all casing with t Change occurring 5. RD WS & WL 6. File subsequent (Spud Date:	A but due to lease issues to 24 hrs before rigging up. 24 hrs before rigging up. 25 oroduction equipment. 26 at 9,321'(top perf 9,371). Cap with reated water and pressure test casing valves (bradenhead and intermediate) 27 or immediately before, during or immediate) 27 or immediately before, during or immediate) 27 cmplete with chart. 20 cmplete with chart. 20 cmplete Date Date Date Date Date Date Date D	h 35ft of cement. to 500 psig for thirty during the internal p diately after the 30 n TA st Succe Conta So it m	Notify OCD 24 hrs . prior to any work done.
The well has been appro 1. Notify NMOCD 2. MIRU WS. LD p 3. RU WL. Set CIB 4. Fill casing with t Open all casing v change occurring 5. RD WS & WL 6. File subsequent O Spud Date:	A but due to lease issues to 24 hrs before rigging up. 24 hrs before rigging up. 25 or oduction equipment. 39 at 9,321'(top perf 9,371). Cap with reated water and pressure test casing valves (bradenhead and intermediate) 30 or immediately before, during or immediate) 31 or immediately before, during or immediate 32 complete with chart. 33 Rig Release Da 34 nabove is true and complete to the be	h 35ft of cement. to 500 psig for thirty during the internal p diately after the 30 n TA st Succe Conta so it m tte:	Notify OCD 24 hrs . prior to any work done.
The well has been appro 1. Notify NMOCD 2. MIRU WS. LD p 3. RU WL. Set CIB 4. Fill casing with t Open all casing with t Open all casing with t Change occurring 5. RD WS & WL 6. File subsequent (Spud Date:	A but due to lease issues to 24 hrs before rigging up. 24 hrs before rigging up. 25 or oduction equipment. 39 at 9,321'(top perf 9,371). Cap with reated water and pressure test casing valves (bradenhead and intermediate) 30 or immediately before, during or immediate) 31 or immediately before, during or immediate 32 complete with chart. 33 Rig Release Da 34 nabove is true and complete to the be	h 35ft of cement. to 500 psig for thirty during the internal p diately after the 30 n TA st Succe Conta so it m tte:	Notify OCD 24 hrs . prior to any work done.
The well has been appro 1. Notify NMOCD 2. MIRU WS. LD p 3. RU WL. Set CIB 4. Fill casing with t Open all casing with t Signature I hereby certify that the information SIGNATURE	A but due to lease issues to 24 hrs before rigging up. 24 hrs before rigging up. 29 at 9,321'(top perf 9,371). Cap with reated water and pressure test casing valves (bradenhead and intermediate) 3 immediately before, during or imme 2103 complete with chart. 2103 complete with chart. 2103 complete with chart. 2103 complete to the be 2104 mabove is true and complete to the be	h 35ft of cement. to 500 psig for thirty during the internal p diately after the 30 n TA st succe Conta so it m tte:	Netify OCD 24 hrs . prior to any work done.
The well has been appro 1. Notify NMOCD 2. MIRU WS. LD p 3. RU WL. Set CIB 4. Fill casing with t Open all casing v change occurring 5. RD WS & WL 6. File subsequent O Spud Date:	A but due to lease issues to 24 hrs before rigging up. 24 hrs before rigging up. 29 at 9,321'(top perf 9,371). Cap with reated water and pressure test casing valves (bradenhead and intermediate) 3 immediately before, during or imme 2103 complete with chart. 2103 complete with chart. 2103 complete with chart. 2103 complete to the be 2104 mabove is true and complete to the be	h 35ft of cement. to 500 psig for thirty during the internal p diately after the 30 n TA st Succe Conta so it m tte:	Netify OCD 24 hrs . prior to any work done.
The well has been approved the second provide the second provides the second provide the second provides	A but due to lease issues to 24 hrs before rigging up. 24 hrs before rigging up. 29 at 9,321'(top perf 9,371). Cap with reated water and pressure test casing valves (bradenhead and intermediate) 3 immediately before, during or imme 2103 complete with chart. 2103 complete with chart. 2103 complete with chart. 2103 complete to the be 2104 mabove is true and complete to the be	h 35ft of cement. to 500 psig for thirty during the internal p diately after the 30 n TA st succe Conta so it m tte:	Netify OCD 24 hrs . prior to any work done.
The well has been appro 1. Notify NMOCD 2. MIRU WS. LD p 3. RU WL. Set CIB 4. Fill casing with t Open all casing with t Signature I hereby certify that the information SIGNATURE	A but due to lease issues to 24 hrs before rigging up. 24 hrs before rigging up. 29 at 9,321'(top perf 9,371). Cap with reated water and pressure test casing valves (bradenhead and intermediate) 3 immediately before, during or imme 2103 complete with chart. 2103 complete with chart. 2103 complete with chart. 2103 complete to the be 2104 mabove is true and complete to the be	h 35ft of cement. to 500 psig for thirty during the internal p diately after the 30 n TA st succe Conta so it m tte:	Netify OCD 24 hrs . prior to any work done.
The well has been appro 1. Notify NMOCD 2. MIRU WS. LD p 3. RU WL. Set CIB 4. Fill casing with t Open all casing with t State Use Only	A but due to lease issues to 24 hrs before rigging up. production equipment. Pat 9,321'(top perf 9,371). Cap with reated water and pressure test casing valves (bradenhead and intermediate) g immediately before, during or imme C103 complete with chart. Rig Release Da n above is true and complete to the be Composed on the best Composed on the	h 35ft of cement. to 500 psig for thirty during the internal p diately after the 30 n TA st succe Conta so it m te:	Netify OCD 24 hrs . prior to any work done. y minutes. Record pressure chart. pressure tests and report a flow or pressure minute pressure test. atus may be granted after a ct the OCD to schedule after a ct the OCD to schedule the test hay be witnessed. and belief. h@vnrenergy.com PHONE: 432-770-9738
The well has been appro 1. Notify NMOCD 2. MIRU WS. LD p 3. RU WL. Set CIB 4. Fill casing with t Open all casing with t State Use Only	A but due to lease issues to 24 hrs before rigging up. 24 hrs before rigging up. 29 at 9,321'(top perf 9,371). Cap with reated water and pressure test casing valves (bradenhead and intermediate) 3 immediately before, during or imme 2103 complete with chart. 2103 complete with chart. 2103 complete with chart. 2103 complete to the be 2104 mabove is true and complete to the be	h 35ft of cement. to 500 psig for thirty during the internal p diately after the 30 n TA st succe Conta so it m te:	Netify OCD 24 hrs . prior to any work done.

•



CLIANTE MEDICIO MEDICI