Submit 3 Copies To Appropriate District Office	State of New Mexico		Form C-103	
District I	Energy, Minerals and Natural Resources		Revised March 25, 1999 WELL API NO.	
1625 N. French Dr., Hobbs, NM 88240 District II	OV. GOVERNMENT TO VERY WOLOVE		30-005-60127	
811 South First, Artesia, NM 88210	OIL CONSERVATION DIVISION		5. Indicate Type of	of Lease
<u>District III</u> 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.		STATE X	
District IV	Santa Fe, NM 87505		6. State Oil & G	
1220 S. St. Francis Dr., Santa Fe, NM 87505			0. 5	
SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or	Unit Agreement Name:
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH				
PROPOSALS.)		31920 ₂₇	Double L Queen U	Jnit
1. Type of Well:	63671 "	310-05153		
Oil Well Gas Well C	☐ Other INJEC ZU ON	4 8		
2. Name of Operator	\(\beta\)	100 P.	8. Well No.	
Tipton Oil & Gas Acquisitions, Inc.	12 DORE	~ (I) (I)	001	
3. Address of Operator	15 00.	ETVED SO	9. Pool name or V	Vildcat
P.O. Box 1234, Lovington, NM 882		MES/A N/	Double L Queen;	Assoc.
4. Well Location	65	- A3/	-lo	
	feet from the	- 1600		
Unit Letter N :	feet from the	line and	feet fro	m theline
Section 25	Township 14S	Range 20E	NMPM Cł	naves, County
	10. Elevation (Show whether L			77
11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
NOTICE OF IN			SEQUENT REI	
PERFORM REMEDIAL WORK		REMEDIAL WOR		ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DR	ILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	MULTIPLE	CASING TEST A	ND 🗍	, is a control of the
	COMPLETION	CEMENT JOB	<u></u>	
OTHER: RETURN INJECTOR	TO PRODUCER	OTHER:	•	
12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date				
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion				
or recompilation.				
Delegas the frame recommend we have DOOM with the CHI 2d 1 d 1				
Release tbg. from permanent packer. POOH with tbg. GIH with work string and bailer. Knock packer to bottom of hole. POOH with work string and bailer. Run new rods, pump, and tbg. Set pumping unit and commence production.				
r oort with work string and baner. Run new rous, pump, and tog. Set pumping unit and commence production.				
	•			
I haraby cartify that the information	shave is two and complete to the	. h	i 1 i - i · C	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.				
SIGNATURE Delivie	McKelvey_TITLE Agent			_DATE_ 4//7/03
Type or print name	Telephone No.	. 4 4		.,
(This space for State use)	A -	1111	D	
ADDDDOVED DV	m su	co sop c		APR 2 3 2003
APPPROVED BY	TITLE	1		DALE: * * CAAA