Wellbore Diagram

r263

30-015-34627-00-00

EAST MILLMAN POOL UNIT No. 009T

Company Name: STEPHENS & JOHNSON OP CO

Location: Sec: 12 T: 19S R: 28E Spot:

Lat: 32.6717727450081 Long: -104.135109164296 **Property Name:** EAST MILLMAN POOL UNIT

County Name: Eddy

String Information

Cement Information

Perforation Information

Top (ft sub)	Bottom (ft sub)	Shts/Ft	No Shts	Dt Sqz
0	0			

Formation Information

St Code	Formation	Depth
Psal	Salado	376
Pbslt	Base of Salt	612
Psrbs	Bowers Sand	1515
Pqu	Queen	1690
Pgb	Grayburg	2032
Psa	San Andres	2482

Hole: Unknown

TD:

TVD: 0

PBTD:

ELL NAME AND NUMBER I	East Millman unit 5-9 R28E,Unit M, 1310' FSL, 1155' F	WI Eddy County
PERATOR Stephen & Johnson		WL Eddy County
RILLING CONTRACTOR		
•	ifies that he is an authorized reprevell and had conducted deviation	sentative of the drilling contractor test and obtained the following
Degrees @ Depth	Degrees @ Depth	Degrees @ Depth
1/4 @ 317'		
1/4 @ 530'		
1/2 @ 996'		
1 @ 2013'		
1 @ 2495'		-
	P	
	-	
	·	
	Drilling Contractor-	UNITED DRILLING, INC.
	Ву:	Mui Burcia (Luisa Garcia)
	Title:	Assistant Office Manger
Subscribed and swo	orn to before me this <u>S</u> day o	of June , 2006.
		Story O COMO
My Commission Expires:)-8-08	Chaus NaM. County State