

Form 3160-5  
(November 1983)  
(Formerly 9-331)

**UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT**

SUBMIT IN TRIPLICATE \*  
(Other Instructions on  
reverse side)

Budget Bureau No. 1004-0135  
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.  
LC-029419-A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

**SUNDRY NOTICES AND REPORTS ON WELLS**

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT - " for such proposals.)

1. OIL ☐ GAS ☐ OTHER ☐  
WELL WELL WIW - P & A

7. UNIT AGREEMENT NAME  
Skelly Unit

2. NAME OF OPERATOR  
The Wisar Oil Company

8. WELL NO.  
42

3. ADDRESS OF OPERATOR  
P.O. Box 2568 Hobbs, New Mexico 88240 (505) 392-9797

9. API WELL NO.  
30-015-05356

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.  
See also space 17 below.)  
At surface

10. FIELD AND POOL, OR WILDCAT  
Grayburg Jackson 7-Rivers-QN-GB-SA

660' FNL & 1880' FEL  
Unit B

11. SEC. T. R. M. OR BLK. AND  
SURVEY OR AREA  
Sec. 22-T17S-R31E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)  
3875' DF

12. COUNTY OR PARISH  
Eddy County

13. STATE  
NM

16. Check Appropriate Box to indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT OFF ☐ FULL OR ALTER CASING ☐  
FRACTURE TREAT ☐ MULTIPLE COMPLETE ☐  
SHOOT OR ACIDIZE ☐ ABANDON\* ☒  
REPAIR WELL ☐ CHANGE PLANS ☐  
(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐ REPAIRING WELL ☐  
FRACTURE TREATMENT ☐ ALTERING CASING ☐  
SHOOTING OR ACIDIZING ☐ ABANDONMENT\* ☐  
(Other) ☐  
(Note: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS: (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Wiser Oil respectfully request approval to plug and abandon the well by the procedure listed below.

Surface Casing: 8-5/8" set @ 616'. Production Casing: 4-1/2" set @ 3764' 11.60#

Perfs: 3188'-3606' 2283'-2400' CIBP @ 2100' & 3106' w/40 cement on plug.

1. Spot 50' plug on CIBP @ 2100'.
2. Perforate csg. @ 1700'. Place 100' of cmt. 51600'-1700' inside & outside of 4-1/2" csg. Tag cmt.
3. 9# mud.
4. Perforate casing @ 670'. Circulate cement to surface. Leave a 100' plug @ 570'-670'.
5. Tag cement.
6. Spot 60' cement plug to surface.
7. Install dry hole markers.
8. Clean location.

18. I hereby certify that the foregoing is true and correct.

SIGNED Mike Jones  
Mike Jones

TITLE Superintendent

DATE November 7, 2002

(This space for Federal or State office use)

APPROVED BY  
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

\*See Instruction On Reverse Side

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.