0.00	State of New Me	exico		Form C-103
Office District I	Energy, Minerals and Natural Resources		May 27, 2004 WELL API NO.	
1625 N. French Dr., Hobbs, NM 88240	218910117273		30-025-20325	
1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION	DIVISION	5. Indicate Type of L	ease
District III 1000 Rio Brazos Rd Aztec NM 87410	1220 South St. Fra	neis Div	STATE 🛛	FEE 🛛
District IV	Santa Fe, New &	CC 2000 7	6. State Oil & Gas Le	ease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	19/50 E		& Fee
SUNDRY NO	TICES AND REPORTS OF WELLS	S CO	7. Lease Name or Un	nit Agreement Name
District II 1301 W. Grand Ave., Artesia, NM 88210 District III 1000 Rio Brazos Rd., Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505 SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO AUDIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM COME) FOR SUCH		City of Carlsbad Com		
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM CHO)) FOR SUCH PROPOSALS.) 1. Type of Well, Oil Well Green Well Other		8. Well Number		
1. Type of Well: Oil Well Gas Well Other			1	
2. Name of Operator		9. OGRID Number		
BOLD ENERGY, LP 3. Address of Operator		233545 10. Pool name or Wildcat		
415 W. Wall, Suite 500 Midland, Texas 79701 4. Well Location			Carlsbad, South; Strawn (Gas)	
	feet from the South line and 198	o feet from the E	ast_line	
Section 25	Township 22S	Range 26E	NMPM	County Eddy
	11. Elevation (Show whether DR			
Pit or Below-grade Tank Application	3226	' DF		
		water well Dis	tance from nearest surface	water
· ·	nil Below-Grade Tank: Volume		nstruction Material	water
12. Checl	k Appropriate Box to Indicate N	lature of Notice,	Report or Other Da	ıta
NOTICE OF	INTENTION TO:	SUB	SEQUENT REPO	ORT OF:
PERFORM REMEDIAL WORK		REMEDIAL WORK		TERING CASING
	☐ CHANGE PLANS ☐	COMMENCE DRI		AND A
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMENT		_
PULL OR ALTER CASING OTHER:		CASING/CEMENT OTHER:	ГЈОВ 🗆	
PULL OR ALTER CASING OTHER: 13. Describe proposed or cor of starting any proposed	MULTIPLE COMPL	CASING/CEMENT OTHER: pertinent details, and	JOB	ncluding estimated date
PULL OR ALTER CASING OTHER: 13. Describe proposed or cor of starting any proposed or recompletion.	mpleted operations. (Clearly state all work). SEE RULE 1103. For Multip	CASING/CEMENT OTHER: pertinent details, and the Completions: Att	I give pertinent dates, in tach wellbore diagram	ncluding estimated date of proposed completion
PULL OR ALTER CASING OTHER: 13. Describe proposed or cor of starting any proposed or recompletion.	MULTIPLE COMPL mpleted operations. (Clearly state all	CASING/CEMENT OTHER: pertinent details, and the Completions: Att	I give pertinent dates, in tach wellbore diagram	ncluding estimated date of proposed completion
PULL OR ALTER CASING OTHER: 13. Describe proposed or cor of starting any proposed or recompletion.	mpleted operations. (Clearly state all work). SEE RULE 1103. For Multip	CASING/CEMENT OTHER: pertinent details, and ole Completions: Attended to the completion of the comple	I give pertinent dates, in tach wellbore diagram	ncluding estimated date of proposed completion utiled.
PULL OR ALTER CASING OTHER: 13. Describe proposed or completion or recompletion. Propose to complete	mpleted operations. (Clearly state all work). SEE RULE 1103. For Multip	CASING/CEMENT OTHER: pertinent details, and ole Completions: Att n 8/21/06. No ear g Perfs: Strawn	I give pertinent dates, in tach wellbore diagram of then pits will be required 10,395' – 10,402' &	ncluding estimated date of proposed completion utiled.
PULL OR ALTER CASING OTHER: 13. Describe proposed or completion. Propose to completion. TD = 11,969' 1. MIRU PU. Kill well, test	mpleted operations. (Clearly state all work). SEE RULE 1103. For Multipmmence workover operations o PBD = 10,830' Existin casing w/ 500 psi and install BOP. PC	CASING/CEMENT OTHER: pertinent details, and ole Completions: Attention 8/21/06. No ear of the perfect of the p	I give pertinent dates, in tach wellbore diagram of then pits will be reg	ncluding estimated date of proposed completion utiled.
PULL OR ALTER CASING OTHER: 13. Describe proposed or corof starting any proposed or recompletion. Propose to co TD = 11,969' 1. MIRU PU. Kill well, test of the coron of the coron of starting any proposed or recompletion. Propose to co TD = 11,969' Miru Pu. Kill well, test of the coron of the coro	mpleted operations. (Clearly state all work). SEE RULE 1103. For Multipmmence workover operations o PBD = 10,830' Existin casing w/ 500 psi and install BOP. PC r to 10,830'. RU WL & perf additional	CASING/CEMENT OTHER: pertinent details, and ole Completions: Attended to the completions of the completions of the completions of the completion of the com	I give pertinent dates, is tach wellbore diagram of then pits will be required to the pits will be requ	ncluding estimated date of proposed completion utiled.
PULL OR ALTER CASING OTHER: 13. Describe proposed or coron of starting any proposed or recompletion. Propose to co TD = 11,969' 1. MIRU PU. Kill well, test 2. Make trip w/ bit & scrape 10,370	mpleted operations. (Clearly state all work). SEE RULE 1103. For Multipmmence workover operations o PBD = 10,830' Existin casing w/ 500 psi and install BOP. PCr to 10,830'. RU WL & perf additional 1'-10,374' 10,471'-10,473'	CASING/CEMENT OTHER: pertinent details, and ole Completions: Att n 8/21/06. No ear g Perfs: Strawn of the W/ production tog Strawn pay as follow 10,560' – 1	I give pertinent dates, in tach wellbore diagram of then pits will be required to the pits will be requ	ncluding estimated date of proposed completion utiled.
PULL OR ALTER CASING OTHER: 13. Describe proposed or corof starting any proposed or recompletion. Propose to co TD = 11,969' 1. MIRU PU. Kill well, test of the coron of the coron of starting any proposed or recompletion. Propose to co TD = 11,969' 1. MIRU PU. Kill well, test of the coron of the c	mpleted operations. (Clearly state all work). SEE RULE 1103. For Multipmmence workover operations o PBD = 10,830' Existing casing w/ 500 psi and install BOP. PC or to 10,830'. RU WL & perf additional or 10,374' 10,471' – 10,473' 10,471' – 10,473' 10,514' – 10,518'	CASING/CEMENT OTHER: pertinent details, and ole Completions: Attended to the completions of the completions of the completions of the completions of the completion of the co	I give pertinent dates, is tach wellbore diagram of then pits will be required. 10,395' - 10,402' & packer. 10,564' 10,586'	ncluding estimated date of proposed completion utired. 10,470' – 10,475'
PULL OR ALTER CASING OTHER: 13. Describe proposed or correct of starting any proposed or recompletion. Propose to co TD = 11,969' 1. MIRU PU. Kill well, test of the starting with the scrape of t	mpleted operations. (Clearly state all work). SEE RULE 1103. For Multipmmence workover operations o PBD = 10,830' Existing casing w/ 500 psi and install BOP. PC or to 10,830'. RU WL & perf additional or 10,374' 10,471' – 10,473' 10,471' – 10,473' 10,514' – 10,518' 100 on 3½" work string & set @ 60 gals 15% HCl acid & 57,000# 30/66	CASING/CEMENT OTHER: pertinent details, and ole Completions: Att n 8/21/06. No ear g Perfs: Strawn of the William of the Will	I give pertinent dates, in tach wellbore diagram of then pits will be required to the pits will be requ	ncluding estimated date of proposed completion quired. 10,470' – 10,475'
PULL OR ALTER CASING OTHER: 13. Describe proposed or corof starting any proposed or recompletion. Propose to co TD = 11,969' 1. MIRU PU. Kill well, test of the starting with the starting any proposed or recompletion. Propose to co TD = 11,969' 1. Make trip w/ bit & scrape of the starting with	mpleted operations. (Clearly state all work). SEE RULE 1103. For Multipmmence workover operations o PBD = 10,830' Existin casing w/ 500 psi and install BOP. PCr to 10,830'. RU WL & perf additional 1' – 10,374' 10,471' – 10,473' 10,471' – 10,518' tool on 3½" work string & set @ 300 gals 15% HCl acid & 57,000# 30/66 am).	CASING/CEMENT OTHER: pertinent details, and ole Completions: Att n 8/21/06. No ear g Perfs: Strawn of the William of the Will	I give pertinent dates, in tach wellbore diagram of then pits will be required to the pits will be requ	ncluding estimated date of proposed completion quired. 10,470' – 10,475'
PULL OR ALTER CASING OTHER: 13. Describe proposed or corof starting any proposed or recompletion. Propose to co TD = 11,969' 1. MIRU PU. Kill well, test of the starting and the starting any propose to co TD = 11,969' 1. Make trip w/ bit & scrape 10,370' 10,396 3. Run packer w/ On/Off 10,370' - 10,586' w/ 400 Nitrogen (20% Quality for the starting any proposed or construction.	mpleted operations. (Clearly state all work). SEE RULE 1103. For Multipmmence workover operations of PBD = 10,830' Existing casing w/ 500 psi and install BOP. PC or to 10,830'. RU WL & perf additional of 10,471' - 10,473' 10,471' - 10,518' tool on 3½" work string & set @ a 100 gals 15% HCl acid & 57,000# 30/60 am).	CASING/CEMENT OTHER: pertinent details, and ole Completions: Att n 8/21/06. No ear g Perfs: Strawn of the William of the Will	I give pertinent dates, in tach wellbore diagram of then pits will be required to the pits will be requ	ncluding estimated date of proposed completion quired. 10,470' – 10,475' new Strawn perfs from ergized with 1500 MSCI
PULL OR ALTER CASING OTHER: 13. Describe proposed or corof starting any proposed or recompletion. Propose to co TD = 11,969' 1. MIRU PU. Kill well, test of the starting with the starting w	mpleted operations. (Clearly state all work). SEE RULE 1103. For Multipmence workover operations of PBD = 10,830' Existing casing w/ 500 psi and install BOP. PC or to 10,830'. RU WL & perf additional or 10,471' - 10,473' at - 10,374' 10,471' - 10,473' at 10,471' - 10,518' at 10 gals 15% HCl acid & 57,000# 30/60 am).	CASING/CEMENT OTHER: pertinent details, and ole Completions: Attended to the completions of the completions of the completions of the completion of the com	I give pertinent dates, is tach wellbore diagram of then pits will be required. 10,395' – 10,402' & a packer. 10,564' 10,586' imulate existing and red bbls of slickwater energy.	ncluding estimated date of proposed completion quired. 10,470' – 10,475' new Strawn perfs from ergized with 1500 MSCI
PULL OR ALTER CASING OTHER: 13. Describe proposed or correct of starting any proposed or recompletion. Propose to co TD = 11,969' 1. MIRU PU. Kill well, test of the starting any propose to co TD = 11,969' 1. Make trip w/ bit & scrape 10,370' 10,396' 3. Run packer w/ On/Off 10,370' - 10,586' w/ 400' Nitrogen (20% Quality for the starting and the starting	mpleted operations. (Clearly state all work). SEE RULE 1103. For Multipmmence workover operations o PBD = 10,830' Existin casing w/ 500 psi and install BOP. PC r to 10,830'. RU WL & perf additional o' - 10,374' 10,471' - 10,473' 10,471' - 10,518' tool on 3½" work string & set @ a 100 gals 15% HCl acid & 57,000# 30/60 am). st as necessary. On/Off tool, release from O/O tool & PC WH equip. Pump plug from O/O tool. on above is true and complete to the best work).	CASING/CEMENT OTHER: pertinent details, and ole Completions: Att n 8/21/06. No ear g Perfs: Strawn of the William of the Will	I give pertinent dates, in tach wellbore diagram of then pits will be required. 10,395' – 10,402' & apacker. 10,564' 10,586' imulate existing and reduced by the pits will be required. 23/8" tbg w/ O/O tool aroad water and return we and belief. I further see	ncluding estimated date of proposed completion quired. 10,470' – 10,475' new Strawn perfs from ergized with 1500 MSCI and latch onto packer. Tell to production.
PULL OR ALTER CASING OTHER: 13. Describe proposed or correct of starting any proposed or recompletion. Propose to co TD = 11,969' 1. MIRU PU. Kill well, test of the starting any propose to co TD = 11,969' 1. Make trip w/ bit & scrape 10,370' 10,396' 3. Run packer w/ On/Off 10,370' - 10,586' w/ 400' Nitrogen (20% Quality for the starting of t	mpleted operations. (Clearly state all work). SEE RULE 1103. For Multip mmence workover operations of the processing w/ 500 psi and install BOP. Post to 10,830'. RU WL & perf additional of 10,471' - 10,473' and 10,471' - 10,473' and 10,471' - 10,518' and 10 gals 15% HCl acid & 57,000# 30/60 am). The processing w/ 500 psi and install BOP. Post tool on 3½" work string & set @ 600 gals 15% HCl acid & 57,000# 30/60 am). The processing w/ 500 psi and complete to the book or closed according to NMOCD guidelines [10]	CASING/CEMENT OTHER: pertinent details, and ole Completions: Att n 8/21/06. No ear g Perfs: Strawn of the William of the Will	I give pertinent dates, in tach wellbore diagram of then pits will be required to the pits will be requ	ncluding estimated date of proposed completion quired. 10,470' – 10,475' new Strawn perfs from ergized with 1500 MSCI and latch onto packer. Tell to production. Trify that any pit or belower OCD-approved plan
PULL OR ALTER CASING OTHER: 13. Describe proposed or consoler of starting any proposed or recompletion. Propose to co TD = 11,969' 1. MIRU PU. Kill well, test to the starting any proposed or recompletion. Propose to co TD = 11,969' 1. MIRU PU. Kill well, test to the starting with the scrape 10,370' 10,370' 10,370' 3. Run packer w/ On/Off 10,370' – 10,586' w/ 400' Nitrogen (20% Quality for the starting of the starting proposed in the starting proposed or constructed in the starting proposed in the starting	mpleted operations. (Clearly state all work). SEE RULE 1103. For Multip mmence workover operations of PBD = 10,830' Existing casing w/ 500 psi and install BOP. PC or to 10,830'. RU WL & perf additional or 10,471' - 10,473' 10,471' - 10,473' 10,471' - 10,518' 100 gais 15% HCl acid & 57,000# 30/60 am). Set as necessary. On/Off tool, release from O/O tool & PC WH equip. Pump plug from O/O tool. On above is true and complete to the boor closed according to NMOCD guidelines in TITLE A	CASING/CEMENT OTHER: pertinent details, and ole Completions: Attention of the Completions of the Completions of the Completions of the Completions of the Completion of the C	I give pertinent dates, in tach wellbore diagram of then pits will be required. 10,395' – 10,402' & a packer. 10,564' 10,586' 10,586' 10 bbls of slickwater energy bbls of slickwater energy bbls of slickwater energy and water and return we and belief. I further ceror an (attached) alternative and stranding.	ncluding estimated date of proposed completion quired. 10,470' – 10,475' new Strawn perfs from argized with 1500 MSCI and latch onto packer. The production completion of the production of t
PULL OR ALTER CASING OTHER: 13. Describe proposed or considerating any proposed or recompletion. Propose to co TD = 11,969' 1. MIRU PU. Kill well, test of the construction of the constructed signal signal of the constructed signal of the constructed signal of the constructed signal signal signal signal signal signal signal s	mpleted operations. (Clearly state all work). SEE RULE 1103. For Multip mmence workover operations o PBD = 10,830' Existin casing w/ 500 psi and install BOP. PC r to 10,830'. RU WL & perf additional of 10,471' - 10,473' 10,471' - 10,473' 10,514' - 10,518' tool on 3½" work string & set @ 600 gals 15% HCl acid & 57,000# 30/60 am). St as necessary. On/Off tool, release from O/O tool & PC WH equip. Pump plug from O/O tool. on above is true and complete to the boor closed according to NMOCD guidelines [10] add E-mail address: ddo	CASING/CEMENT OTHER: pertinent details, and ole Completions: Att n 8/21/06. No ear g Perfs: Strawn of the William of the Will	I give pertinent dates, in tach wellbore diagram of then pits will be required. 10,395' – 10,402' & a packer. 10,564' 10,586' 10,586' 10 bbls of slickwater energy bbls of slickwater energy bbls of slickwater energy and water and return we and belief. I further ceror an (attached) alternative and stranding.	ncluding estimated date of proposed completion quired. 10,470' – 10,475' new Strawn perfs from argized with 1500 MSCI and latch onto packer. The production completion of the production of t
PULL OR ALTER CASING OTHER: 13. Describe proposed or considerating any proposed or recompletion. Propose to co TD = 11,969' 1. MIRU PU. Kill well, test of the construction of the constructed signal signal of the constructed signal of the constructed signal of the constructed signal signal signal signal signal signal signal s	mpleted operations. (Clearly state all work). SEE RULE 1103. For Multip mmence workover operations o PBD = 10,830' Existin casing w/ 500 psi and install BOP. PC r to 10,830'. RU WL & perf additional of 10,471' - 10,473' 10,471' - 10,473' 10,514' - 10,518' tool on 3½" work string & set @ 600 gals 15% HCl acid & 57,000# 30/60 am). St as necessary. On/Off tool, release from O/O tool & PC WH equip. Pump plug from O/O tool. on above is true and complete to the boor closed according to NMOCD guidelines [10] add E-mail address: ddo	CASING/CEMENT OTHER: pertinent details, and ole Completions: Att n 8/21/06. No ear g Perfs: Strawn of the William of the Will	I give pertinent dates, in tach wellbore diagram of then pits will be required to the pits will be requ	ncluding estimated date of proposed completion quired. 10,470' – 10,475' new Strawn perfs from ergized with 1500 MSCI and latch onto packer. The relief to production. The occupance o
PULL OR ALTER CASING OTHER: 13. Describe proposed or considerating any proposed or recompletion. Propose to co TD = 11,969' 1. MIRU PU. Kill well, test of the construction of the constructed signal signal of the constructed signal of the constructed signal of the constructed signal signal signal signal signal signal signal s	mpleted operations. (Clearly state all work). SEE RULE 1103. For Multip mmence workover operations of PBD = 10,830' Existing casing w/ 500 psi and install BOP. PC or to 10,830'. RU WL & perf additional or 10,471' - 10,473' 10,471' - 10,473' 10,471' - 10,518' 100 gais 15% HCl acid & 57,000# 30/60 am). Set as necessary. On/Off tool, release from O/O tool & PC WH equip. Pump plug from O/O tool. On above is true and complete to the boor closed according to NMOCD guidelines in TITLE A	CASING/CEMENT OTHER: pertinent details, and ole Completions: Att n 8/21/06. No ear g Perfs: Strawn of the William of the Will	I give pertinent dates, in tach wellbore diagram of then pits will be required to the pits will be requ	ncluding estimated date of proposed completion quired. 10,470' – 10,475' new Strawn perfs from argized with 1500 MSCI and latch onto packer. The production completion of the production of t

