I D UTTED OTHER		1
Figure 2001) UNITED STATES DEPARTMENT OF THE INTERIOR	OCD-ARTESIA	FORM APPROVED OMB No. 1004-0135
BUREAU OF LAND MANAGEMENT	AICI MAICE IN	Expires January 31, 2004
NEUNDRY NOTICES AND REPORTS ON	WELLS	5. Lease Serial No.
DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT NOTICES AND REPORTS ON Do not use this form for proposals to drill or re abandoned well. Use Form 3160-3 (APD) for such	enter an proposals.	NM-043625 6. If Indian, Allottee or Tribe Name
UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT Do not use this form for proposals to drill or re enter an abandored well. Use Form 3160-3 (APD) for such proposals. SUBMICIN TRIPLICATE - Other instructions on reverse side 1. Type of Well Gas Well Other		7. If Unit or CA/Agreement, Name and/or No ルハ つんらい
		8. Well Name and No.
Name of Operator Yates Petroleum Corporation		Saguaro AGS Federal Com #9 9. API Well No.
a. Address 3b. Ph	one No. (include area code)	30-015-26737
105 S. 4th Str., Artesia, NM 88210	505-748-1471	10. Field and Pool, or Exploratory Area
4. Location of Well (Footage, Sec., T., R., M., OR Survey Description)		Cemetary; Wolfcamp
CONTAIL S 4000(FIAM of Continue 22 TOOC FOAT (HAUT C AIFANA)		11. County or Parish, State
60'FNL & 1980'FWL of Section 23-T20S-R24E (UNIT		Eddy County, New Mexico
12. CHECK APPROPRIATE BOX(ES) TO INDIC		EPORT, OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACTION	
Acidize	Deepen Production	(Start/Resume) Water Shut-Off
X Notice of Intent Alter Casing	Fracture Treat Reclamation	n Well Integrity
	= =	
Subsequent Report Casing Repair	New Construction Recomplete	Other
Change Plans	Plug and Abandon Temporaril	y Abandon
Final Abandonment Notice Convert to Injection	Plug Back Water Disp	osal
 Describe Proposed of Completed Operation (clearly state all pertinent details, including If the proposal is to deepen directionally or recomplete horizontally, give subsurface local 	ations and measured and true vertical depths of all	pertinent markers and zones.
Attach the Bond under which the work will be performed or provide the Bond No. on fi following completion of the involved operations. If the operation results in a multiple co	ile with BLM/BIA. Required subsequent reports sh	nall be filed within 30 days.
	ompletion or recompletion in a new interval, a Form	n 3160-4 shall be filed once
testing has been completed. Final Abandonment Notices shall be filed only after all redetermined that the site is ready for final inspection.)		
testing has been completed. Final Abandonment Notices shall be filed only after all re		
testing has been completed. Final Abandonment Notices shall be filed only after all redetermined that the site is ready for final inspection.)	equirements, including reclamation, have been com	pleted, and the operator has
testing has been completed. Final Abandonment Notices shall be filed only after all redetermined that the site is ready for final inspection.) Tates Petroleum Corporation plans to plug and abandon IOTE: CIBP at 7580' + 35' cement	equirements, including reclamation, have been com	pleted, and the operator has
testing has been completed. Final Abandonment Notices shall be filed only after all redetermined that the site is ready for final inspection.) Yates Petroleum Corporation plans to plug and abandor NOTE: CIBP at 7580' + 35' cement Rig up safety equipment as needed. TOOH with rods	equirements, including reclamation, have been com n this well as follows: s and pump. TOOH with tubing	pleted, and the operator has
testing has been completed. Final Abandonment Notices shall be filed only after all redetermined that the site is ready for final inspection.) Tates Petroleum Corporation plans to plug and abandon IOTE: CIBP at 7580' + 35' cement Rig up safety equipment as needed. TOOH with rods sub, mud joint with bull plug and all but 5607' of the tu	equirements, including reclamation, have been coments of this well as follows: s and pump. TOOH with tubing abing.	and lay down TAC, S/N, perf
testing has been completed. Final Abandonment Notices shall be filed only after all redetermined that the site is ready for final inspection.) Yates Petroleum Corporation plans to plug and abandor NOTE: CIBP at 7580' + 35' cement Rig up safety equipment as needed. TOOH with rods sub, mud joint with bull plug and all but 5607' of the tue. RIH with gauge ring and junk basket to +/-6450'. POO	equirements, including reclamation, have been coments of this well as follows: s and pump. TOOH with tubing abing.	pleted, and the operator has
testing has been completed. Final Abandonment Notices shall be filed only after all redetermined that the site is ready for final inspection.) Yates Petroleum Corporation plans to plug and abandon NOTE: CIBP at 7580' + 35' cement Rig up safety equipment as needed. TOOH with rods sub, mud joint with bull plug and all but 5607' of the tut. RIH with gauge ring and junk basket to +/-6450'. POG. Set a 7" CIBP at 6437' with 35' cement on top.	equirements, including reclamation, have been comental this well as follows: s and pump. TOOH with tubing libing. OH.	and lay down TAC, S/N, perf
testing has been completed. Final Abandonment Notices shall be filed only after all redetermined that the site is ready for final inspection.) Tates Petroleum Corporation plans to plug and abandor NOTE: CIBP at 7580' + 35' cement Rig up safety equipment as needed. TOOH with rods sub, mud joint with bull plug and all but 5607' of the tut. RIH with gauge ring and junk basket to +/-6450'. POC Set a 7" CIBP at 6437' with 35' cement on top. Spot a cement plug across the DV tool and the Wolfce Spot 100' cement plug (25 sx) across the Bone Spring	this well as follows: and pump. TOOH with tubing bing. OH. amp from 5607'-5748'. g from 3502'-3602'.	and lay down TAC, S/N, perf
testing has been completed. Final Abandonment Notices shall be filed only after all redetermined that the site is ready for final inspection.) Yates Petroleum Corporation plans to plug and abandor NOTE: CIBP at 7580' + 35' cement Rig up safety equipment as needed. TOOH with rods sub, mud joint with bull plug and all but 5607' of the tuble. RIH with gauge ring and junk basket to +/-6450'. POC B. Set a 7" CIBP at 6437' with 35' cement on top. Spot a cement plug across the DV tool and the Wolfca Spot 100' cement plug (25 sx) across the Bone Spring Spot 100' cement plug (25 sx) from 1170'-1270'. Tag	this well as follows: and pump. TOOH with tubing bing. OH. amp from 5607'-5748'. g from 3502'-3602'.	and lay down TAC, S/N, perf
testing has been completed. Final Abandonment Notices shall be filed only after all redetermined that the site is ready for final inspection.) Tates Petroleum Corporation plans to plug and abandon NOTE: CIBP at 7580' + 35' cement Rig up safety equipment as needed. TOOH with rods sub, mud joint with bull plug and all but 5607' of the tut. RIH with gauge ring and junk basket to +/-6450'. POC 5. Set a 7" CIBP at 6437' with 35' cement on top. Spot a cement plug across the DV tool and the Wolfce. Spot 100' cement plug (25 sx) across the Bone Spring 5. Spot 100' cement plug (25 sx) from 1170'-1270'. Tag 7. Spot 100' cement plug (25 sx) from 100' to surface.	this well as follows: and pump. TOOH with tubing bing. OH. amp from 5607'-5748'. g from 3502'-3602'.	and lay down TAC, S/N, perf APPROVED LES BABYAK
testing has been completed. Final Abandonment Notices shall be filed only after all redetermined that the site is ready for final inspection.) Tates Petroleum Corporation plans to plug and abandon IOTE: CIBP at 7580' + 35' cement Rig up safety equipment as needed. TOOH with rods sub, mud joint with bull plug and all but 5607' of the tut. RIH with gauge ring and junk basket to +/-6450'. POC 5. Set a 7" CIBP at 6437' with 35' cement on top. Spot a cement plug across the DV tool and the Wolfci Spot 100' cement plug (25 sx) across the Bone Spring Spot 100' cement plug (25 sx) from 1170'-1270'. Tag 5. Spot 100' cement plug (25 sx) from 100' to surface. To 5. Cut off wellhead and install dry hole marker.	this well as follows: and pump. TOOH with tubing bing. OH. amp from 5607'-5748'. g from 3502'-3602'. I plug. Fag plug.	and lay down TAC, S/N, perf
testing has been completed. Final Abandonment Notices shall be filed only after all redetermined that the site is ready for final inspection.) Yates Petroleum Corporation plans to plug and abandon NOTE: CIBP at 7580' + 35' cement Rig up safety equipment as needed. TOOH with rods sub, mud joint with bull plug and all but 5607' of the tut. RIH with gauge ring and junk basket to +/-6450'. POC 3. Set a 7" CIBP at 6437' with 35' cement on top. Spot a cement plug across the DV tool and the Wolfci Spot 100' cement plug (25 sx) across the Bone Spring Spot 100' cement plug (25 sx) from 1170'-1270'. Tag 7. Spot 100' cement plug (25 sx) from 100' to surface. To 8. Cut off wellhead and install dry hole marker.	this well as follows: and pump. TOOH with tubing bing. OH. amp from 5607'-5748'. g from 3502'-3602'. I plug. Fag plug.	and lay down TAC, S/N, perf APPROVED LES BABYAK
testing has been completed. Final Abandonment Notices shall be filed only after all redetermined that the site is ready for final inspection.) Tates Petroleum Corporation plans to plug and abandor IOTE: CIBP at 7580' + 35' cement Rig up safety equipment as needed. TOOH with rods sub, mud joint with bull plug and all but 5607' of the tu. RIH with gauge ring and junk basket to +/-6450'. POC. Set a 7" CIBP at 6437' with 35' cement on top. Spot a cement plug across the DV tool and the Wolfce. Spot 100' cement plug (25 sx) across the Bone Spring. Spot 100' cement plug (25 sx) from 1170'-1270'. Tag. Spot 100' cement plug (25 sx) from 100' to surface. To Cut off wellhead and install dry hole marker.	this well as follows: and pump. TOOH with tubing bing. OH. amp from 5607'-5748'. g from 3502'-3602'. I plug. Fag plug.	and lay down TAC, S/N, perf APPROVED LES BABYAK
testing has been completed. Final Abandonment Notices shall be filed only after all redetermined that the site is ready for final inspection.) Tates Petroleum Corporation plans to plug and abandor IOTE: CIBP at 7580' + 35' cement Rig up safety equipment as needed. TOOH with rods sub, mud joint with bull plug and all but 5607' of the tu. RIH with gauge ring and junk basket to +/-6450'. POC. Set a 7" CIBP at 6437' with 35' cement on top. Spot a cement plug across the DV tool and the Wolfce. Spot 100' cement plug (25 sx) across the Bone Spring. Spot 100' cement plug (25 sx) from 1170'-1270'. Tag. Spot 100' cement plug (25 sx) from 100' to surface. To Cut off wellhead and install dry hole marker. NOTE: Yates Petroleum Corporation will use steel pits. 1. Thereby certify that the foregoing is true and correct Name (Printed/Typed)	this well as follows: and pump. TOOH with tubing abing. The prom 5607'-5748'. The prom 3502'-3602'. The plug.	and lay down TAC, S/N, perf APPROVED LES BABYAK PETROLEUM ENGINEER
testing has been completed. Final Abandonment Notices shall be filed only after all redetermined that the site is ready for final inspection.) (ates Petroleum Corporation plans to plug and abandor IOTE: CIBP at 7580' + 35' cement Rig up safety equipment as needed. TOOH with rods sub, mud joint with bull plug and all but 5607' of the tut. RIH with gauge ring and junk basket to +/-6450'. POC. Set a 7" CIBP at 6437' with 35' cement on top. Spot a cement plug across the DV tool and the Wolfcate. Spot 100' cement plug (25 sx) across the Bone Spring Spot 100' cement plug (25 sx) from 1170'-1270'. Tag (25 spot 100' cement plug (25 sx) from 100' to surface. To complete the surface of the surf	this well as follows: and pump. TOOH with tubing bing. OH. amp from 5607'-5748'. g from 3502'-3602'. I plug. Fag plug.	and lay down TAC, S/N, perf APPROVED LES BABYAK PETROLEUM ENGINEER
testing has been completed. Final Abandonment Notices shall be filed only after all redetermined that the site is ready for final inspection.) (ates Petroleum Corporation plans to plug and abandor IOTE: CIBP at 7580' + 35' cement Rig up safety equipment as needed. TOOH with rods sub, mud joint with bull plug and all but 5607' of the tut. RIH with gauge ring and junk basket to +/-6450'. POC. Set a 7" CIBP at 6437' with 35' cement on top. Spot a cement plug across the DV tool and the Wolfci. Spot 100' cement plug (25 sx) across the Bone Spring Spot 100' cement plug (25 sx) from 1170'-1270'. Tag Spot 100' cement plug (25 sx) from 100' to surface. To Cut off wellhead and install dry hole marker. NOTE: Yates Petroleum Corporation will use steel pits of the Name (Printed/Typed) Tina Huerta	this well as follows: and pump. TOOH with tubing bing. OH. amp from 5607'-5748'. g from 3502'-3602'. I plug. Tag plug. and no earth pits Title Regulatory Comple	and lay down TAC, S/N, perf APPROVED LES BABYAK PETROLEUM ENGINEER
testing has been completed. Final Abandonment Notices shall be filed only after all redetermined that the site is ready for final inspection.) Yeates Petroleum Corporation plans to plug and abandor NOTE: CIBP at 7580' + 35' cement Rig up safety equipment as needed. TOOH with rods sub, mud joint with bull plug and all but 5607' of the tut. RIH with gauge ring and junk basket to +/-6450'. POO Set a 7" CIBP at 6437' with 35' cement on top. Spot a cement plug across the DV tool and the Wolfce Set a 7" CIBP at 6437' with 35' cement on top. Spot 100' cement plug (25 sx) across the Bone Spring Sepot 100' cement plug (25 sx) from 1170'-1270'. Tag T. Spot 100' cement plug (25 sx) from 100' to surface. The second surface of the surface o	n this well as follows: s and pump. TOOH with tubing abing. OH. amp from 5607'-5748'. g from 3502'-3602'. plug. rag plug. and no earth pits Title Regulatory Compl	and lay down TAC, S/N, perf APPROVED LES BABYAK PETROLEUM ENGINEER
testing has been completed. Final Abandonment Notices shall be filed only after all redetermined that the site is ready for final inspection.) Yates Petroleum Corporation plans to plug and abandor NOTE: CIBP at 7580' + 35' cement Rig up safety equipment as needed. TOOH with rods sub, mud joint with bull plug and all but 5607' of the tut. RIH with gauge ring and junk basket to +/-6450'. POC B. Set a 7" CIBP at 6437' with 35' cement on top. Spot a cement plug across the DV tool and the Wolfca B. Spot 100' cement plug (25 sx) across the Bone Spring B. Spot 100' cement plug (25 sx) from 1170'-1270'. Tag Y. Spot 100' cement plug (25 sx) from 100' to surface. The surface of t	this well as follows: and pump. TOOH with tubing bing. OH. amp from 5607'-5748'. g from 3502'-3602'. I plug. Tag plug. and no earth pits Title Regulatory Comple	and lay down TAC, S/N, perf APPROVED LES BABYAK PETROLEUM ENGINEER iance Supervisor
testing has been completed. Final Abandonment Notices shall be filed only after all redetermined that the site is ready for final inspection.) Yates Petroleum Corporation plans to plug and abandor NOTE: CIBP at 7580' + 35' cement 1. Rig up safety equipment as needed. TOOH with rods sub, mud joint with bull plug and all but 5607' of the tub. RIH with gauge ring and junk basket to +/-6450'. POC B. Set a 7" CIBP at 6437' with 35' cement on top. 1. Spot a cement plug across the DV tool and the Wolfce B. Spot 100' cement plug (25 sx) across the Bone Spring B. Spot 100' cement plug (25 sx) from 1170'-1270'. Tag Y. Spot 100' cement plug (25 sx) from 100' to surface. The surface of the surfac	n this well as follows: s and pump. TOOH with tubing abing. OH. amp from 5607'-5748'. g from 3502'-3602'. plug. Tag plug. and no earth pits Title Regulatory Complete Complet	and lay down TAC, S/N, perf APPROVED LES BABYAK PETROLEUM ENGINEER iance Supervisor
testing has been completed. Final Abandonment Notices shall be filed only after all redetermined that the site is ready for final inspection.) Yeates Petroleum Corporation plans to plug and abandor NOTE: CIBP at 7580' + 35' cement Rig up safety equipment as needed. TOOH with rods sub, mud joint with bull plug and all but 5607' of the tut. RIH with gauge ring and junk basket to +/-6450'. POO 15. Set a 7" CIBP at 6437' with 35' cement on top. Spot a cement plug across the DV tool and the Wolfci 15. Spot 100' cement plug (25 sx) across the Bone Spring 15. Spot 100' cement plug (25 sx) from 1170'-1270'. Tag 15. Cut off wellhead and install dry hole marker. NOTE: Yates Petroleum Corporation will use steel pits 15. This Space For	this well as follows: and pump. TOOH with tubing abing. OH. amp from 5607'-5748'. g from 3502'-3602'. applug. Tag plug. Title Regulatory Complete Date January 3, 2006 Title Warrant or	and lay down TAC, S/N, perf APPROVED LES BABYAK PETROLEUM ENGINEER iance Supervisor



