

District I  
1625 N French Dr, Hobbs, NM 88240  
District II  
1301 W Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S St Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

SEP 12 2007  
OCD-ARTESIA

Form C-141  
Revised March 17, 1999

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

30-015-25419

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company Devon Energy Production Company, L.P.	Contact Jerry Mathews, Foreman	
Address P. O. Box 250, Artesia, NM 88211	Telephone No. <input type="checkbox"/> (505) 748-5234	
Facility Name Barclay 11N Fed SWD Pump	Facility Type <input type="checkbox"/> Salt Water Disposal Well	
Surface Owner <i>H</i>	Mineral Owner	Lease No. <input type="checkbox"/>

LOCATION OF RELEASE

Unit Letter	Section 11	Township 023S	Range 031E	Feet from the 2180	North/South Line North	Feet from the 660	East/West Line East	County Eddy
-------------	---------------	------------------	---------------	-----------------------	---------------------------	----------------------	------------------------	----------------

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 35 bbls	Volume Recovered <input type="checkbox"/> 10 bbls
Source of Release Pump at Battery	Date and Hour of Occurrence 9-5-07 7:30 AM	Date and Hour of Discovery 9-5-07 7:30 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Linda Berryman	
By Whom? <input type="checkbox"/> Jerry Mathews	Date and Hour <input type="checkbox"/> 9-5-07 9:12 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

N/A

Describe Cause of Problem and Remedial Action Taken.\*

2x1 swedge broke in threads due to vibration on pump. Swedge was XH plastic coated. We are having pulsation dampener and valves in pump checked to make sure we don't have a problem with this pump. We also changed out the flange on the pump while we were there, it was eaten up on the inside.

Describe Area Affected and Cleanup Action Taken.\*

On location 85'x60', in pasture 3'x60'. Called vacuum truck, had water picked up, tilled and fertilized the area.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Jerry Mathews</i>	OIL CONSERVATION DIVISION	
Printed Name: Jerry Mathews	Approved by <input type="checkbox"/> District Supervisor: <i>Berryman</i>	
Title: Production Foreman	Approval Date: SEP 17 2007	Expiration Date: