

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS

OCD-ARTESIA

FORM APROVED OMB NO. 1004-0135 EXPIRES: NOVEMBER 30, 2000

SUNDRY NOTICES AND REPORTS ON WELLS				5. Lease Serial No.	
Do not use this form for proposals to drill or to re-enter an				NM 96222 6. It Indian, Allottee or Tribe Name	
abandoned well. Use Form 3160-3 (APD) for such proposals				o. if ingian, Allotte	e or inde name
SUBMIT IN TRIPLICATE				7 Unit or CA Agreement Name and No	
1a Type of Well Oil Well Gas Well Other				- Only of Oxyngreement value and the	
SEP 24 2007				8 Well Name and No.	
2 Name of Operator				Ore Ida 14 Federal 5	
DEVON ENERGY PRODUCTION COMPANY, LP OCD-ARIESIA				9. API Well No.	
3 Address and Telephone No				30-015-29243	
20 North Broadway, Oklahoma City, OK 73102 405-235-3611				10. Field and Pool, or Exploratory	
4. Location of Well (Report location clearly and in accordance with Federal requirements)*				40. County of Posish 40. Cited	
935' FNL 1705' FEL B SEC14 T24S T29E				12. County or Parish 13 State	
				Eddy	NM
TYPE OS SUBMISSION	APPROPRIATE BOX(s) TO INC		CE, REPORT, OF ACTION	OR OTHER DAT	A
TTPE OS SUBIVISSION				(5) (5)	
			Reclamation	n (Start/Resume)	Water Shut-Off Well Integrity
			_		Other
Final Abandonment Notice	Change Plans	Plug and Abandon		ily Abandon	
	Convert to Injection	Plug Back	Water Dis	<del>'                                    </del>	
Describe Proposed or Completed Operations (C deepen directionally or recomplete horizontally, give si the Bond No on file with BLM/BIA Required subsequinterval, a Form 3160-4 shall be filed once testing has determined that the site is ready for final inspection)  Devon Energy Production Com	ubsurface location and measured and true ent reports shall be filed within 30 days for been completed. Final Abandonment No epany, L. P. respectfully r	e vertical depths of all pertinent mari illowing completion of the involved o tices shall be filed only after all requ equests to recomplete	kers and zones A operations If the o pirement, including to the Che	attach the Bond under w peration results in a mu reclamation, have beer erry Canyon.	thich the work will be performed or provide litiple completion or recompletion in a new
1. MIRU PU. Conduct safety meeting 2. Ensure well is dead, if not load hol 3. ND wellhead. 4. NU BOPE and test per company g 5. MIRU WLSU. Install Wireline BOF 6. RIH w/4" csg gun. Perf Cherry Ca 7. RIH with treating packer on tubing 8. RU treaters and acidize 6200' – 62 rate possible with pumps on location 9. Unset treating packer and run thro recovered or oil cut reaches 15%. E-10. If no frac is necessary unset pach 11. RIH w/production tubing and BHA 12. PUH and set TA. NU pumping W 13. RIH w/pump and rods. Hang wel 14. Report daily production test until	e with fresh water.  uidelines. PE and test per company gui nyon at the following interva set at approximately 6150' a 210' with 1200 gal 7½% Pen- (up to 10 BPM). If ballout o ugh perfs to knock balls off to valuate for frac. ker and POOH. A and circulate well clean. H assembly. I on pump @ 8 x 144" SPM. further notice.	idelines. I, 2 SPF (120° phase) 62 and test to 2000 psi. tol acid, dropping 40 ball ccurs, surge balls off and then set packer above pe	200' - 6210':2 I sealers eve d continue w	20 holes. RD W nly with the acid ith acid. Flush v	l. Pump acid at maximum vith FW.
Signed Jane E.	Name Title	Judy A. Barne Regulatory Ana		Date	9/10/2007
(This space for Federal or State Office us Approved by Conditions of approval, if any	R. GLASS	PETROLEUM EN	IGINEER	Date	SEP 1 9 2007

Title to 0.5 C. Section 1001, thakes it a clime for any person knowingly and williony to make any department or agency of the onlined States any faise, notificus of fraudulent statements of representations to any marter within its jurisdiction



