UNITED STATES DEPARTMENT OF THE INTERIOR OIL CONS. BUREAU OF LAND MANAGEMENT M.M. DIV-Dist. 2

FORM APPROVED OMB No 1004-0135 Expires July 31, 1996.



.5. Lease Serial No

SUNDRY NOTICES AND REP	ORTSONWEL	Ligiana Aven	NM-32323	v	
Do not use this form for proposals to drill or to resenter and 88210 abandoned well. Use Form 3160-3 (APD) for such proposals.			6. If Indian, Allottee or Tribe Name		
SUBMIT IN TRIPLICATE – Other ins	tructions on re	verse side	7. If Unit or CA/.	Agreement, Name and/or No	
I. Type of Well			8. Well Name and No.		
Oil Well Gas Well Other	NOV 1-3 2008		SNAKEWEED B FEDERAL 1		
2. Name Of Operator			9. API Well No		
MCKAY OIL CORPORATION		OCD-ARTESIA		30-005-64002	
3a. Address	,	3b. Phone No. (include area code)		10. Field and Pool, or Exploratory Area	
P.O. BOX 2014 ROSWELL, NM 88202-2014 4. Location of Well (Footage, Sec., T., R, M., or Survey Desc				WEST PECOS ABO SLOPE 11. County or Parish, State	
1980' FSL, & 2080' FWL, UNIT K, SEC 18, T6S, R23			CHAVES COUNTY, NM		
1000 1 00, 0 2000 1 442, 0 111 11, 0 20 10, 100, 1202			CHAVES COUNTY, NIV		
12. CHECK APPROPRIATE BOX(ES)	TO INDICATE NA	ATURE OF NOTIC	E, REPORT, OR	OTHER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION				
☐ Acidize	Deepen	Producti	on (Start/Resume)	☐ Water Shut-Off	
Notice of Intent Alter Casing	Fracture Trea	t 🔲 Reclama	tion	☐ Well Integrity	
☐ Casing Repair	☐ New Constru	ction	lete	Other	
Change Plans	Plug and Aba	ndon 🔲 Tempora	rily Abandon		
Final Abandonment Notice Convert to Injection	☐ Plug Back	☐ Water D	sposal		
13. Described Proposed or Completed Operation (clearly state a thereof. If the proposal is to deepen directionally or recomple and zones. Attach the Bond under which the work will be a within 30 days following completion of the involved operation shall be filed once testing has been completed. Final Abandon the operator has determined that the site is ready for final insp	ete horizontally, give sub performed or provide the ons. If the operation resonment Notices shall be f	bsurface locations and me Bond No. on file with sults in a multiple compl	easured and true verting BLM/BIA. Required etion or recompletion	cal depths of all pertinent markers I subsequent reports shall be filed in a new interval, a Form 3160-4	
1) 10/18/08: Set packer @ 850'. Tested casing to 500#. Casing tested good.					
2) 10/19/08: Pumped 50sks to 830'. WOC 4hrs. Pumped additional 50sks to 830'. WOC 4hrs. Tagged @ 715'. Drilled cement bridge out 715' to 790'.					
 10/20/08: Pumped 50sks cement to 715'. WOC 4hrs. Pumped 50sks to 550'. WOC 4hrs. Pumped 50sks from 225' to surface. WOC 4hrs. 					
 Location cleared of debris and equipment. Up marker erected. Pit closure will be completed 					
14. I hereby certify that the foregoing is true and correct		ACCEPTED FOR RECORD			
Name (Printed/Typed)		Title			
CAROL SHANKS Signature		Date ' NOV 1 3 2008		NOV 10 2000	
(M) XMME		14/02/2009			
ACCEPTED FOR RECORSPACE	FOR FEDERAL (OR STATE OFFIC	E USE NMO	Guye; Deputy Field Inspector CD-District II ARTESIA	
Approved By /S/ DAVID R. GLAS	S. , , , , , ,	Title		Date	
onditions of approval, if any, are attached. Approval of this notice does not warran certify that the applicant holds legal or equitable title to those rights in the subject lease hich would entitle the applicant to conduct operations thereon. DAVID R. GLASS itle 18 U.S.C. Section FOOI, makes it algorithm any person knowingly and willfully to make		APPRO WELL	APPROVED AS TO PLUGGING OF THIS WELL BORE I LARIL ITY LINDER BOARD		
Title 18 U.S.C. Sequint FOOL, makes it alorithe for any person kno fraudulent statements or representations as to any matter within its	wingly and willfully to r jurisdiction.	nake to any department o	or agenomofthe United	d States any false, fictitious or	

Plugging Procedure In AFMSS According To BLM Petroleum Engineering Technician On Location.

Laid Down Drill Collars And Picked Up Drill Pipe. Tagged Pack-Off @ 450'. Rig Tool Pusher Wanted To Spot Cement In Stages, For Fear Of Getting Drill Pipe Cemented In. Pulled Up To 420'. Spot A 35 Sack Balance Plug. WOC. Tagged TOC @ 450'. Laid 1 Joint Of Drill Pipe Down And Spot Another 35 Sack Balance Plug @ 420'. WOC. Tagged TOC @ 290'. Laid 1 Joint Of Drill Pipe Down. Started Pumping Cement. At 13 Sacks, Started Getting Cement At Surface. Stopped Pumping Cement. Pulled Drill Pipe With No Water Displacement. Gave The Order To WOC Cement For 4 Full Hours To Ensure That Cement Is Hard Enough To Get A Solid Tag With Drill Pipe. Gave Order To Get A Vacuum Truck To Pull Returns At Well Head Rather Than Run Water And Cement On Ground. Tagged TOC @ 255'. Pumped 47 Sacks Cement. WOC. Tagged TOC @ 27'. Topped Well Out. Cement To Surface.