

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENTOCD-ARTESIA
FEB 19 2009FORM APPROVED
OMB No. 1004-0137
Expires: July 31, 2010

LM

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.**SUBMIT IN TRIPLICATE - Other instructions on page 2**

1 Type of Well <input type="checkbox"/> Oil Well <input type="checkbox"/> Gas Well <input checked="" type="checkbox"/> Other <i>WTR INS</i>		5. Lease Serial No. NMNM 2747
2 Name of Operator BURNETT OIL CO., INC.		6. If Indian, Allottee or Tribe Name
3a Address 801 CHERRY STREET, SUITE 1500		7 If Unit or CA/Agreement, Name and/or No
3b. Phone No (include area code) (817) 332-5108		8 Well Name and No. JACKSON B #15
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) UNIT #8 FORT WORTH TX 76102-6881		9 API Well No. 30-015-04038 S1
UNIT L. 1980' FSL. 660' FWL. SEC 1. T17S. R30E- SURF & BHL		10. Field and Pool, or Exploratory Area SQUARE LAKE (GB-SA)
		11 County or Parish, State Eddy County, N.M.

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input checked="" type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input type="checkbox"/> Other
	<input type="checkbox"/> Change Plans	<input checked="" type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

DRILLED 1/1945**PRESENT WELL CONDITION: 8-1/4" CSG @ 558' W/50 SKS CMT, 5-1/2" CSG @ 2838' W/100 SKS CMT. O/H TD IS 3161' P&A PRODCURE AS FOLLOWS: 9.5 PPG BRINE WATER W/MUD GEL WILL BE CIRCULATED BETWEEN EACH PLUG.**

- 1.) Notify BLM-Carlsbad and NMOCD- Artesia before work begins. 2.) RUSU, NU BOP. 3.) Pull & LD cmt lined tbg & packer. 4.) GIH w/2-7/8" workstring w/ bit w/5-1/2" csg scraper, run to 2730'. (DO NOT RUN INTO OH.) POOH W/ ALL. 5.) GIH w/ Cement retainer & set @ 2650'. Pump 50 sks cement to cover top of San Andres (2711') and producing interval. 6.) Pull out of retainer and POOH w/workstring. 7.) Perforate 4 squeeze holes @ 1450' (50' below Top of Yates and Base of Salt at 1399'). 8.) GIH w/workstring and packer, pump 50 sks inside & outside of casing above & below Base of Salt @ 1399'. **WOC. TAG PLUG.** 9.) Perforate 4 squeeze holes @ 610' (to be 50' below base of 8-1/4" surface csg shoe.) 10.) RIH w/packer and pump 50 sks cement through squeeze holes to obtain 50' cement plug inside & outside 5-1/2" casing above and below 8-1/4" casing shoe @ 558' and Top of Salt @ 413'. **WOC. TAG PLUG.** 11.) Perforate 4 squeeze holes @ 60'. Pump 25 sks cement through squeeze holes to circulate to surface.

NOTE: All cement plugs, including surface plugs, should leave 25 sk minimum inside casing and be at least 100', plus 10% for each 1000' of depth.

- 12.) Cut off csg and wellhead. Top off surface with cement. 13.) RDSU. 14.) Install P&A marker. RESTORE LOCATION FOR FINAL BLM INSPECTION.

**SEE ATTACHED FOR
CONDITIONS OF APPROVAL**

14 I hereby certify that the foregoing is true and correct.)

Name (Printed/Typed)

MARK A. JACOBY

ENGINEERING MANAGER

Signature

Mark A. Jacoby

Title

Date

*2/05/2009***THIS SPACE FOR FEDERAL OR STATE OFFICE USE**

Approved by

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Title

Office

Date

FEB 17 2009

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

JAMES A. AMOS
SUPERVISOR-EPS

8. Squeeze w/adequate cmt to fill 100' interval. Tag @ 1350
10. Squeeze w/adequate cmt to fill 247' interval. Tag @ 363

HOLE SIZE _____

50 SX


CASING SIZE 8"
TD 558'

HOLE SIZE _____

Pulled 7" @ 2281

100 SX
CASING SIZE 5 1/2"
TD 2838

3161 TD



Sg. 50 SX
Perf @ 40'

SALT SECTIONS TOP 413
BASE 1399
RIIP

CAVE / KARST
SPEC WATER

363
WOC Tag
Perf. @ 610

FORMATIONS Top Salt 413
Base Salt 1399
Savvy Rivers 1785
Queen 2217
SA 2711

1350 WOC Tag
Perf 4 Sg. holes
@ 1450

CR @ 2650 DVT
Sg. 50 SX
PERFORATIONS

**BUREAU OF LAND MANAGEMENT
Carlsbad Field Office
620 East Greene Street
Carlsbad, New Mexico 88220
575-234-5972**

**Permanent Abandonment of Federal Wells
Conditions of Approval**

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within ninety (90) days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90th day provide this office, prior to the 90th day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

2. **Notification:** Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.

3. **Blowout Preventers:** A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.

4. **Mud Requirement:** Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of water. Minimum nine (9) pounds per gallon.

5. **Cement Requirement:** Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. In lieu of a cement plug in a cased hole, a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

6. **Dry Hole Marker:** All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The well bore shall then be capped with a 4-inch pipe, 10-feet in length, 4 feet above ground and embedded in cement. The following information shall be permanently inscribed on the dry hole marker: well name and number, name of the operator, lease serial number, surveyed location (quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer such as metes and bounds).

7. **Subsequent Plugging Reporting:** Within 30 days after plugging work is completed, file one original and five copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. **Show date well was plugged.**

8. **Trash:** All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration conditions of approval will be developed and furnished to you.