
District-I - 1625 N French Dr , Hobbs, NM 88240 District II
1301 W. Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S St. Francis Dr., Santa Fe, NM 87505



Oil Conservation Division 1220 South St. Francis Dr. Santa Fe NM 87505

Rec D 4/9/09

Form C-141 Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back side of form

Santa 1 c, 14141 67505													
Release Notification and Corrective Action													
MCB 09/0448390						OPERATOR							
Name of Company SOUTHWEST ROYALTIES, INC.						Contact DAWN M. HOWARD							
Address 6 DESTA DRIVE, STE 2100, MIDLAND, TX 79705						Telephone No. 432/688-3267							
Facility Nat	ne WILD	ERSPIN FE			Facility Type BATTERY – closest to well #1								
Surface Owner BLM –grazing permit allottee   Mineral Owner BLM/SWR   Lease No. NMNM1478B/16282													
Winston Ballard #77020						DLW/5WK			Lease Inc. Inivinivi1476b/10262				
LOCATION OF RELEASE													
Unit Letter	Section	Township	Range	Feet from the	North	South Line	Feet from the	East/V	Vest Line	County			
F	11	218	27E	1980	N		1980	W		EDDY			
Latitude Longitude													
NATURE OF RELEASE													
Type of Release OIL						Volume of Release ~115			Volume Recovered 57				
Source of Release HOLE IN TANK							lour of Occurrence	e		ate and Hour of Discovery			
W. L. W. C. O.						4/1/09 mid				/2/09 10:30 a.m.			
Was Immediate Notice Given?  ☐ Yes ☐ No ☐ Not Require						If YES, To Whom?  d NMOCD – Mike Bratcher; BLM – Jim Amos							
D 11/1 0													
By Whom? Dawn Howard Was a Watercourse Reached?						Date and Hour 4/2/09 11:30 a.m.							
was a watercourse Reached? ☐ Yes ⊠ No						If YES, Volume Impacting the Watercourse.							
If a Watercou	rse was Imp	pacted, Descri	ibe Fully.*	:		<u> </u>							
Describe Caus	Describe Course of Doublam and Doublish Astin Talunt												
Describe Cause of Problem and Remedial Action Taken.*  A hole in the side of oil stock tank at the battery was discovered when the pumper gauged. The tank will be repaired.													
Describe Area	Describe Area Affected and Cleanup Action Taken.*												
All oil was contained within the firewall. Vacuumed and recovered 57 Bbls of oil. A backhoe was used to scrape and dust location due to cattle in the													
area. An environmental contractor's services have been obtained to analyze and aid in the efforts to remediate this location.													
I hereby certif	y that the ir	formation give	ven above	is true and comp	lete to t	he best of my	knowledge and u	nderstan	d that purs	uant to NMO	OCD n	ules and	
regulations all	operators a	ire required to	report and	d/or file certain re	elease n	otifications an	d perform correc	tive acti	ons for rele	eases which:	may er	ndanger	
				e of a C-141 repo									
should their of	perations ha	ive failed to a	dequately:	investigate and re	emodiat	e contaminatio	on that pose a thre	eat to gr	ound water	, surface wa	ter, hui	man health	
federal, state,				ance of a C-141 i	report a	oes not relieve	the operator of r	esponsi	bility for co	ompliance w	ith any	other	
receiu, state,	or room raw	s and or regu	·				OIL CONS	SFRV	ATION	DIVISIO	N		
	$\sim$	$\supset C$			OIL CONSERVATION DIVISION								
Signature:	aler	~~~~	<u> </u>										
Printed Name:	_ DAWN	M. HOWARI	•		Approved bsigistics Supplied Beneur								
m: 1							PR 1 7 200	19					
Title:	_OPERA	TIONS ASSIS	STANT			Approval Date			expiration I	Date:			
E-mail Addres	s: DHOWA	.RD@CLAY	ΓΟΝWILI	JAMS COM		Conditions of	Approval: Seme	diatan	per			-	
						Och Pul	S Rules & Guide lines Attached						
Doto: 4/2/00	Dhono: 42	2/600 2267			j	0 / 0 / 0	~ ( ) JU(10) ~ [ //	rea		i		1	

\* Attach Additional Sheets If Necessary

Date: 4/3/09 Phone: 432/688-3267

2RP-300

1/7/09 VOTE: Excaustin of improbal material has commend & vemodiation is ongoing.