District I 1625 N. French Dr., Hobbs, NM 88240 District II

1301 W. Grand Avenue, Artesia, NM 88210

District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

\* Attach Additional Sheets If Necessary

## State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

RECEIVED

Form C-141 Revised October 10, 2003

FEB 1 4 2011 Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back **NMOCD ARTESIA** side of form

## **Release Notification and Corrective Action**

1MLB/021934173						<b>OPERA</b>	<b>FOR</b>	☐ Initi	☐ Initial Report ☒ Final Repor			
Name of Company COG Operating LLC						Contact Par	t Ellis					
Address 550 W. Texas, Suite 1300 Midland, Texas 79701						Telephone No. (432) 685-4332						
Facility Name Caddo Federal #6						Facility Type Wellhead						
Surface Owner: Federal Mineral Owner						Lease No. API 30-015-36673						
Darrace OW	Her. I eder				N OF BEE	BA CD	1 Deuse 1	10.711.130	015 5	70075		
	[ a ·		ъ			N OF REI			10			
Unit Letter B	Section 17	Township Range Feet from the No. 17S 30E 990'				rth/South Line   Feet from the   H NORTH   2310'		East/West Line County EAST		Edd	Eddy	
									<u> </u>			
<b>Latitude</b> N 32 50.46° <b>Longitude</b> W 103 59.577°												
NATURE OF RELEASE												
Tyme of Poles	na: Produce	ad Fluide		IVAI	UKE	Volume of Release 10 bbls Volume Recovered 5 bbls						
Type of Release: Produced Fluids Source of Release: Wellhead							our of Occurrence		Date and Hour of Discovery			
bource of Release. Wellied						9/02/10 9/02/10					8:00a.m.	
Was Immediate Notice Given?						If YES, To	Whom?					
			Yes 🏻	No 🖾 Not Re	quired							
By Whom?						Date and Hour 3/15/10 4:59 p.m.						
Was a Watercourse Reached?						If YES, Volume Impacting the Watercourse.						
☐ Yes ☒ No						N/A						
If a Watercou	rse was Imp	acted, Descri	be Fully.*									
N/A												
IN/A												
Describe Cause of Problem and Remedial Action Taken.*												
The course of the release was due to the tubing healthreese when the state of the s												
The cause of the release was due to the tubing backpressure valve plugged by packing. The tubing backpressure value was removed and unplugged and the stuffing box was re-packed.												
stutting box was to-packed,												
Describe Area Affected and Cleanup Action Taken.*												
Totro Took inc	nacted site	and collected	namalas te	dafina anilla auta	nt Cai	il that avandar	I DDAI was rome	oved and hauled a	way for neon	or disc	annal Sita	
								submitted to NMC			Josai, Site	
	9.24 mp 55 5 m											
								derstand that pursi				
								ve actions for rele				
								port" does not relie to ground water,				
								sponsibility for co				
federal, state, o	r local laws	and/or regula	tions.					<u> </u>	-			
		\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	<b>\</b>				OIL CONS	ERVATION 1	<u>DIVISIO</u>	<u>1</u>		
Signature:		' //						. 11				
						Approved by Disgign By is Alily Busseum						
Printed Name:	Ike Tavarez	depo	WTJ	or COG	) [	Approved by D	ABDOORSY SEL	FILT DOME		•		
	_		· · · · ·				1.1.		./			
Title: Project M	1anager				<u></u>	Approval Date:	21/6/2011	Expiration D	ate: N/A			
E-mail Address	s: Ike.Tavar	ez@TetraTecl	ı.com			Conditions of A	pproval: MA				1	
E-mail Address: Ike.Tavarez@TetraTech.com							1: /	7	Attached			
Date: 2/7	[//			132) 682-4559			nout					
Attach Addition	orial Sheets	If Necessar	y				, ,	00	1	//.	7	
								$\mathcal{J}KI$	2-4	41		
								V/11	7 (			