

DRILL STEM TESTS

Moab Drilling Company
Buffalo-Lodewick #1

April 27, 1955

Attempted D.S.T. 657-749
Misrun, packer failure.

May 1, 1955

D.S.T. #1 665-779. Tool open 15 mins.
w/weak blow of air, died in 2 mins. Re-
set tool, open 30 mins. w/weak blow of
air that died in 2 mins.
recovered 40' of \emptyset mud.

May 17, 1955

D.S.T. #2 1660-1715
Tool opened with fair blow of air. Packer
seat failed in 3 minutes. Recovered 800'
 \emptyset mud. Initial hydrostatic press. 800#
Final hydrostatic press. 670#

May 29, 1955

D.S.T. #3 2080-2204
Tool opened one hour with weak blow of
air died in 2 mins. Recovered 30' of
 \emptyset mud.
Shut in press. 0# in 30 minutes
Hydrostatic press. 1110#
Initial flowing press. 0#
final flowing press. 0#