

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE
IN ONE ENVELOPE
verses side
Drawer DD

Budget Bureau No. 1004-0135
Expires August 31, 1985

45F

LEASE DESIGNATION AND SERIAL NO.

NM-05876

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. ☐ OIL WELL ☒ GAS WELL ☐ OTHER

2. NAME OF OPERATOR

Breck Operating Corp.

3. ADDRESS OF OPERATOR

P.O. Box 911, Breckenridge, Texas 76024

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

990' FNL & 990' FWL of Sec. 27, T-10-S, R-25-E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3475' GR

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

DeKalb Federal

9. WELL NO.

4

10. FIELD AND POOL, OR WILDCAT

Bitter Lake (San Andres)

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 27, T-10-S, R-25-E

12. COUNTY OR PARISH

Chaves

13. STATE

New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETION

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT*

(Other)

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

This well was plugged in the following manner.

11/14/84 - RIH w/ 2-3/8" tubing to 903' (TD). Pump 20 sx. Class H cement plug. POOH w/ 8 joints of tubing. Wait 3 hours. RIH & tag plug @ 750'. Circulate & fill hole w/mud. POOH to 500'. Pump 15 sx. Class H cement plug. Plug #2 is 500' - 400'. POOH to 65'. Pump 10 sx. Class H cement plug to surface. Cut off pipe 3' below surface and weld on metal cap. Place abandonment marker.



Box ID-2
9-19-86
BIA

18. I hereby certify that the foregoing is true and correct

SIGNED

Daniel D. Wilh

TITLE

Petroleum Engineer

DATE

8/22/86

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

APPROVED
PETER W. CHESTER

SEP 10 1986

BUREAU OF LAND MANAGEMENT
ROSWELL RESOURCE AREA

*See Instructions on Reverse Side

1000

1000