

May 15, 1967

Mercury Production Company
508 Fort Worth Nat'l. Bank Bldg.
Fort Worth, Texas

Re: Brown Pool Inspection

Gentlemen:

A field inspection of the Brown Pool was made May 12, 1967. This inspection revealed various deficiencies which must be corrected. The work to be done is as follows:

- (1). Well signs must be placed at all producing and injection wells.
- (2). Regulation markers must be placed on or at the three plugged holes, State E-92 #2 F, 7 G and 8 F. The markers are to be of 4 inch pipe extending 4 feet above the ground. The operator, lease, well No., unit, section, township and range must be permanently shown on the marker. The marker must be cemented in the hole or ground.
- (3). The area around dry holes must be cleaned and leveled.

A reinspection of this pool will be made after 30 days.

Very truly yours,

OIL CONSERVATION COMMISSION

R. L. Stamets
Geologist

RLS/bh