

NO. OF COPIES RECEIVED	6
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	4

**RECEIVED**  
NEW MEXICO OIL CONSERVATION COMMISSION

NOV 4 1971

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

**O. C. C.**

ARTESIA, OFFICE

**SUNDRY NOTICES AND REPORTS ON WELLS**

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER		5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
2. Name of Operator <b>Adobe Oil Company</b>		5. State Oil & Gas Lease No. <b>L-5253</b>
3. Address of Operator <b>601 Wilkinson-Foster Bldg., Midland, Texas 79701</b>		7. Unit Agreement Name
4. Location of Well UNIT LETTER <b>N</b> <b>660</b> FEET FROM THE <b>south</b> LINE AND <b>1980</b> FEET FROM THE <b>west</b> LINE, SECTION <b>2</b> TOWNSHIP <b>8-S</b> RANGE <b>27-E</b> NMPM.		8. Farm or Lease Name <b>Montgomery State</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>3936' Gr.</b>		9. Well No. <b>I</b>
		10. Field and Pool, or Wildcat <b>Wildcat</b>
		12. County <b>Chaves</b>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐  
TEMPORARILY ABANDON ☐  
PULL OR ALTER CASING ☐  
OTHER ☐

PLUG AND ABANDON ☒  
CHANGE PLANS ☐  
OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒  
COMMENCE DRILLING OPNS. ☐  
CASING TEST AND CEMENT JOBS ☐  
OTHER ☐  
ALTERING CASING ☐  
PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Adobe Oil Company proposes to P&A the above well. We plan to squeeze the perforations from 6104-6112' with 50 sxs regular neat cement thru a RTTS packer. Pull packer and tubing and cut 5-1/2" casing off at approximately 4600'. Set 25 sx plug at top of 5-1/2" casing, 35 sx plug from 4000-4100', 35 sx plug 2584-2684', 35 sx plug in and out of 9-5/8" casing from 1400-1500', 10 sx plug at surface. Place marker and finish cleanup to complete P&A operations.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *M. H. Lopez*

TITLE Vice President

DATE 11/3/71

APPROVED BY *W. A. Gussett*

TITLE OIL AND GAS INSPECTOR

DATE NOV 4 1971

CONDITIONS OF APPROVAL, IF ANY: